

PRODUCT BULLETIN

SERVICE BULLETIN:

Spektrum™ SPMAR7350 and SPMAR9350 receivers (PID numbers beginning with TRA) will shut down if connected to a temperature sensor and that sensor reaches 110 degrees F.

NOTICE: *This bulletin only applies to receivers with PID number beginning with TRA. Receivers with a different PID number are not affected.*

Please update the receiver Firmware:

1. If you have not already registered your Spektrum receiver, please visit www.spektrumrc.com.
2. Connect the receiver to a computer using the USB Transmitter/Receiver Programming Cable (SPMA3065).
3. Visit http://spektrumrc.cachefly.net/apps/updater_instructions.html.
4. Follow the instructions listed under Spektrum Updater to update the Firmware.

Once you have completed the Firmware Update, the issue will be resolved

If you have questions, please call: [877-504-0233](tel:877-504-0233) Product Support hours are:

Monday-Friday 8 A.M. – 6 P.M.

Download English PDF Bulletin here: <https://www.spektrumrc.com/ProdInfo/Files/59369-SPMAR7350-SPMAR9350-Bulletin.pdf>

NOTICE: Horizon disclaims all legal liabilities and warranties involved with any consumer who fails to act upon this product bulletin.

Horizon Hobby, LLC. is not responsible for inadvertent errors in this email.

©2018 Horizon Hobby, LLC. Blade, Inductrix, and the Horizon Hobby logo are trademarks or registered trademarks of Horizon Hobby, LLC.

Horizon Hobby, LLC | 4105 Fieldstone Road | Champaign, IL 61822 | United States
800.338.4639

[Terms of Use](#) | [Privacy Policy](#) | [My Account](#)

We hope you found this message useful. However, if you prefer not to receive commercial email from Horizon Hobby, or if you've changed your email address, please click [here](#). Please send any questions, comments or concerns to webmaster@horizonhobby.com. Thank you.