

Created using **RPAS Wilco**®

Operation Name:

Pilot Name:

Pilot Certificate:

Flight Start:

Flight End:

Flight Area (Latitude):

Flight Area (Longitude):

Altitude - Radius:

Airspace:

FIR - Contact:

Weather:

Wingham Jet



January 25, 2023 1:33 PM

January 25, 2023 3:33 PM

43° 52' 4.30" N (43.868)

81° 17' 52.40" W (-81.298)

Alt: 800 ft - Rad: 926.0 m (0.5 nm)

UNCONTROLLED

CZYZ - 905-676-4509

-1.4 Celsius - Snow, Partially cloudy

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

Included |

Site Survey

Obstacles (if available)

Nearby Aerodromes

Canadian Aviation Regulations

GFA

Aerodrome Supplements

METAR & TAF (if available)

NOTAMs

CFS



Flight Map




MAP Details

		Latitude	Longitude	
×	MODEL	43° 52' 4.30" N (43.868)	81° 17' 52.40" W (-81.298)	
	Pilot	43° 52' 7.90" N (43.8689)	81° 17' 56.00" W (-81.2989)	



Airspace Classification



Overlying Airspaces

Class	Name	Floor	Ceiling
E	Southern Ontario Low Level Control Area CAE	3500MSL	12500MSL
В	Southern Ontario Low Level Control Area CAE	12500MSL	18000MSL
Е	T616 Airway	2200AGL	12500MSL
В	T616 Airway	12500MSL	18000MSL
Е	T616 Airway	2200AGL	12500MSL
В	T616 Airway	12500MSL	18000MSL

Nearest Aerodromes & Distance from Operation

WINGHAM (INGLIS FIELD) (CWH5 AERODROME Reg)	Lat: 43.896 Long: 81.336 4.373 KM 2.36 NM
RICHARD W. LEVAN (CPR7 AERODROME Reg)	Lat: 43.867 Long: 81.298 0.096 KM 0.05 NM
TEESWATER (THOMPSON FIELD) (CPC6 AERODROME Reg)	Lat: 43.948 Long: 81.272 9.149 KM 4.94 NM
TEESWATER (DENT ETELD) (CDE2 AFRODROME Reg)	lat: 43.994 long: 81.294 14.029 KM 7.58 NM

Weather Information for Mission Day

Summary: Partly cloudy throughout the day with snow.

Condition	Temperature	Feels Like	Precipitation	Visibility	Cloud Coverage	Wind Speed	Humidity
Snow, Partially cloudy	1.4 Celsius	6.7 Celsius	98.0 %	5.0 Km	89.0 %	33.1 kph	88.9 %

Canadian Aviation Regulations

Division III — General Operating and Flight Rules

For full listing please visit https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

Visual Line-of-sight

- 901.11 (1) Subject to subsection (2) no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - O (b) emergency procedures, including with respect to
 - (i) a control station failure,
 - (ii) an equipment failure.
 - (iii) a failure of the remotely piloted aircraft,
 - (iv) a loss of the command and control link,
 - (v) a fly-away, and
 - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation

Operations at or in the Vicinity of an Aerodrome, Airport or Heliport

0


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
- Subject to section 901.73 no pilot shall operate a remotely piloted aircraft at a distance of less than
 - O (a) three nautical miles from the centre of an airport; and
 - O (b) one nautical mile from the centre of a heliport.
- (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903 03.

Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
 - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights and
 - (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - (i) the names of the persons who performed them.
 - (ii) the dates they were undertaken,
 - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - (iv) if applicable any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
 - O (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).



GFA Issue time + 00 hr - CLOUDS AND WEATHER




GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 06 hr - CLOUDS AND WEATHER




GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 12 hr - CLOUDS AND WEATHER



GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





WINGHAM (INGLIS FIELD) - CWH5 - Reg

NOTAM

(G0080/23 NOTAMN

- Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2301250400 C) 2301260900
- D) DAT Y 0400-0900
- E) FO OWING NAVAIDS UNMONITORED: CYAM I S RWY 12 CYKF I S RWY 26 CYTZ I S RWY 08

- CYXU I S RWY 15

. CAMPBE FORD DME YCF 113.5MHZ/CH82X TORONTO VOR/DME YYZ 112.15MHZ/CH58Y PEARSON (TORONTO) VOR YTP 116.55MHZ ONDON VOR/DME YXU 117.2MHZ/CH119X WIARTON VOR/DME YVV 117.7MHZ/CH124X

NORTH BAY VOR/DME YYB 115.4MHZ/CH101X MOOSONEE VOR/DME YMO 112.9MHZ/CH76X TIMMINS VOR/DME YTS 113MHZ/CH77X)

(G0033/23 NOTAMR G2417/22

- 0) CZXX/Q0ECH/IV/NB0/E/000/999/5518N09358W999
- Q) CZXX/QUECH/IV/NBO/E/000/999/5518N09358W999
 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES
 ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA
 AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

- Q) CZYZ/QFAXX/IV/NBO/A/000/999/4352N08118W005
- A) CXXX B) 2301231627 C) 2304211700EST E) CPR7 WINGHAM/RICHARD W. EVAN
- E) CPR7 WINGHAM/RICHARD W. EVAN GRASS PRKG NOT AVB DUE SOFT COND)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NB0/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
- E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)



RICHARD W. LEVAN - CPR7 - Reg

NOTAM

(G0080/23 NOTAMN

- Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2301250400 C) 2301260900
- D) DAT Y 0400-0900
- E) FO OWING NAVAIDS UNMONITORED: CYAM I S RWY 12 CYKF I S RWY 26 CYTZ I S RWY 08

- CYXU I S RWY 15

. CAMPBE FORD DME YCF 113.5MHZ/CH82X TORONTO VOR/DME YYZ 112.15MHZ/CH58Y PEARSON (TORONTO) VOR YTP 116.55MHZ ONDON VOR/DME YXU 117.2MHZ/CH119X WIARTON VOR/DME YVV 117.7MHZ/CH124X NORTH BAY VOR/DME YYB 115.4MHZ/CH101X MOOSONEE VOR/DME YMO 112.9MHZ/CH76X TIMMINS VOR/DME YTS 113MHZ/CH77X)

(G0033/23 NOTAMR G2417/22

- 0) CZXX/Q0ECH/IV/NB0/E/000/999/5518N09358W999
- Q) CZXX/QUECH/IV/NBO/E/000/999/5518N09358W999
 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES
 ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA
 AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

- Q) CZYZ/QFAXX/IV/NBO/A/000/999/4352N08118W005
- A) CXXX B) 2301231627 C) 2304211700EST E) CPR7 WINGHAM/RICHARD W. EVAN
- E) CPR7 WINGHAM/RICHARD W. EVAN GRASS PRKG NOT AVB DUE SOFT COND)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NB0/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
- E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)



TEESWATER (THOMPSON FIELD) - CPC6 - Reg

NOTAM

(G0080/23 NOTAMN

- Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2301250400 C) 2301260900
- D) DAT Y 0400-0900
- E) FO OWING NAVAIDS UNMONITORED: CYAM I S RWY 12 CYKF I S RWY 26 CYTZ I S RWY 08

CYXU I S RWY 15

. CAMPBE FORD DME YCF 113.5MHZ/CH82X TORONTO VOR/DME YYZ 112.15MHZ/CH58Y PEARSON (TORONTO) VOR YTP 116.55MHZ ONDON VOR/DME YXU 117.2MHZ/CH119X WIARTON VOR/DME YVV 117.7MHZ/CH124X NORTH BAY VOR/DME YYB 115.4MHZ/CH101X MOOSONEE VOR/DME YMO 112.9MHZ/CH76X TIMMINS VOR/DME YTS 113MHZ/CH77X)

(G0033/23 NOTAMR G2417/22

- 0) CZXX/Q0ECH/IV/NB0/E/000/999/5518N09358W999
- Q) CZXX/QUECH/IV/NBO/E/000/999/5518N09358W999
 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES
 ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA
 AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

- O) CZXX/OXXXX/I/NBO/W/000/999/5245N09040W999
- Q) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999
 A) CZYZ CZWG B) 2301181712 C) 2301260901
 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)



TEESWATER (DENT FIELD) - CDF2 - Reg

NOTAM

(G0080/23 NOTAMN

- Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2301250400 C) 2301260900
- D) DAT Y 0400-0900
- E) FO OWING NAVAIDS UNMONITORED: CYAM I S RWY 12 CYKF I S RWY 26 CYTZ I S RWY 08

- CYXU I S RWY 15

. CAMPBE FORD DME YCF 113.5MHZ/CH82X TORONTO VOR/DME YYZ 112.15MHZ/CH58Y PEARSON (TORONTO) VOR YTP 116.55MHZ ONDON VOR/DME YXU 117.2MHZ/CH119X WIARTON VOR/DME YVV 117.7MHZ/CH124X NORTH BAY VOR/DME YYB 115.4MHZ/CH101X MOOSONEE VOR/DME YMO 112.9MHZ/CH76X TIMMINS VOR/DME YTS 113MHZ/CH77X)

(G0033/23 NOTAMR G2417/22

- 0) CZXX/Q0ECH/IV/NB0/E/000/999/5518N09358W999
- Q) CZXX/QUECH/IV/NBU/E/0809/999/518N09358W999
 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES
 ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA
 AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

- O) CZXX/OXXXX/I/NBO/W/000/999/5245N09040W999
- Q) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999
 A) CZYZ CZWG B) 2301181712 C) 2301260901
 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

WINGHAM (INGLIS FIELD) ON

CWH5

WINGHAIW (I	NOLIS FIELD) ON	CWH5
REF	N43 53 47 W81 20 11 1.2NW 9°W (2013) UTC-5(4) Elev 1015′ A5000	£ ELEV 1015
OPR	Tom Inglis 519-357-2781 Reg PPR	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
RWY DATA RCR	Rwy 04(036°)/22(216°) 2968x65 TURF Thld 22 displ 650' spring and fall only. Opr No win maint. Rwy soft in spring and fall, particularly at N end.	2800 2800
COMM ATF	tfc 123.0 3NM 4000	
PRO	Rgt hand circuits Rwy 22 (CAR 602.96)	_@
CAUTION	1.0NM NE of A/D 1500 ASL. Ocsl wildlif	yy not vis when on thid. Two twrs 0.8NM and e on rwy. Wooded area with 50' trees lining SL over hwy on 04 apch. Wingham Airfield



















WINGHAM / RICHARD W LeVAN ON

CDD7

WINGHAIM	RICHARD W. LEVAN ON	CPR
REF	N43 52 03 W81 17 55 1SE 9°W (2013) UTC-5(4) Elev 1067' A5000 LO6 CAP	ELEV 1067
OPR	Tyler and Summer Papple 519-318-4224 (text preferred) www.PappleAviation.ca Reg	3000 125
PF	A-5 B-6 C-1,2,3,4	270
CUST	AOE/15 888-226-7277 14-22Z‡ Mon-Fri exc hols	Te anoius sta
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	2600
SERVICES FUEL	100LL, MG-3 A/D not attended. Self-sel	rve, see OPR website.
RWY DATA RCR	Rwy 13(130°)/31(310°) 4000x75 ASPH Opr No win maint	RPAS RPAS
LIGHTING	13-(TE ME), 31-(TE ME) ARCAL-123	3.0 type K
COMM	tfc 123.0 3NM 4000 ASL	
PRO	Rgt hand circuits Rwy 13 (CAR 602.96).	
CAUTION	2 silos 80 AGL NE thld Rwy 31. Numeror Glider activity in the vicinity of A/D Sat-S	













RWY DATA

сомм

CAUTION

RCR

ATF


TEESWATER (THOMPSON FIELD) ON

	· /
REF	N43 56 54 W81 16 19 2.5S 9°W UTC-5(4) Elev 1000′ A5000
OPR	D. Thompson 519-392-6988 Reg
PF	C-1,2,3,4,5
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
SERVICES S	4,5,6

Rwy 18(177°)/36(357°) 2450x60 turf

Hydro wires 600' S of Thld 36. Bush 500' N of Thld 18.

Opr No win maint. Soft in spring.





















CAUTION

IEE5WA	IEK (DEN	T FIELD)	ON

REF	N43 59 40 W81 17 37 Adj W 9°W UTC-5(4) Elev 1050' A5000
OPR	J. Dent 519-392-8314 Reg PPR
PF	B-1 C-2 D-3,4,5,6
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
SERVICES S	4,5,6
RWY DATA Rwy 18(177°)/36(357°) 2500x60 to RCR Opr Ltd win maint	
COMM	tfc 122.8 5NM 4000 ASL

Trees 500' N of Thid 18.



















