

Created using **RPAS Wilco**®

Reference No:
Title:
Pilot Name:
Pilot Certificate:
Flight Start:
Flight End:
Flight Address:
Flight Area (Latitude):
Flight Area (Longitude):
Altitude - Radius:
Classification:
FIR - Contact:

A44DE5 Mission 10-21-2024

October 21, 2024 10:00 AM

October 21, 2024 11:00 AM Jackson Road, Knutsford, British Columbia VOE 2AO, Canada

50° 33' 23.27" N (50.556) 120° 17' 6.26" W (-120.285)

Alt: 400 ft - Rad: 185.2 m (0.1 nm)

UNCONTROLLED

CZVR - 604-586-4500

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

Included

Site Survey

Obstacles (if available)

Nearby Aerodromes

Canadian Aviation Regulations

GFA

Aerodrome Supplements

-METAR & TAF (if available)

-NOTAMs

-CFS



Flight Map



RPAS Specification

- Manufacturer: MAAC
- Model: MODEL AIRPLANE (Timber Evo)
- Registration Number: C-2314724718
- Eligible for advanced operations: Yes
- Manufacturer RPAS safety assurance:
 - Controlled Airspace: YES
 - Near People: NO
 - o Over People: NO


MAP Details

| | | Latitude | Longitude |
|----|-----------------|--------------------------------|----------------------------------|
| × | MODEL | 50° 33' 23.27" N (50.556) | 120° 17' 6.26" W (-120.285) |
| • | Pilot | () | () |
| • | Payload Op. | () | () |
| 88 | Observer | () | () |
| | | | |

Latitude Longitude
Latitude Longitude



Airspace Classification



Overlying Airspaces


| Class | Name | Floor | Ceiling |
|-------|-----------------------|----------|----------|
| E | T650 Airway | 2200AGL | 12500MSL |
| В | T650 Airway | 12500MSL | 18000MSL |
| E | T799 Airway | 2200AGL | 12500MSL |
| В | T799 Airway | 12500MSL | 18000MSL |
| В | T695 Airway | 12500MSL | 18000MSL |
| E | T695 Airway | 2200AGL | 12500MSL |
| E | Kamloops, BC TA | 700AGL | 12500MSL |
| В | Kamloops, BC TA | 12500MSL | 18000MSL |
| E | T611 Airway | 2200AGL | 12500MSL |
| В | T611 Airway | 12500MSL | 18000MSL |
| E | T687 Airway | 2200AGL | 12500MSL |
| В | T687 Airway | 12500MSL | 18000MSL |
| E | Kamloops, BC TA | 1600AGL | 12500MSL |
| В | Kamloops, BC TA | 12500MSL | 18000MSL |
| E | Williams Lake, BC CAE | 8000MSL | 12500MSL |
| В | Williams Lake, BC CAE | 12500MSL | 18000MSL |


Nearest Aerodromes & Distance from Operation


| KAML Cert | OOPS (ROYAL INLAND HOSPITA | L) (CBC4 - HELIPORT - | Lat: 50.669 | Long: -120.333 | 12.962KM 7. | ONM | N |
|--------------|----------------------------|-----------------------|----------------|-------------------|-------------|-------|----|
| KAML | .00PS (CAH7 - WATERDROME - |) | Lat: 50.7 | Long: -120.433 | 19.069KM 10 |).3NM | NW |
| KAML | OOPS (CYKA - AERODROME - C | ert) | Lat: 50.703 | Long: -120.448 | 19.939KM 10 | .77NM | NW |

KAMLOOPS (ROYAL INLAND HOSP) BC (Heli)

CBC4







| REF | N50 40 09 W120 19 59 Adj 17°E (2012) UTC-8(7) Elev 1453′ A5004 | |
|----------------|---|--|
| OPR | Interior Health Authority 250-374-5111 Cert PPR | |
| PF | B-1,2,4 C-3,5,6 | |
| FLT PLN FIC | Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA) or 250-376-8392 | |
| HELI DATA | Surface Pad 1: FATO 86' dia elevated TLOF 57' dia CONC Safety Area 115' dia elevated 17,000 lbs Max heli overall length 57.4' (CAR 602.96) Rooftop Pad 2: FATO 86' x 86' non-supporting TLOF 71' x 71' CONC Safety Area 115' x 115' 18,000 lbs Max heli overall length 57.4' (CAR 602.96) | |
| RCR | Opr | |
| LIGHTING | Surface Pad 1: RY(LO) green ARCAL-125.7 type J Rooftop Pad 2: RW(ME) green LED ARCAL-122.9 type K | |

| KAMLOOPS (ROYAL INLAND HOSP) BC (Heli) (Cont'd) CB | | |
|--|--|--|
| COMM MF A/G | Kamloops rdo 125.7 5NM 4100 ASL centered on Kamloops aprt (CAR 602.98). Hosp Security PEPCORD1 148.655 FM 3 min PN | |
| PRO | Surface Pad 1 Arr/dep 125° fr heli, (H3) (CAR 602.96). Arr/dep 002° to 125° fr he (H1) (CAR 602.96). Rooftop Pad 2 Arr/dep 265° to 108° fr heli (H1) (CAR 602.96). | |
| CAUTION | Unlgtd embankment to 40', adj SE. Marked & lgtd hosp penthouse elevator aprx 30' W of rooftop pad safety area. | |


























KAMLOOPS BC CYKA



| REF | N50 42 09 W120 26 55 5WNW 16°E (2016) UTC-8(7) Elev 1133' A5004 LO2 HI3 CAP RCAP | | |
|--|--|--|--|
| OPR | Kamloops Aprt Ltd 250-376-3613 Cert | | |
| PF | A-1,2,3,6 C-4,5 | | |
| CUST | AOE/15 1630-0800Z‡ AOE/30 1630-0030Z‡ Mon-Fri exc hols 888-226-7277 | | |
| FLT PLN FIC WX | Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA) or 250-376-8392 METAR H24. TAF H24, issue times: 01, 07, 13, 19Z. | | |
| SERVICES FUEL OIL S ARFF PVT ADV MIL CON | Shell 123.0 250-376-7633; Executive Flight Centre 122.85 250-376-9069 | | |
| RWY DATA RWY CERT TWY CERT TWY APRON | Rwy 09(087°)/27(267°) 8000x148 ASPH Rwy 05(045°)/23(225°) 1875x49 ASPH Thld 23 displ 249'. Rwy 05/23 AGN I Rwy 09/27 AGN IIIB Twy: D, E AGN II Twy A, no vehicle ctl first 600' W of Apron I. Twy E: Unlgtd Apron 1: Uncontrolled, avbl to sked pax flt only. All acft must yield to acft in pushback from ATB. Prkg fees. Apron II: Uncontrolled, avbl for transient and itinerant prkg. All acft must yield to acft in pushback from ATB. Pilot/pax access via groundside Gate 10 only; no access/egress permitted via ATB. Prkg fees. Apron V: Uncontrolled, PPR for prkg on or within 25' of apn. FSS Win maint 13-08Z‡ O/T 2 hrs PN cost recovery. CRFI, PLR/PCN. | | |
| LIGHTING | 09-AO(TE ME) P2, 27-AO(TE ME) P2 ARCAL-125.7 type K avbl when FSS clsd PAPI limitation/restriction. PAPI Rwy 09 to be used only within 4NM of thld; PAPI Rwy 27 to be used only within 4NM of thld. Twy D RR. | | |

| KAMLOOPS | BC (Cont'd) | CYKA |
|-------------------------------------|--|-------|
| COMM RADIO RCO CLNC DEL MF PAL | 125.7 PTC avbl (V) (emerg only 250-376-7941) Pacific rdo 123.375 (FISE) 126.7 (bcst) 121.9 PTC avbl ltd hrs rdo 125.7 5NM 4100 ASL (CAR 602.98) Vancouver Ctr 132.35 133.5 134.4 236.0 | |
| DME ILS LOC | IKA 109.3 Ch 30 N50 42 14 W120 27 41 (1136') IKA 109.3 (Rwy 09) IPP 109.9 (Rwy 27) reliable only within 10° of cent | WILCO |
| PRO | Pilots should refer to Canadian Airport Charts (CAC) to obtain details on established hot spots, prior to operating on maneuvering areas. CAC are available for free on the NAV CANADA website. Day: rgt hand circuits Rwys 05, 23 & 27 (CAR 602.96). Night: follow VTPC night circuit pro. Tkof and ldg in grass adj rwys by fixed-wing acft not auth. | |
| CAUTION | Only pilots familiar with Icl terrain should use this aprt dur hrs of darkness. Ngt of recommended unless all 6 hazard beacons are oprg. Hi terrain reduces open length of Rwys 09 and 27 PAPI. Painted & Igtd twr 1253 ASL (128 AGL) aprx 250' beyond Thid 05 and aprox NW rwy centreline. Fuel facility (tanks 80 AGL) aprx 0.5NM NE A/D; no low a ops. | |













Canadian Aviation Regulations

Division III — General Operating and Flight Rules

For full listing please visit: https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

Visual Line-of-sight

- 901.11 (1) Subject to subsection (2), no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - O (b) emergency procedures, including with respect to
 - (i) a control station failure,
 - (ii) an equipment failure.
 - (iii) a failure of the remotely piloted aircraft,
 - (iv) a loss of the command and control link,
 - (v) a fly-away, and
 - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation.

Operations at or in the Vicinity of an Aerodrome, Airport or Heliport


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
- Subject to section 901.73, no pilot shall operate a remotely piloted aircraft at a distance of less than
 - O (a) three nautical miles from the centre of an airport; and
 - O (b) one nautical mile from the centre of a heliport.
- (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
 - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights; and
 - O (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - (i) the names of the persons who performed them.
 - (ii) the dates they were undertaken,
 - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - (iv) if applicable, any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
 - (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).



GFA Issue time + 00 hr - CLOUDS AND WEATHER




GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 06 hr - CLOUDS AND WEATHER




GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 12 hr - CLOUDS AND WEATHER



GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





KAMLOOPS (ROYAL INLAND HOSPITAL) - CBC4 - Cert

NOTAM

(F4282/24 NOTAMR F3793/24

- Q) CZXX/QANCH/I/NB0/E/000/180/5203N11739W200 A) CZEG CZVR B) 2410171415 C) PERM
- E) AMEND PUBLICATIONS: T789: BTN VIDRI AND ELLKS: MEA TO READ 15000)

(F4264/24 NOTAMR F4096/23

- Q) CZXX/QADTT/IV/B0/E/000/999/6650N11045W999 A) CZVR CZEG B) 2410161345 C) 2504171600
- E) TRIGGER NOTÁM AIP SUPPLÉMENT 26/18 IN EFFECT. ADJUSTMENT TO THE CANADA AIR DEFENCE IDENTIFICATION ZONE (ADIZ).)

- (I6059/24 NOTAMR I7049/23 Q) CZVR/QOBTT/IV/BO/AE/000/016/5040N12020W001
- A) CXXX B) 2410161341 C) 2504171600
 E) CBC4 KAMLOOPS (ROYAL INLAND HOSPITAL) (HELI)
 TRIGGER NOTAM ALP SUPPLEMENT 74/22 IN EFFECT.
 TOWER CRANE ERECTED KAMLOOPS, BRITISH COLUMBIA)

(T5956/24 NOTAMN

- (15350/24 NOTA-M Q) CZVR/QMXXX/IV/M/A/000/999/5042N12027W005 A) CYKA B) 2410101845 C) 2410311900
- E) TWY D FIRST 33FT SOUTH OF APN II CLSD DUE CONST)

(T5941/24 NOTAMR T5664/24

- Q) CZVR/QFAXX/IV/NBO/A/000/999/5042N12026W005
- A) CXXX B) 2410092220 C) 2410312300EST
- E) CAH7 KAMLOOPS (WATER)
 FLOAT PLANE DOCK NOT AVBL)

(I5679/24 NOTAMR I5020/24

- 0) CZVR/0FFAH/IV/B0/A/000/999/5042N12027W005
- A) CYKA B) 2410010730 C) 2410270730 E) ACFT RESCUE AND FIRE FIGHTING (ARFF) HR OF OPS:
- SUN-FRI 0015-0145 0330-0430 0630-0730 1230-1330 1630-1830
- SAT 0015-0145 0330-0430 0630-0730 1230-1330 1630-1830 OTHER TIMES 2 HR PN, COST RECOVERY)

(T5606/24 NOTAMN

- Q) CZVR/QMNLC/IV/NBO/A/000/999/5042N12027W005
- A) CYKA B) 2409251400 C) 2410311900 E) APN STAND 1 AND 2 NOT AVBL)

(T5607/24 NOTAMR T5238/24

- Q) CZVR/QMNLT/IV/NBO/A/000/999/5042N12027W005
- A) CYKA B) 2409241953 C) 2410311900 E) APN II TAXILANE AVBL FOR ACFT WITH WINGSPAN LESS THAN 118FT)

(I5605/24 NOTAMR I5536/24

- 0) CZVR/OMNLT/IV/NBO/A/000/999/5042N12027W005
- A) CYKA B) 2409241949 C) 2410311900 E) APN II AVBL TO MEDEVAC AND COURIER ONLY,
- OTHER ACFT VIA PPR CTC 250-377-5823)

(T5591/24 NOTAMN

- CZVR/QFZXX/IV/NB0/A/000/999/5042N12027W005
- A) CYKA B) 2409241518 C) PERM
- E) AMEND PUBLICATIONS: CUST TO READ: AOE/30 1630-0030Z (DT 1530-2330Z)

MON-FRI EXC HOLS 888-226-7277)

(F3794/24 NOTAMN

- Q) CZXX/QAACH/IV/B0/E/000/180/5143N11720W200
- A) CZEG CZVR B) 2409182024 C) PERM
 E) AMEND PUBLICATIONS: T676: BTN MERYT AND ANDIE: MEA TO READ 15000)

- Q) CZVR/QFHLC/IV/NBO/A/000/999/5042N12027W005
- A) CYKA B) 2409021400 C) 2410311900 E) HELIPADS A AND B CLSD DUE CONST)

(F3440/24 NOTAMR F2802/24

(F3440/24 NOTAMR F2802/24
Q) CZXX/QOEXX/IV/NBO/E/000/999/6650N11045W999
A) CZVR CZEG B) 2408281609 C) 2410271800EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT ENTER THE BEIRUT FIR (OLBB), DUE TO POTENTIAL RISK TO AVIATION FM MIL ACT. THIS NOTAM SUPERSEDES THE ADVICE FOR LEBANON IN AIC 13/24.)

(F3309/24 NOTAMN

- Q) CZXX/Q0EXX/IV/NB0/E/000/999/6650N11045W999
- Q) CZXX/QOEXX/TV/NBO/E/000/999/6650N11045W999
 A) CZVR CZEG B) 2408231337 C) 2411211600EST
 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN AFGHANISTAN. CANADIAN AIR OPR AND OWNERS OF ACT REGISTERED IN CANADA ARE RECOMMENDED TO MAINTAIN A FLI LEVEL EQUAL TO 0R ABV F1320, WITHIN THE KABUL FIR (OAKX), DUE TO POTENTIAL RISK TO AVIATION FM EXTREMIST AND MIL ACT AND LTD RISK MITIGATION CAPABILITIES. THIS NOTAM SUPERSEDES THE ADVICE FOR AFGHANISTAN IN AIC 13/24.)

(14588/24 NOTAMN Q) CZVR/QPDCH/I/NBO/A/000/999/5042N12027W005 A) CYKA B) 2408141511 C) PERM E) AMEND PUBLICATION: OLONA ONE DEP: DEP RTE RWY 27: MIN CLB GRADIENT TO READ: 430 FT/NM TO 5000 INSTEAD OF 4800.)



KAMLOOPS - CAH7 -

NOTAM

(F4282/24 NOTAMR F3793/24 Q) CZXX/QANCH/I/NB0/E/000/180/5203N11739W200 A) CZEG CZVR B) 2410171415 C) PERM E) AMEND PUBLICATIONS: T789: BTN VIDRI AND ELLKS: MEA TO READ 15000) (F4264/24 NOTAMR F4096/23 Q) CZXX/QADTT/IV/B0/E/000/999/6650N11045W999 A) CZVR CZEG B) 2410161345 C) 2504171600 E) TRIGGER NOTÁM - AIP SUPPLÉMENT 26/18 IN EFFECT. ADJUSTMENT TO THE CANADA AIR DEFENCE IDENTIFICATION ZONE (ADIZ).) (T5956/24 NOTAMN Q) CZVR/QMXXX/IV/M/A/000/999/5042N12027W005 A) CYKA B) 2410101845 C) 2410311900 E) TWY D FIRST 33FT SOUTH OF APN II CLSD DUE CONST) (I5941/24 NOTAMR I5664/24 Q) CZVR/QFAXX/IV/NBO/A/000/999/5042N12026W005 A) CXXX B) 2410092220 C) 2410312300EST E) CAH7 KAMLOOPS (WATER) FLOAT PLANE DOCK NOT AVBL) (I5679/24 NOTAMR I5020/24 Q) CZVR/QFFAH/IV/B0/A/000/999/5042N12027W005 A) CYKA B) 2410010730 C) 2410270730 E) ACFT RESCUE AND FIRE FIGHTING (ARFF) HR OF OPS: SÚN-FRI 0015-0145 0330-0430 0630-0730 1230-1330 1630-1830 SAT 0015-0145 0330-0430 0630-0730 1230-1330 1630-1830 0THER TIMES 2 HR PN, COST RECOVERY) (I5606/24 NOTAMN Q) CZVR/QMNLC/IV/NBO/A/000/999/5042N12027W005 A) CYKA B) 2409251400 C) 2410311900 E) APN STAND 1 AND 2 NOT AVBL) (15607/24 NOTAMR 15238/24 Q) CZVR/QMNLT/IV/NBO/A/000/999/5042N12027W005 A) CYKA B) 2409241953 C) 2410311900 E) APN II TAXILANE AVBL FOR ACFT WITH WINGSPAN LESS THAN 118FT) (I5605/24 NOTAMR I5536/24 Q) CZVR/QMNLT/IV/NB0/A/000/999/5042N12027W005 Q) CZVK/QMNLI/10/NBD/A/000/999/5042NI202/WG A) CYKA B) 2409241949 C) 2410311900 E) APN II AVBL TO MEDEVAC AND COURIER ONLY, OTHER ACFT VIA PPR CTC 250-377-5823) (I5591/24 NOTAMN Q) CZVR/QFZXX/IV/NB0/A/000/999/5042N12027W005 A) CYKA B) 2409241518 C) PERM E) AMEND PUBLICATIONS: CUST TO READ: AOE/30 1630-0030Z (DT 1530-2330Z) MON-FRI EXC HOLS 888-226-7277) (F3794/24 NOTAMN (P3)347.24 NOLANIN Q) CZXX/QAACH/IV/BO/E/000/180/5143N11720W200 A) CZEG CZVR B) 2409182024 C) PERM E) AMEND PUBLICATIONS: T676: BTN MERYT AND ANDIE: MEA TO READ 15000) Q) CZVR/QFHLC/IV/NBO/A/000/999/5042N12027W005 A) CYKA B) 2409021400 C) 2410311900 E) HELIPADS A AND B CLSD DUE CONST) (F3440/24 NOTAMR F2802/24 (F3440/24 NOTAMR F2802/24 Q) CZXX/QOEXX/IV/NBO/E/000/999/6650N11045W999 A) CZVR CZEG B) 2408281609 C) 2410271800EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT ENTER THE BEIRUT FIR (OLBB), DUE TO POTENTIAL RISK TO AVIATION FM MIL ACT. THIS NOTAM SUPERSEDES THE ADVICE FOR LEBANON IN AIC 13/24.) (F3309/24 NOTAMN (F3399/24 NOTAMN Q) CZXX/QOEXX/IV/NBO/E/000/999/6650N11045W999 A) CZVR CZEG B) 2408231337 C) 2411211600EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN AFGHANISTAN. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO MAINTAIN A FLT LEVEL EQUAL TO OR ABV FL320, WITHIN THE KABUL FIR (OAKX), DUE TO POTENTIAL RISK TO AVIATION FM EXTREMIST AND MIL ACT AND LTD RISK MITIGATION CAPABILITIES. THIS NOTAM SUPERSEDES THE ADVICE FOR AFGHANISTAN IN AIC 13/24.)

(T4588/24 NOTAMN

- Q) CZVR/QPDCH/I/NBO/A/000/999/5042N12027W005
- A) CYKA B) 2408141511 C) PERM
 E) AMEND PUBLICATION: OLONA ONE DEP:
 DEP RTE RWY 27: MIN CLB GRADIENT TO READ: 430 FT/NM TO 5000 INSTEAD OF 4800.)



KAMLOOPS - CYKA - Cert

METAR

METAR CYKA 211600Z 28007KT 30SM FEW019 SCT042 BKN080 07/04 A2996 RMK SF1SC3AC4 SF TR SLP155=

TAF

FM211800 26010KT P6SM SCT030 BKN100 TEMPO 2118/2121 BKN020 FM212100 27010KT P6SM SCT020 BKN060 TEMPO 2121/2201 P6SM -SHRA

```
TAF CYKA 211240Z 2113/2201 28006KT P6SM SCT020 BKN040 TEMP0 2113/2115 5SM -SHRA BR BKN020
RMK NXT FCST BY 211900Z=
NOTAM
                                                        (F4282/24 NOTAMR F3793/24
                                                       Q) CZXX/QANCH/I/NB0/E/000/180/5203N11739W200
                                                       A) CZEG CZVR B) 2410171415 C) PERM
E) AMEND PUBLICATIONS: T789: BTN VIDRI AND ELLKS: MEA TO READ 15000)
                                                        (F4264/24 NOTAMR F4096/23
                                                       Q) CZXX/QADTT/TV/BO/E/000/999/6650N11045W999
A) CZVR CZEG B) 2410161345 C) 2504171600
E) TRIGGER NOTAM - AIP SUPPLEMENT 26/18 IN EFFECT. ADJUSTMENT TO THE
                                                       CANADA AIR DEFENCE IDENTIFICATION ZONE (ADIZ).)
                                                       (T5956/24 NOTAMN
                                                       Q) CZVR/QMXXX/IV/M/A/000/999/5042N12027W005
                                                          CYKA B) 2410101845 C) 2410311900
TWY D FIRST 33FT SOUTH OF APN II CLSD DUE CONST)
                                                        (T5941/24 NOTAMR T5664/24
                                                       (1554)24 WOTAM 15004/24
(9) CZVR/QFAXX/IV/NBO/A/000/999/5042N12026W005
A) CXXX B) 2410092220 C) 2410312300EST
                                                       E) CAH7 KAMLOOPS (WATER)
FLOAT PLANE DOCK NOT AVBL)
                                                       (I5679/24 NOTAMR I5020/24
                                                        O) CZVR/OFFAH/IV/BO/A/000/999/5042N12027W005
                                                       A) CYKA B) 2410010730 C) 2410270730
E) ACFT RESCUE AND FIRE FIGHTING (ARFF) HR 0F 0PS:
SUN-FRI 0015-0145 0330-0430 0630-0730 1230-1330 1630-1830
                                                       SAT 0015-0145 0330-0430 0630-0730 1230-1330 1630-1830
                                                       OTHER TIMES 2 HR PN, COST RECOVERY)
                                                       (T5606/24 NOTAMN
                                                        Q) CZVR/QMNLC/IV/NB0/A/000/999/5042N12027W005
                                                       A) CYKA B) 2409251400 C) 2410311900
E) APN STAND 1 AND 2 NOT AVBL)
                                                        (T5607/24 NOTAMR T5238/24
                                                        Q) CZVR/QMNLT/IV/NBO/A/000/999/5042N12027W005
                                                       A) CYKA B) 2409241953 C) 2410311900
E) APN II TAXILANE AVBL
FOR ACFT WITH WINGSPAN LESS THAN 118FT)
                                                       O) CZVR/OMNLT/IV/NBO/A/000/999/5042N12027W005
                                                       A) CYKA B) 2409241949 C) 2410311900
E) APN II AVBL TO MEDEVAC AND COURIER ONLY,
                                                       OTHER ACFT VIA PPR CTC 250-377-5823)
                                                        (I5591/24 NOTAMN
                                                       Q) CZVR/QFZXX/IV/NBO/A/000/999/5042N12027W005
A) CYKA B) 2409241518 C) PERM
                                                       E) AMEND PUBLICATIONS: CUST TO READ: A0E/30 1630-0030Z (DT 1530-2330Z)
                                                       MON-FRI EXC HOLS 888-226-7277)
                                                       (F3794/24 NOTAMN
                                                       Q) CZXX/QAACH/IV/B0/E/000/180/5143N11720W200
A) CZEG CZVR B) 2409182024 C) PERM
                                                       E) AMEND PUBLICATIONS: T676: BTN MERYT AND ANDIE: MEA TO READ 15000)
                                                        (I5025/24 NOTAMN
                                                       Q) CZVR/QFHLC/IV/NBO/A/000/999/5042N12027W005
A) CYKA B) 2409021400 C) 2410311900
E) HELIPADS A AND B CLSD DUE CONST)
```

(F3440/24 NOTAMR F2802/24

(CJM4024 NOTHINE F2002/90)

Q) CZXX/QOEXX/IV/NBO/E/000/999/6650N11045W999

A) CZVR CZEG B) 2408281609 C) 2410271800EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT ENTER THE BEIRUT FIR (OLBB), DUE TO POTENTIAL

RISK TO AVIATION FM MIL ACT. THIS NOTAM SUPERSEDES THE ADVICE FOR LEBANON IN AIC 13/24.)

- (F3309/24 NOTAMN
 Q) CZXX/QOEXX/IV/NBO/E/000/999/6650N11045W999
 A) CZVR CZEG B) 2408231337 C) 2411211600EST
 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN AFGHANISTAN. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO MAINTAIN A FLT LEVEL EQUAL TO OR ABV FL320, WITHIN THE KABUL FIR (OAKX), DUE TO POTENTIAL RISK TO AVIATION FM EXTREMIST AND MIL ACT AND LTD RISK MITIGATION CAPABILITIES. THIS NOTAM SUPERSEDES THE ADVICE FOR AFGHANISTAN IN AIC 13/24.)

- (14588/24 NOTAMN
 Q) CZVR/QPDCH/I/NBO/A/000/999/5042N12027W005
 A) CYKA B) 2408141511 C) PERM
 E) AMEND PUBLICATION: OLONA ONE DEP:
 DEP RTE RWY 27: MIN CLB GRADIENT TO READ:
 430 FT/NM TO 5000 INSTEAD OF 4800.)