

Created using **RPAS Wilco**®

Operation Name:

Pilot Name:

Pilot Certificate:

Flight Start:

Flight End:

Flight Area (Latitude):

Flight Area (Longitude):

Altitude - Radius:

Airspace:

FIR - Contact:

Weather:

Guelph Gremlins

20, 2023 4:04 PM

January 20, 2023 6:04 PM

43° 40' 18.91" N (43.672)

80° 9' 29.52" W (-80.158)

Alt: 600 ft - Rad: 926.0 m (0.5 nm)

UNCONTROLLED

CZYZ - 905-676-4509

-0.2 Celsius - Snow, Rain, Partially cloudy

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

Included |

Site Survey

Obstacles (if available)

Nearby Aerodromes

Canadian Aviation Regulations

GFA

Aerodrome Supplements


METAR & TAF (if available)

NOTAMs

CFS




Flight Map



MAP Details



Airspace Classification



Overlying Airspaces

Class	Name	Floor	Ceiling
E	Southern Ontario Low Level Control Area CAE	2500MSL	6500MSL
E	Southern Ontario Low Level Control Area CAE	6500MSL	12500MSL
В	Southern Ontario Low Level Control Area CAE	12500MSL	18000MSL
E	Toronto XPNDR MANDTRY	6500MSL	12500MSL
В	Windsor, ON TA	12500MSL	18000MSL
E	Windsor, ON TA	700AGL	12500MSL
E	T614 Airway	2200AGL	12500MSL
В	T614 Airway	12500MSL	18000MSL
E	T614 Airway	2200AGL	12500MSL
В	T614 Airway	12500MSL	18000MSL
С	Toronto, ON TCA	4500MSL	12500MSL
С	Toronto, ON TCA	3500MSL	4500MSL

Nearest Aerodromes & Distance from Operation

FERGUS (HOLYOAKE AIRFIELD) (CPY9 AERODROME Reg)	Lat: 43.729 Long: 80.283 11.872 KM 6.41 NM
FERGUS (VODAREK FIELD) (CVF2 AERODROME Reg)	Lat: 43.723 Long: 80.289 11.951 KM 6.45 NM
GUELPH (CNC4 AERODROME Reg)	Lat: 43.564 Long: 80.196 12.38 KM 6.68 NM
ELORA (CDF5 AERODROME Reg)	Lat: 43.632 Long: 80.356 16.521 KM 8.92 NM

Weather Information for Mission Day

Summary: Partly cloudy throughout the day with early morning snow or rain.

Condition	Temperature	Feels Like	Precipitation	Visibility	Cloud Coverage	Wind Speed	Humidity
Snow, Rain, Partially cloudy	0.2 Celsius	4.7 Celsius	100.0 %	10.4 Km	90.0 %	23.0 kph	86.7 %

Canadian Aviation Regulations

Division III — General Operating and Flight Rules

For full listing please visit https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

Visual Line-of-sight

- 901.11 (1) Subject to subsection (2) no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - O (b) emergency procedures, including with respect to
 - (i) a control station failure,
 - (ii) an equipment failure.
 - (iii) a failure of the remotely piloted aircraft,
 - (iv) a loss of the command and control link,
 - (v) a fly-away, and
 - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation

Operations at or in the Vicinity of an Aerodrome, Airport or Heliport

0


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
- Subject to section 901.73 no pilot shall operate a remotely piloted aircraft at a distance of less than
 - O (a) three nautical miles from the centre of an airport; and
 - O (b) one nautical mile from the centre of a heliport.
- (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903 03.

Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
 - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights and
 - (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - (i) the names of the persons who performed them.
 - (ii) the dates they were undertaken,
 - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - (iv) if applicable any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
 - O (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).



GFA Issue time + 00 hr - CLOUDS AND WEATHER




GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 06 hr - CLOUDS AND WEATHER




GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 12 hr - CLOUDS AND WEATHER



GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





FERGUS (HOLYOAKE AIRFIELD) - CPY9 - Reg

NOTAM

(G0033/23 NOTAMR G2417/22

- (G0033/23 NOTAMR G2417/22
 Q) CZXX/QDECH/IV/NBO/E/000/999/5518N09358W999
 A) CZWG CZYZ B) 2390111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS).
 EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022
FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA
AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
- A) CL72 CLWG B) 230116172 C) 2301200901

 E) AIRSPACE SECURITY WARRING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

(J1800/22 NOTAMN

- (J1809/22 NUTAMN)
 Q) CZYZ/QFAXX/IV/NBO/A/000/999/4346N08022W005
 A) CXXX B) 2203171517 C) PERM
 E) CHP2 BE WOOD (HEURISKO POND) (WATER)
 AMEND PUB ICATIONS: OPR TE TO READ: 519-835-0939)



FERGUS (VODAREK FIELD) - CVF2 - Reg

NOTAM

(G0033/23 NOTAMR G2417/22

- (G0033/23 NOTAMR G2417/22
 Q) CZXX/QDECH/IV/NBO/E/000/999/5518N09358W999
 A) CZWG CZYZ B) 2390111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS).
 EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022
FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA
AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
- A) CL72 CLWG B) 230116172 C) 2301200901

 E) AIRSPACE SECURITY WARRING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

(J1800/22 NOTAMN

- (J1809/22 NUTAMN)
 Q) CZYZ/QFAXX/IV/NBO/A/000/999/4346N08022W005
 A) CXXX B) 2203171517 C) PERM
 E) CHP2 BE WOOD (HEURISKO POND) (WATER)
 AMEND PUB ICATIONS: OPR TE TO READ: 519-835-0939)



GUELPH - CNC4 - Req

NOTAM

(U0108/23 NOTAMN

- Q) CZYZ/QO AS/IV/M/AE/000/014/4335N08013W005 A) CXXX B) 2301200115 C) 2302021300
- E) CNC4 GUE PH

OBST GT U/S TOWER 433507N 0801246W (APRX 1.49NM NNW AD) 165FT AG , 1349FT AMS .)

(U0060/23 NOTAMR U1380/22

- Q) CZYZ/Q0 AS/TV/M/AE/000/013/4334N08012W005 A) CXXX B) 2301091808 C) 2304071800EST E) CNC4 GUE PH

OBST GT U/S TOWER 433346N 0801223W (APRX 2809FT W AD) 164FT AG , 1249FT AMS .)

(G0033/23 NOTAMR G2417/22

- Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999
- Q) CZXX/QOECH/TV/NBO/E/000/999/5518N09358W999
 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIT OPERATOR CERTIFICATE (ACC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERTENCING INE TGHT EMERG. EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG
- A $\,$ AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA ATRSPACE. AFFECTED ACCTY WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA ATRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.SC.CA.)

(J6391/22 NOTAMN

- Q) CZYZ/QFZAH/IV/NBO/A/000/999/4334N08012W005
- A) CXXX B) 2209221633 C) PERM E) CNC4 GUE PH

AMEND PUB ICATIONS: CUST HR TO READ: 14-21Z (DT 13-20Z)

(G0067/23 NOTAMR G0065/23

- (G0067/23 NOTAMR G0065/23
 Q) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999
 A) CZYZ CZWG B) 2301181712 C) 2301260901
 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CAMADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)



ELORA - CDF5 - Reg

NOTAM

(G0033/23 NOTAMR G2417/22

- (G0033/23 NOTAMR G2417/22
 Q) CZXX/QDECH/IV/NBO/E/000/999/5518N09358W999
 A) CZWG CZYZ B) 2390111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS).
 EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022
FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA
AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
- A) CL72 CLWG B) 230116172 C) 2301200901

 E) AIRSPACE SECURITY WARRING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

FERGUS (HOLYOAKE AIRFIELD) ON

CPY9

REF	N43 43 43 W80 16 59 4.3NE 10°W UTC-5(4) Elev 1380' VTA A5000	ELEV 1380 O ANDIUS 5 NA
OPR	Wilf Holyoake 519-843-3095 Reg PPR	Q Q Q Q 3100
PF	B-1 C-2,3,4,5 D-6	0 6 6
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
RWY DATA RCR	Rwy 14(136°)/32(316°) 1900x70 turf Opr May-Oct ltd hrs. No win maint. Rwy soft in spring.	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
СОММ		δ , , , , , , , , , , , , , , , , , , ,
ATF	tfc 123.2 2NM 4400 ASL	_
CAUTION	Trees 40 AGL N of Thld 14; gravel road	& 6' ditch before ThId 14.







WILCO













FERGUS (VODAREK FIELD) ON

CVF2

FERGUS (VO	DAREK FIELD) ON CVF2			
REF	N43 43 23 W80 17 21 4ENE 10°W UTC-5(4) Elev 1380' VTA A5000			
OPR	Tom Vodarek 519-843-6515 Reg PPR			
PF c	B-1 C-2,3,4,5 D-6			
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)			
RWY DATA RCR	Rwy 14(143°)/32(323°) 1920x60 turf Opr May-Oct. Ltd hrs. No win maint. Rwy soft in spring.			
СОММ	· 6 } 6			
ATF	tfc 123.2 2NM 4400 ASL			
PRO	Rgt hand circuits Rwy 14 (CAR 602.96)			
CAUTION	Trees 40 AGL at Thid 14. Wildlife in vic of rwy.			



















GUELPH ON		CNC4	
REF	N43 33 49 W80 11 45 1.3NE 10°W UTC-5(4) Elev 1100' VTA A5000 LO6	ELEV 1100	
OPR	Inglis Berry 519-716-0521 or 519-829-3300 Reg	REDIUS SAM	
PF	B-1,2 C-3,4,5,6	2800	
CUST	AOE/15 888-226-7277 14-22Z‡ Mon-Fri exc hols	200	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)		
SERVICES FUEL S	100LL H24 Cardlock 1,2,3,5		
RWY DATA RCR	Rwy 14(144°)/32(324°) 2562x100 TURF/ASPH, centre 40' asphalt Rwy 06(056°)/24(236°) 2006x40 ASPH Thid 24 displ 730' Opr		
LIGHTING	14-(TE LO non-std), 32-(TE LO non-std end of Rwy 32 Only 2053' Igtd.	d) Ngt thid 253' fr end of Rwy 14 & 257' fr	
COMM ATF	UNICOM ltd hrs O/T tfc 123.0 3NM 300	0 ASL	
PRO	Tng Rwy 06/24 proh without prior authori specifications.	zation fr Transport Canada via ops	
CAUTION	Rwy 06/24 aprx 65 AGL. Trees 1260' AS RCL. Steep apch Rwy 24 due to pvt road, thld Rwy 24. Acft flying at Waterloo Regio	terrain, and trees. Ditch & culvert 36' SSE nal aprt (10NM SW of Guelph aprt) Rwy 26 0 ASL. Glider activity 4NM WNW wknds & gress within 1NM radius N43 34 W80 11	







ELORA ON		CDF5
REF	N43 37 57 W80 21 23 4.5SE 10°W (2015) UTC-5(4) Elev 1240' VTA A5000	Q Q Q ELEV 1240
OPR	John Donkers 519-846-0970 Reg PPR	11111
PF	C-1,2,3,4	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) or 519-452-4040	ANDIUS SALLINIS
RWY DATA RCR	Rwy 15(145°)/33(325°) 2575x75 TURF Opr May-Oct. No win maint. Rwy soft in spring.	2900
COMM	tfc 123.2 3NM 4200 ASL	
CAUTION	P-line 30 AGL 325' fr Thld 15.	Office Office

















