

Created using **RPAS Wilco**®

Operation Name: Pilot Name: Pilot Certificate: Flight Start: Flight End: Flight Area (Latitude): Flight Area (Longitude): Altitude - Radius: Airspace: FIR - Contact: Weather:

Hilltop Flying Farmers

January 23, 2023 8:32 AM January 23, 2023 10:32 AM 44° 9' 50.90" N (44.164) 77° 2' 22.60" W (-77.04) Alt: 600 ft - Rad: 926.0 m (0.5 nm) UNCONTROLLED CZYZ - 905-676-4509 -0.9 Celsius - Snow, Partially cloudy

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

Included


Site Survey Obstacles (if available) Nearby Aerodromes Canadian Aviation Regulations GFA Aerodrome Supplements METAR & TAF (if available)

NOTAMS

CFS



Flight Map



MAP Details

Latitude



44° 9' 50.90" N 77° (44.164) (-7 44° 9' 54.50" N 77° (44.1651) (-7


77° 2' 22.60" W (-77.04)

77° 2' 26.20" W (-77.0406)

Longitude



Airspace Classification



Overlying Airspaces

Class	Name	Floor	Ceiling
В	Southern Ontario Low Level Control Area CAE	17000MSL	18000MSL
E	Trenton, ON TCA	700AGL	12500MSL
В	Trenton, ON TCA	12500MSL	17000MSL
E	Trenton, ON TCA	700AGL	17000MSL

Nearest Aerodromes & Distance from Operation

TYENDINAGA (MOHAWK) (CPU6	AERODROME Reg)		Lat: 44.185 Long	: 77.108	5.927 KM	3.2 NM
PICTON (GREENBUSH) (CGB3	AERODROME Reg)		Lat: 44.001 Long	: 77.073	18.335 KM	9.9 NM
PICTON (CNT7 AERODROME	Reg)		Lat: 43.989 Long	: 77.139	21.031 KM	11.36 NM
BELLEVILLE (MARKER FIELD)	(CNU4 AERODROME	Reg)	Lat: 44.192 Long	: 77.309	21.705 KM	11.72 NM

Weather Information for Mission Day

Summary: Partly cloudy throughout the day with early morning snow.

Condition	Temperature	Feels Like	Precipitation	Visibility	Cloud Coverage	Wind Speed	Humidity
Snow, Partially cloudy	0.9 Celsius	5.6 Celsius	100.0 %	16.1 Km	82.6 %	20.5 kph	87.5 %

Canadian Aviation Regulations

Division III — General Operating and Flight Rules

0

For full listing please visit https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

Visual Line-of-sight

- 901.11 (1) Subject to subsection (2) no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - (b) emergency procedures, including with respect to
 - (i) a control station failure,
 - (ii) an equipment failure,
 - (iii) a failure of the remotely piloted aircraft,
 - (iv) a loss of the command and control link,
 - (v) a fly-away, and
 - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation.

Operations at or in the Vicinity of an Aerodrome, Airport or Heliport


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
 - (2) Subject to section 901.73 no pilot shall operate a remotely piloted aircraft at a distance of less than
 - O (a) three nautical miles from the centre of an airport; and
 - O (b) one nautical mile from the centre of a heliport.
 - (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903 03.

Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
 - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights and
 - O (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - (i) the names of the persons who performed them,
 - (ii) the dates they were undertaken,
 - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - (iv) if applicable any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of

 (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).







GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL









GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL







GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL



RPAS WILCO

Flight Plan & Site Survey

TYENDINAGA (MOHAWK) - CPU6 - Reg

NOTAM

(J7506/22 NOTAMR J7233/22 Q) C2YZ/QMR /IV/NBO/A/000/999/4411N07706W005 A) CXXX B) 2211082039 C) PERM E) CPU6 TYENDINAGA (MOHAWK) AMEND PUB ICATIONS: RWY DATA: RWY 09/27 AND RWY 15/33 WIDTH TO READ: 144FT ADD IGHTING: RWY 09 AND RWY 27 NON-STANDARD RED (0) MAY-NOV)

(H0185/23 NOTAMN

Q) CZU /QCAAS/IV/B/AE/000/240/4519N07538W200 A) CZU B) 2301231400 C) 2301231700

E) MONTREA CENTRE PERIPHERA STATION (PA) 128.775MHZ AT OTTAWA U/S

CENTRE DE MONTREA STATION PERIPHERIQUE (PA) 128.775MHZ A OTTAWA U/S)

(G0033/23 NOTAMR G2417/22

(G0033/23 NOTAMR G2417/22 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999 A) CZWG CZYZ B) 230111838 C) 2304121800EST E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING FT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 ATTER MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

Q) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARIMENT OF TRANSPIT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

(G0076/23 NOTAMN Q) CZYZ/QNBAS/IV/B0/AE/000/999/4412N07724W025 A) CYTR B) 2301221409 C) 2301231400 E) TRENTON NDB YTR 215KHZ U/S)

(G2799/22 NOTAMN Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500 E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

(J0132/23 NOTAMR J7122/22 Q) CZYZ/QMRAP/IV/NBO/A/000/999/4411N07706W005 A) CXXX B) 2301091644 C) 2304071600EST RWY 09/27 AND 15/33 AVB PPR 613-885-1340 OR 613-888-6556)

(G2693/22 NOTAMN

Q) CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100

A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR)



PICTON (GREENBUSH) - CGB3 - Reg

NOTAM

(H0185/23 NOTAMN () CZU /QCAAS/IV/B/AE/000/240/4519N07538W200 A) CZU B) 2301231400 C) 2301231700 E) MONTREA CENTRE PERIPHERA STATION (PA) 128.775MHZ AT OTTAWA U/S

FR: CENTRE DE MONTREA STATION PERIPHERIQUE (PA) 128.775MHZ A OTTAWA U/S)

(G0033/23 NOTAMR G2417/22 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFY CANADA'S COASTS). AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.

AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

Q) CZXX/QXXX/I/NBO/W/000/999/5245M09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 26/23) KOREA ISSUED IN AIC 35/22.)

(G0076/23 NOTAMN Q) CZYZ/QNBAS/IV/B0/AE/000/999/4412N07724W025 A) CYTR B) 2301221409 C) 2301231400 E) TRENTON NDB YTR 215KHZ U/S)

(G2799/22 NOTAMN (0) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500 E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

(G2693/22 NOTAMN

CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100

A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR)

WILCO

Flight Plan & Site Survey

PICTON - CNT7 - Req

NOTAM

(H0185/23 NOTAMN () CZU /QCAAS/IV/B/AE/000/240/4519N07538W200 A) CZU B) 2301231400 C) 2301231700 E) MONTREA CENTRE PERIPHERA STATION (PA) 128.775MHZ AT OTTAWA U/S

FR: CENTRE DE MONTREA STATION PERIPHERIQUE (PA) 128.775MHZ A OTTAWA U/S)

(G0033/23 NOTAMR G2417/22 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFY CANADA'S COASTS). AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.

AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

Q) CZXX/QXXX/I/NBO/W/000/999/5245M09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 26/23) KOREA ISSUED IN AIC 35/22.)

(G0076/23 NOTAMN Q) CZYZ/QNBAS/IV/B0/AE/000/999/4412N07724W025 A) CYTR B) 2301221409 C) 2301231400 E) TRENTON NDB YTR 215KHZ U/S)

(G2799/22 NOTAMN (0) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500 E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

(G2693/22 NOTAMN

CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100

A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR)



BELLEVILLE (MARKER FIELD) - CNU4 - Reg

NOTAM

(H0185/23 NOTAWN Q) CZU /QCAAS/IV/B/AE/000/240/4519N07538W200 A) CZU B) 2301231400 C) 2301231700 E) MONTREA CENTRE PERIPHERA STATION (PA) 128.775MHZ AT OTTAWA U/S

FR: CENTRE DE MONTREA STATION PERIPHERIQUE (PA) 128.775MHZ A OTTAWA U/S)

(G0033/23 NOTAMR G2417/22 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999 A) CZWG CZYZ B) 230111838 C) 2304121800EST E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (ACC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F WITHIN 12MM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.

A AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23 0) CZXX/0XXXX/T/NB0/W/000/999/5245N09040W999

Q) CZXX/QXXX/I/NBO/W/000/999/5245M09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901 E) AIRSPACE SECURITY WARWING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

(G0076/23 NOTAMN Q) CZYZ/QNBAS/IV/BO/AE/000/999/4412N07724W025 A) CYTR B) 2301221409 C) 2301231400 E) TRENTON NDB YTR 215KHZ U/S)

(G2799/22 NOTAMN Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500 E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ) (G2693/22 NOTAMN

Q) CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100 A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR)

(U1740/22 NOTAMN Q) C2YZ/QO A5/IV/M/AE/000/007/4412N07724W005 A) CXXX B) 2212211809 C) 2303211700EST E) CBV5 BE EVI E (QHC) (HE I) OBST GT U/S TOWER 441156N 0772418W (APRX 3NM NW AD) 295FT AG , 620FT AMS .) ONTARIO

REF

OPR

PF

PRO

CAUTION

AERODROME/FACILITY DIRECTORY

TYENDINAGA (MOHAWK) ON

CPU6 **ELEV 260** N44 11 05 W77 06 28 3SW 13°W DIUS 5 NA UTC-5(4) Elev 260' A5000 ୢୄଡ଼ୖ First Nations Technical Institute Flt Ops 613-885-1340 Mon-Fri 13-20Z‡ 2300 exc hols Reg B-1 Mon-Fri 13-20Z‡ exc hols C-2,5 11 D-3,4,6 FLT PLN FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) RWY DATA Rwy 09/27 4270x150 asphalt Thld 09 displ 390'. Bay of Quinte Rwy 15/33 2575x150 asphalt Thld 15displ 150'. RCR Opr Ltd win maint сомм ATF Mohawk UNICOM Itd hrs O/T tfc 123 5 5NM 3300 ASL All mil aircrew are rstd fr conducting tng flt at CPU6 unless prior perms has been obtained fr opr.

Extv bird activity Apr-Oct. Possibility of NORDO maint equip on rwys. Extv flt tng



activity on and within 20NM of A/D.





****A/II

ONTARIO

AERODROME/FACILITY DIRECTORY

PICTON (GREENBUSH) ON

CGB3

REF	N44 00 04 W77 04 24 2 87 ESE 12°W (2014) UTC-5(4) Elev 460' A5000	$\begin{bmatrix} 2 & t & 2 \\ t & 2 \\ t & 2 \\ \end{bmatrix} \begin{pmatrix} \frac{1}{2} & \frac{1}{2} \\ \frac{1}{2} & $
OPR	Jeff Douglass 613-885-6917 Reg PPR	
PF	B-1 C-2,3,4,5 D-6	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) or 519-452-4040	RADIUS 5 AM OF THE OP T
SERVICES FUEL	MOGAS PN Opr	
RWY DATA RCR	Rwy 05(049°)/23(229°) 1500x60 TURF Opr No win maint. Rwy soft in spring.	
COMM	tfc 123.2 5NM 3500 ASL	BPAS C
CAUTION		ows at mid-field to 50' to cross seasonal ar may cause mechanical turbulence. Extv ug.



CANADA FLIGHT SUPPLEMENT / GPH 205 Effective 0901Z 29 December 2022 to 0901Z 23 February 2023

ONTARIO

AERODROME/FACILITY DIRECTORY

PICTON ON

CNT7

		Chi		
REF	N43 59 21 W77 08 21 Adj SE 12°W UTC-5(4) Elev 465' A5000			
OPR	Loch Sloy Holdings Ltd. 613-476-3064 Reg PPR			
PF c	C-1,2,3,4,5,6	J. J. A.		
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)			
RWY DATA	Rwy 05/23 2580x150 asphalt Rwy 10/28 2550x150 asphalt Rwy 17/35 2520x150 asphalt Opr No win maint	$\begin{array}{c} 1\\ 1\\ 0\\ 0\\ 0\\ 0\\ 0\\ 0\\ 0\\ 0\\ 0\\ 0\\ 0\\ 0\\ 0\\$		
COMM ATF	tfc 123.2 5NM 3500 ASL			
CAUTION	Extv glider activity 4NM radius to 3500 ASL mid Jun-Aug 31, dly.			



















CANADA FLIGHT SUPPLEMENT / GPH 205 Effective 0901Z 29 December 2022 to 0901Z 23 February 2023

ONTARIO

AERODROME/FACILITY DIRECTORY

BELLEVILLE (MARKER FIELD) ON

CNU4

REF	N44 11 32 W77 18 34 1.8E 12°W UTC-5(4) Elev 320' A5000	2 lings more than 0 LUS State	
OPR	D. Byrd 613-962-7337 Reg PPR		
PF	B-1 C-2,3,4,5,6	(1900)	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)		
SERVICES	1	t 2 2 t 1	
RWY DATA RCR	Rwy 08/26 3280x75 turf/gravel Thid 08 displ 240´. Thid 26 displ 740´. Opr No win maint.		
COMM	tfc 122.8 3.5NM 3300 ASL Area unde	rlies E quadrant of the CYTR Mil CZ	
PRO	Refer VTPC Trenton for east & westbound rtes & Belleville Area alt.		
CAUTION	Glider activity to 2000 ASL.	WILCO	

