

Created using **RPAS Wilco**®

Operation Name:

Pilot Name:

Pilot Certificate:

Flight Start:

Flight End:

Flight Area (Latitude):

Flight Area (Longitude):

Altitude - Radius:

Airspace:

FIR - Contact:

Weather:

Desronto RFC waterfront site

January 21, 2023 5:26 PM

January 21, 2023 7:26 PM

44° 11' 30.80" N (44.192)

77° 2' 56.10" W (-77.049)

Alt: 600 ft - Rad: 926.0 m (0.5 nm)

UNCONTROLLED

CZYZ - 905-676-4509

-1.4 Celsius - Snow, Overcast

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

Included |

Site Survey

Obstacles (if available)

Nearby Aerodromes

Canadian Aviation Regulations

GFA

Aerodrome Supplements


METAR & TAF (if available)

NOTAMs

CFS



Flight Map




MAP Details

| | | Latitude | Longitude |
|---|-------|---------------------------------|---------------------------------|
| × | MODEL | 44° 11' 30.80" N (44.192) | 77° 2' 56.10" W (-77.049) |
| | Pilot | 44° 11' 34.40" N (44.1929) | 77° 2' 59.70" W (-77.0499) |



Airspace Classification



Overlying Airspaces

| Class | Name | Floor | Ceiling |
|-------|---|----------|----------|
| В | Southern Ontario Low Level Control Area CAE | 17000MSL | 18000MSL |
| E | Trenton, ON TCA | 700AGL | 12500MSL |
| В | Trenton, ON TCA | 12500MSL | 17000MSL |
| E | Trenton, ON TCA | 700AGL | 17000MSL |

Nearest Aerodromes & Distance from Operation

| TYENDINAGA (MOHAWK) (CPU6 | AERODROME Reg) | Lat | : 44.185 | Long: 77.10 | 8 4.773 KM | 2.58 NM |
|---------------------------|-----------------|----------|----------|-------------|-------------|----------|
| BELLEVILLE (MARKER FIELD) | (CNU4 AERODROME | Reg) Lat | : 44.192 | Long: 77.30 | 9 20.736 KM | 11.2 NM |
| PICTON (GREENBUSH) (CGB3 | AERODROME Reg) | Lat | : 44.001 | Long: 77.07 | 3 21.313 KM | 11.51 NM |
| PICTON (CNT7 AERODROME | Reg) | Lat | : 43.989 | Long: 77.13 | 9 23.68 KM | 12.79 NM |

Weather Information for Mission Day

Summary: Cloudy skies throughout the day with early morning snow.

| Condition | Temperature | Feels Like | Precipitation | Visibility | Cloud Coverage | Wind Speed | Humidity |
|----------------|-------------|-------------|---------------|------------|----------------|------------|----------|
| Snow, Overcast | 1.4 Celsius | 4.3 Celsius | 100.0 % | 22.1 Km | 95.6 % | 11.9 kph | 83.8 % |

Canadian Aviation Regulations

Division III — General Operating and Flight Rules

For full listing please visit https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

Visual Line-of-sight

- 901.11 (1) Subject to subsection (2) no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - O (b) emergency procedures, including with respect to
 - (i) a control station failure,
 - (ii) an equipment failure.
 - (iii) a failure of the remotely piloted aircraft,
 - (iv) a loss of the command and control link,
 - (v) a fly-away, and
 - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation

Operations at or in the Vicinity of an Aerodrome, Airport or Heliport

0


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
- Subject to section 901.73 no pilot shall operate a remotely piloted aircraft at a distance of less than
 - O (a) three nautical miles from the centre of an airport; and
 - O (b) one nautical mile from the centre of a heliport.
- (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903 03.

Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
 - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights and
 - (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - (i) the names of the persons who performed them.
 - (ii) the dates they were undertaken,
 - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - (iv) if applicable any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
 - O (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).



GFA Issue time + 00 hr - CLOUDS AND WEATHER




GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 06 hr - CLOUDS AND WEATHER




GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 12 hr - CLOUDS AND WEATHER



GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





TYENDINAGA (MOHAWK) - CPU6 - Reg

NOTAM

(J7506/22 NOTAMR J7233/22

- Q) CZYZ/QMR /IV/NBO/A/000/999/4411N07706W005 A) CXXX B) 2211082039 C) PERM
- E) CPU6 TYENDINAGA (MOHAWK)

AMEND PUB ICATIONS: RWY DATA: RWY 09/27 AND RWY 15/33 WIDTH TO READ: 144FT

ADD IGHTING: RWY 09 AND RWY 27 NON-STANDARD RED (0) MAY-NOV)

(G0033/23 NOTAMR G2417/22

- Q) CZXX/Q0ECH/IV/NB0/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
- A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR
 INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE
 CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN
 FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS
 INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION
 OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE
 (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES
 ADE DEDUTITION TO HATED EXTENDED TO AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999
- A) CZYZ CZWG B) 2301181712 C) 2301260901
 E) ATRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN MORTH KOREA. CAMADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIAL RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

- Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025
- A) CYTR B) 2212071605 C) 2302071500 E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

(J0132/23 NOTAMR J7122/22

- Q) CZYZ/QMRAP/IV/NBO/A/000/999/4411N07706W005
- A) CXXX B) 2301091644 C) 2304071600EST E) CPU6 TYENDINAGA (MOHAWK)
- RWY 09/27 AND 15/33 AVB PPR 613-885-1340 OR 613-888-6556)

(G2693/22 NOTAMN

- CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100
- A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR



BELLEVILLE (MARKER FIELD) - CNU4 - Reg

NOTAM

(G2799/22 NOTAMN

- Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500 E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

(G0033/23 NOTAMR G2417/22

- Q) CZXX/Q0ECH/IV/NB0/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
- A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR
 INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE
 CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN
 FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS
 INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION
 OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE
 (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES
 APER PROMETRIES TO REFER EYTL OR OVEREY CAMADA & TERPOTTORIES ARE PROMIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022
FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA
AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NB0/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
- E) AIRSPACE SECURITY WARRING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

(G2693/22 NOTAMN

- Q) CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100
- A) CZYZ B) 2211161400 C) PERM
 E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION:
 DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR)

(U1740/22 NOTAMN

- (U1740/22 NOIANN Q) CZYZ/QO AS/TV/M/AE/000/007/4412N07724W005 A) CXXX B) 2212211809 C) 2303211700EST E) CBV5 BE EVI E (QHC) (HE I) OBST GT U/S TOWER 441156N 0772418W (APRX 3NM NW AD) 295FT AG , 620FT AMS .)



PICTON (GREENBUSH) - CGB3 - Reg

NOTAM

(G2799/22 NOTAMN

- Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500 E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

(G0033/23 NOTAMR G2417/22

- Q) CZXX/Q0ECH/IV/NB0/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
- A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR
 INDIRECT Y OWNED, CHARTERED, EASED, DPERATED OR OTHERWISE
 CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN
 FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS
 INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION
 OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE
 (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES
 ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA
 AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS).
 EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022
FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA
AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NB0/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
- E) AIRSPACE SECURITY WARRING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

(G2693/22 NOTAMN

- (62693/22 NOIANN
 Q) CZYZ/QARCH/IV/BO/E/600/220/4429N07732W100
 A) CZYZ B) 2211161400 C) PERM
 E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION:
 DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR
 ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR)



PICTON - CNT7 - Reg

NOTAM

(G2799/22 NOTAMN

- Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500 E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

(G0033/23 NOTAMR G2417/22

- Q) CZXX/Q0ECH/IV/NB0/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2301111838 C) 2304121800EST
- A) CZWG CZYZ B) 2301111838 C) 2304121800EST
 E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR
 INDIRECT Y OWNED, CHARTERED, EASED, DPERATED OR OTHERWISE
 CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN
 FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS
 INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION
 OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE
 (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES
 ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA
 AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS).
 EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022
FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA
AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G0067/23 NOTAMR G0065/23

- Q) CZXX/QXXXX/I/NB0/W/000/999/5245N09040W999 A) CZYZ CZWG B) 2301181712 C) 2301260901
- E) AIRSPACE SECURITY WARRING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIC 35/22.)

(G2693/22 NOTAMN

- (62693/22 NOIANN
 Q) CZYZ/QARCH/IV/BO/E/600/220/4429N07732W100
 A) CZYZ B) 2211161400 C) PERM
 E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION:
 DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR
 ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR)

TYENDINAGA (MOHAWK) ON CPU6 REF N44 11 05 W77 06 28 3SW 13°W UTC-5(4) Elev 260' A5000 OPR First Nations Technical Institute Fit Ops 613-885-1340 Mon-Fri 13-20Z‡ 2300 exc hols Reg PF B-1 Mon-Fri 13-20Z‡ exc hols C-2,5 D-3,4,6 FLT PLN FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) RWY DATA Rwy 09/27 4270x150 asphalt Thid 09 displ 390'. Rwy 15/33 2575x150 asphalt ThId 15displ 150'. RCR Opr Ltd win maint сомм ATF Mohawk UNICOM Itd hrs O/T tfc 123 5 5NM 3300 ASL PRO All mil aircrew are rstd fr conducting tng flt at CPU6 unless prior perms has been obtained fr opr.



CAUTION



activity on and within 20NM of A/D.

Extv bird activity Apr-Oct. Possibility of NORDO maint equip on rwys. Extv flt tng















BELLEVILLE (MARKER FIELD) ON

CNU₄

| | (1111 (1111 1111 1111 1111 1111 1111 1111 1111 1111 | |
|----------------|--|--|
| REF | N44 11 32 W77 18 34 1.8E 12°W UTC-5(4) Elev 320′ A5000 | 2 lines mumin Q ELEV 320 |
| OPR | D. Byrd 613-962-7337 Reg PPR | |
| PF | B-1 C-2,3,4,5,6 | (1900) |
| FLT PLN FIC | London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) | silo silo time to the s |
| SERVICES S | 1 | \$ 800000 3280° |
| RWY DATA RCR | Rwy 08/26 3280x75 turf/gravel Thid 08 displ 240'. Thid 26 displ 740'. Opr No win maint. | |
| COMM | tfc 122.8 3.5NM 3300 ASL Area unde | rlies E quadrant of the CYTR Mil CZ |
| PRO | Refer VTPC Trenton for east & westbou | nd rtes & Belleville Area alt. |
| CAUTION | Glider activity to 2000 ASL. | WILCO |



















PICTON (GREENBUSH) ON

CGB3

| | Eliboon, on | |
|------------------|--|--|
| REF | N44 00 04 W77 04 24 2 87 ESE 12°W (2014) UTC-5(4) Elev 460' A5000 | $ \begin{array}{c cccc} & & & & & & & & \\ & & & & & & & \\ & & & &$ |
| OPR | Jeff Douglass 613-885-6917 Reg PPR | 0 0 |
| PF | B-1 C-2,3,4,5 D-6 | 1 |
| FLT PLN FIC | London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) or 519-452-4040 | ADIUS 5 MAR Q |
| SERVICES FUEL | MOGAS PN Opr | 2100 |
| RWY DATA RCR | Rwy 05(049°)/23(229°) 1500x60 TURF Opr No win maint. Rwy soft in spring. | t t |
| COMM | tfc 123.2 5NM 3500 ASL | S RPAS |
| CAUTION | | ows at mid-field to 50' to cross seasonal ar may cause mechanical turbulence. Extv ug. |



















| PICTON ON | | CNT7 |
|----------------|--|---------------------------------------|
| REF | N43 59 21 W77 08 21 Adj SE 12°W UTC-5(4) Elev 465′ A5000 | |
| OPR | Loch Sloy Holdings Ltd. 613-476-3064 Reg PPR | 2100 |
| PF | C-1,2,3,4,5,6 | |
| FLT PLN FIC | London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) | 2550 |
| RWY DATA RCR | Rwy 05/23 2580x150 asphalt Rwy 10/28 2550x150 asphalt Rwy 17/35 2520x150 asphalt Opr No win maint | 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 |
| COMM ATF | tfc 123.2 5NM 3500 ASL | |
| CAUTION | Extv glider activity 4NM radius to 3500 A | ASL mid Jun-Aug 31, dly. |

















