

# Created using **RPAS Wilco**®

Operation Name:

Pilot Name:

Pilot Certificate:

Flight Start:

Flight End:

Flight Area (Latitude):

Flight Area (Longitude):

Altitude - Radius:

Airspace:

FIR - Contact:

Weather:

Prince Edward



January 22, 2023 12:59 PM

January 22, 2023 2:59 PM

43° 57' 47.20" N ( 43.963 )

77° 6' 46.60" W ( -77.113 )

Alt: 600 ft - Rad: 926.0 m ( 0.5 nm)

UNCONTROLLED

CZYZ - 905-676-4509

0.2 Celsius - Snow, Rain, Overcast

Please ensure you received all required authorizations prior to flight.

# Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

# Included |

Site Survey

Obstacles (if available)

**Nearby Aerodromes** 

Canadian Aviation Regulations

GFA

Aerodrome Supplements


METAR & TAF (if available)

**NOTAMs** 

CFS



# Flight Map




# MAP Details

		Latitude	Longitude
×	MODEL	43° 57' 47.20" N ( 43.963 )	77° 6' 46.60" W ( -77.113 )
	Pilot	43° 57' 50.80" N ( 43.9641 )	77° 6' 50.20" W ( -77.1139 )



# Airspace Classification



# Overlying Airspaces

Class	Name	Floor	Ceiling
E	Trenton, ON TCA	700AGL	12500MSL
В	Trenton, ON TCA	12500MSL	17000MSL
E	Trenton, ON TCA	700AGL	17000MSL
В	Southern Ontario Low Level Control Area CAE	17000MSL	18000MSL

# Nearest Aerodromes & Distance from Operation

PICTON (CNT7 AERODROME Reg)	Lat: 43.989	Long: 77.139	3.554 KM	1.92 NM
PICTON (GREENBUSH) (CGB3 AERODROME Reg)	Lat: 44.001	Long: 77.073	5.288 KM	2.86 NM
PICTON (PRINCE EDWARD COUNTY HOSP) (CPE7 HELIPORT Cert)	Lat: 44.016	Long: 77.138	6.213 KM	3.35 NM
MOUNTAIN VIEW (CPZ3 AERODROME DND)	Lat: 44.07	Long: 77.339	21.634 KM	11.68 NM

# Weather Information for Mission Day

Summary: Cloudy skies throughout the day with a chance of rain or snow throughout the day.

Condition	Temperature	Feels Like	Precipitation	Visibility	Cloud Coverage	Wind Speed	Humidity
Snow, Rain, Overcast	0.2 Celsius	3.8 Celsius	100.0 %	9.9 Km	97.7 %	20.4 kph	89.5 %

# Canadian Aviation Regulations

## Division III — General Operating and Flight Rules

For full listing please visit https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

### Visual Line-of-sight

- 901.11 (1) Subject to subsection (2) no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

### Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
  - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
  - O (b) emergency procedures, including with respect to
    - (i) a control station failure,
    - (ii) an equipment failure.
    - (iii) a failure of the remotely piloted aircraft,
    - (iv) a loss of the command and control link,
    - (v) a fly-away, and
    - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

## Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation

## Operations at or in the Vicinity of an Aerodrome, Airport or Heliport

0


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
- Subject to section 901.73 no pilot shall operate a remotely piloted aircraft at a distance of less than
  - O (a) three nautical miles from the centre of an airport; and
  - O (b) one nautical mile from the centre of a heliport.
- (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903 03.

## Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
  - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights and
    - (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
      - (i) the names of the persons who performed them.
      - (ii) the dates they were undertaken,
      - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
      - (iv) if applicable any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
  - O (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
  - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).



GFA Issue time + 00 hr - CLOUDS AND WEATHER




GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 06 hr - CLOUDS AND WEATHER




# GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






# GFA Issue time + 12 hr - CLOUDS AND WEATHER



# GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





# PICTON - CNT7 - Req

## NOTAM

### (H0185/23 NOTAMN

- Q) CZU /QCAAS/IV/B/AE/000/240/4519N07538W200 A) CZU B) 2301231400 C) 2301231700
- E) MONTREA CENTRE PERIPHERA STATION (PA ) 128.775MHZ AT OTTAWA U/S

CENTRE DE MONTREA STATION PERIPHERIQUE (PA ) 128.775MHZ A OTTAWA U/S)

- (G0033/23 NOTAMR G2417/22 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999
- A) CZWG CZYZ B) 2301111838 C) 2304121800EST E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

## (G0067/23 NOTAMR G0065/23

- O) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999
- Q) CZXX/QXXXX/I/NBO/W/6006/999/5245N09040W999
  A) CZYZ CZWG B) 2301181712 C) 2301260901
  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIG 26 (22) KOREA ISSUED IN AIC 35/22.)

### (G0076/23 NOTAMN

- (Q) CZYZ/QNBAS/IV/BO/AE/000/999/4412N07724W025 A) CYTR B) 2301221409 C) 2301231400 E) TRENTON NDB YTR 215KHZ U/S)

- Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500
- E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

- CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100
- A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR



# PICTON (GREENBUSH) - CGB3 - Reg

## **NOTAM**

### (H0185/23 NOTAMN

- Q) CZU /QCAAS/IV/B/AE/000/240/4519N07538W200 A) CZU B) 2301231400 C) 2301231700
- E) MONTREA CENTRE PERIPHERA STATION (PA ) 128.775MHZ AT OTTAWA U/S

CENTRE DE MONTREA STATION PERIPHERIQUE (PA ) 128.775MHZ A OTTAWA U/S)

- (G0033/23 NOTAMR G2417/22 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999
- A) CZWG CZYZ B) 2301111838 C) 2304121800EST E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

## (G0067/23 NOTAMR G0065/23

- O) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999
- Q) CZXX/QXXXX/I/NBO/W/6006/999/5245N09040W999
  A) CZYZ CZWG B) 2301181712 C) 2301260901
  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIG 26 (22) KOREA ISSUED IN AIC 35/22.)

### (G0076/23 NOTAMN

- (Q) CZYZ/QNBAS/IV/BO/AE/000/999/4412N07724W025 A) CYTR B) 2301221409 C) 2301231400 E) TRENTON NDB YTR 215KHZ U/S)

- Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500
- E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

- CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100
- A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR



# PICTON (PRINCE EDWARD COUNTY HOSP) - CPE7 - Cert

# **NOTAM**

### (H0185/23 NOTAMN

- Q) CZU /QCAAS/IV/B/AE/000/240/4519N07538W200 A) CZU B) 2301231400 C) 2301231700
- E) MONTREA CENTRE PERIPHERA STATION (PA ) 128.775MHZ AT OTTAWA U/S

CENTRE DE MONTREA STATION PERIPHERIQUE (PA ) 128.775MHZ A OTTAWA U/S)

- (G0033/23 NOTAMR G2417/22 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999
- A) CZWG CZYZ B) 2301111838 C) 2304121800EST E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

## (G0067/23 NOTAMR G0065/23

- O) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999
- Q) CZXX/QXXXX/I/NBO/W/6006/999/5245N09040W999
  A) CZYZ CZWG B) 2301181712 C) 2301260901
  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIG 26 (22) KOREA ISSUED IN AIC 35/22.)

### (G0076/23 NOTAMN

- (Q) CZYZ/QNBAS/IV/BO/AE/000/999/4412N07724W025 A) CYTR B) 2301221409 C) 2301231400 E) TRENTON NDB YTR 215KHZ U/S)

- Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500
- E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

- CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100
- A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR



# MOUNTAIN VIEW - CPZ3 - DND

## **NOTAM**

### (H0185/23 NOTAMN

- Q) CZU /QCAAS/IV/B/AE/000/240/4519N07538W200 A) CZU B) 2301231400 C) 2301231700
- E) MONTREA CENTRE PERIPHERA STATION (PA ) 128.775MHZ AT OTTAWA U/S

CENTRE DE MONTREA STATION PERIPHERIQUE (PA ) 128.775MHZ A OTTAWA U/S)

- (G0033/23 NOTAMR G2417/22 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999
- A) CZWG CZYZ B) 2301111838 C) 2304121800EST E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR E) A ACFT, REGARD ESS OF THE STATE OF REGISTRY, DIRECT Y OR INDIRECT Y OWNED, CHARTERED, EASED, OPERATED OR OTHERWISE CONTRO ED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BE ARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE AWS OF THE RUSSIAN FEDERATION OR BE ARUS, AND A OPERATORS HO DING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BE ARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERF Y CANADA'S TERRITORIA AIRSPACE (INC UDING F T WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INF IGHT EMERG.
- AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER F T SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIA AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR C R INTO CANADA'S TERRITORIA AIRSPACE MAY APP Y TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAI AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

## (G0067/23 NOTAMR G0065/23

- O) CZXX/QXXXX/I/NBO/W/000/999/5245N09040W999
- Q) CZXX/QXXXX/I/NBO/W/6006/999/5245N09040W999
  A) CZYZ CZWG B) 2301181712 C) 2301260901
  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN NORTH KOREA. CANADIAN AIR OPERATORS AND OWNERS OF AIRCRAFT REGISTERED IN CANADA ARE ADVISED NOT TO ENTER THE PYONGYANG FIR (ZKKP), DUE TO POTENTIA RISK TO AVIATION FROM BA ISTIC MISSI E AUNCHES WITHOUT PRIOR NOTICE. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING NORTH KOREA ISSUED IN AIG 26 (22) KOREA ISSUED IN AIC 35/22.)

### (G0076/23 NOTAMN

- (Q) CZYZ/QNBAS/IV/BO/AE/000/999/4412N07724W025 A) CYTR B) 2301221409 C) 2301231400 E) TRENTON NDB YTR 215KHZ U/S)

- Q) CZYZ/QCAAS/IV/B/AE/000/999/4407N07732W025 A) CYTR B) 2212071605 C) 2302071500
- E) WING OPS UHF 268.0MHZ U/S. CTC WING OPS VHF 122.35MHZ)

- CZYZ/QARCH/IV/B0/E/000/220/4429N07732W100
- A) CZYZ B) 2211161400 C) PERM E) AMEND PUB ICATIONS: MANDATORY IFR ROUTES: OCATION TO OCATION: DE ETE: CYOW H AND DEP TO CYTZ RNAV AP OV ORKA I IXU ARR ADD: CYOW H AND DEP TO CYTZ F 220 RNAV AP OV ORKA I IXU ARR

PICTON ON		CNT7
REF	N43 59 21 W77 08 21 Adj SE 12°W UTC-5(4) Elev 465′ A5000	CELEV 465
OPR	Loch Sloy Holdings Ltd. 613-476-3064 Reg PPR	2100
PF	C-1,2,3,4,5,6	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	2550'
RWY DATA  RCR	Rwy 05/23 2580x150 asphalt Rwy 10/28 2550x150 asphalt Rwy 17/35 2520x150 asphalt Opr No win maint	Q Q Q Q
COMM	tfc 123.2 5NM 3500 ASL	
CAUTION Extv glider activity 4NM radius to 3500 /		ASL mid Jun-Aug 31, dly.



















# PICTON (GREENBUSH) ON

CGB3

1 10 10 11 (011)	LINDOON) ON	CGBO
REF	N44 00 04 W77 04 24 2 87 ESE 12°W (2014) UTC-5(4) Elev 460' A5000	$\begin{bmatrix} Q & & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & $
OPR	Jeff Douglass 613-885-6917 Reg PPR	0 0
PF	B-1 C-2,3,4,5 D-6	1
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) or 519-452-4040	ADIUS 5 MA
SERVICES FUEL	MOGAS PN Opr	2100
RWY DATA RCR	Rwy 05(049°)/23(229°) 1500x60 TURF Opr No win maint. Rwy soft in spring.	1 1 2
COMM	tfc 123.2 5NM 3500 ASL	O RPAS
CAUTION		ows at mid-field to 50' to cross seasonal ar may cause mechanical turbulence. Extv ug.



















### PICTON (PRINCE EDWARD COLINTY HOSP)

CPE7

I IOTON (FINI	ICE EDWARD COUNTY HOSP) ON (Hell)	GPE/
REF	N44 00 59 W77 08 17 Adj 12°W (2012) UTC-5(4) Elev 353´ A5000	ELEV 353 Picton Bay
OPR	Quinte Health Care 613-969-7400 Cert	SE TOT WHITE
PF c	C-1,2,3,4,5,6	1 / 1 / 1 / A
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	2050
HELI DATA RCR	FATO/TLOF 82' dia CONC/ASPH Safety Area 110' x 110' Max heli overall length 54.6' Opr	
LIGHTING	RY(LO) RF(FL&FH)	
COMM	tfc 123.2 5NM 3400ASL	PDAS O
PRO	Arr/dep btwn 295°-360° & 045°-090° fr h	neli, slope 8% (H3), day/night use.



















CAUTION

TRENTON / I	MOUNTAIN VIEW ON	CPZ3
REF	N44 04 12 W77 20 22 5 2SE 12°W (2022) UTC-5(4) Elev 362' A5000 LO6 LO7 HI5	# Q ELEV 362
OPR LCO	DND All users 24 hr PPR through Trenton Ops 613-965-3316, CSN 319-827-3316 Fax 613-965-7093. Regardless of PPR all users check in with Wg Ops via phone or radio 122.35, 268.0 prior to using Mountain View aprt.	1900 field
PF	B-1 D-2,3,5	and marks who was a
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) (Note: Wg Ops/ATC will not accept telephone/air filing).	# 5 # # # # # # # # # # # # # # # # # #
SERVICES MIL ADV	Trenton 268.0 or 122.35 20 min prior to	o ldg
RWY DATA RCR	side) Rwy 06L(060°)/24R(240°) 4797X60 GR Rwy 16(158°)/34(338°) 3004X150 crush	
LIGHTING		anels avbl. Overt/covert AMP3 lgt avbl Rwy 24R ARCAL 123.3, both type J; overt lgt avbl ys PNR
COMM		erlies the SE quadrant of the CYTR Mil CZ. or to entering the Mountain View ATF area.
PRO	end of the rwy. Acft on apch for Rwy 24l less than 3° initiate go around before ov Increased mil tfc within 35NM of CYTR. (135.45) prior to contacting CYTR Twr fc glider activity at Trenton (CYTR) & Mour	nall only turn around on the first 300ft of each L & 24R must maintain 3° GP due to hwy, if erflight of hwy exc Gliders and tow acft. Pilots are advised to listen to CYTR ATIS or entry into ATF area. Extensive paradrop & tain View to 3500 ASL, ocsl to 12,500 ASL.

Timing and alt will be bost on ATIS. Non-std circuit pro for mil acft. All users external to 8 Wing intending to conduct training at Mountain View must request permission and a procedures briefing. Request permission from 8 Wing Ops at 613-392-2811 ext

Possible NORDO vehicles on rwy/twy, verify rwy unobstructed prior to ldg.

4560/2559/2766 a minimum of 24 hours in advance.