



This certifies that MAAC has reauthorized **HESPELER MODEL AVIATORS INC [Club 496, Zone E]**

To operate the following categories of models: **mRPAS and RPAS**

At or from the following location: **2400 HESPELER RD, CAMBRIDGE** (Land-based RC on private land) – within 0.5 nm of **43° 27' 45.10" N, 80° 18' 38.0" W**

This authorization is contingent upon all members who use this site following the applicable Canadian Aviation Regulations, local laws, and all MAAC, Club or event rules. MAAC provides the following direction:

This site is in Kitchener/Waterloo Airport (CYKF) Class C Control Zone controlled airspace.

All RPAS must conform with the MAAC Safety assurance/manufacturer declaration policy or another manufacturer's safety assurance/manufacturer declaration.

All pilots responsible for RPAS operation must have an Advanced RPAS operator certificate.

All pilots responsible for RPAS operation must receive approval from NAV CANADA using NAV DRONE.

This site has been approved for mRPAS (sub-250gram) and RPAS operation only in accordance with the approved site rules. Clear procedures in the event of a lateral or vertical flyaway outside the approved flying area must be included in club rules, with the contact information for Air Traffic Services (CYKF ATC) prominently displayed at the site. (CAR 901.15).

Per CAR 901.47(2), as the pilot stations are located within 3nm of an airport (Kitchener/Waterloo airport (CYKF) 2.98nm northwest), the club rules must comply with MAAC policy and procedure documents and must contain any additional procedures the Club deems appropriate to meet CAR 901.73 and the guidance contained in TP 14371, RPA Section 3.2.35 and 3.4.5, and which otherwise permit RPAS operation in a manner that should not interfere with aircraft operating in the established traffic pattern (CAR 901.47(1)).

Any changes to club rules or procedures upon which this authorization was issued must be sent to MAAC.

CAR compliance remains an individual responsibility.

This authorization is valid until the HESPELER MODEL AVIATORS INC [Club 496, Zone E] fails to renew their MAAC membership, dissolves, or otherwise does not comply with any MAAC requirements or requests.

President, MAAC

Nov 24 2023

Date