

Created using **RPAS Wilco**®

Operation Name: Pilot Name: Pilot Certificate: Flight Start: Flight End: Flight Area (Latitude): Flight Area (Longitude): Altitude - Radius: Airspace: FIR - Contact:

Bushplane Museum Survey Craig Knight PC2305719100 December 13, 2023 9:17 PM December 13, 2023 11:59 PM 46° 30' 16.06" N (46.504) 84° 19' 27.16" W (-84.324) Alt: 100 ft - Rad: 100 m (0.05 nm) UNCONTROLLED CZYZ - 905-676-4509

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

Included

Site Survey Obstacles (if available) Nearby Aerodromes Canadian Aviation Regulations GFA Aerodrome Supplements -METAR & TAF (if available) -NOTAMs

-CFS


RPAS WILCO

Flight Plan & Site Survey

Flight Map



MAP Details



Longitude



Airspace Classification



Overlying Airspaces

No Airspace Info Available

Nearest Aerodromes & Distance from Operation

SAULT STE. MARIE (CPX8 - WATERDROME - Reg)	Lat: 46.504 Long: -84.323 0.106 KM 0.06 NM
SAULT STE. MARIE (CNR3 - HELIPORT - Reg)	Lat: 46.504 Long: -84.323 0.106 KM 0.06 NM
PARTRIDGE POINT (CPP9 - WATERDROME - Reg)	Lat: 46.514 Long: -84.248 5.928 KM 3.2 NM
SAULT STE. MARIE (SAULT AREA HOSP) (CSM9 - HELIPORT - Cert)	Lat: 46.547 Long: -84.312 4.822 KM 2.6 NM
SAULT STE. MARIE (CYAM - AERODROME - Cert)	Lat: 46.485 Long: -84.509 14.31 KM 7.73 NM

Canadian Aviation Regulations

Division III — General Operating and Flight Rules

0

For full listing please visit : https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

Visual Line-of-sight

- 901.11 (1) Subject to subsection (2), no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - (b) emergency procedures, including with respect to
 - (i) a control station failure,
 - (ii) an equipment failure,
 - (iii) a failure of the remotely piloted aircraft,
 - (iv) a loss of the command and control link,
 - (v) a fly-away, and
 - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation.

Operations at or in the Vicinity of an Aerodrome, Airport or Heliport


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
 - (2) Subject to section 901.73, no pilot shall operate a remotely piloted aircraft at a distance of less than
 - O (a) three nautical miles from the centre of an airport; and
 - O (b) one nautical mile from the centre of a heliport.
 - (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Records

- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
 - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights; and
 - O (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - (i) the names of the persons who performed them,
 - (ii) the dates they were undertaken,
 - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - (iv) if applicable, any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of


 (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).






GFA Issue time + 00 hr - CLOUDS AND WEATHER


GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL









GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL







GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





SAULT STE. MARIE - CPX8 - Reg

NOTAM

(M3440/23 NOTAMR M3434/23 Q) CZYZ/QCAAS/IV/B/AE/000/999/4629N08431W070 A) CYAM B) 2312062147 C) 2312152359 E) SAULT STE. MARIE EMERG FREQ 243.0MHZ U/S)

(G2479/23 NOTAMR G1466/23

Q) CZXX/Q0ECH/IV/NBO/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2310091803 C) 2401081800EST E) ALL ACT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATO CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CANADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G2482/23 NOTAMN

() CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310102347 C) 2401101700EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

(G2577/23 NOTAMR G2576/23

() CZXX/Q0EXX/IV/NBO/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310201806 C) 2401192359EST E) ATRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)



SAULT STE. MARIE - CNR3 - Reg

NOTAM

(M3440/23 NOTAMR M3434/23 Q) CZYZ/QCAAS/IV/B/AE/000/999/4629N08431W070 A) CYAM B) 2312062147 C) 2312152359 E) SAULT STE. MARIE EMERG FREQ 243.0MHZ U/S)

(G2479/23 NOTAMR G1466/23

Q) CZXX/Q0ECH/IV/NBO/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2310091803 C) 2401081800EST E) ALL ACT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATO CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CANADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G2482/23 NOTAMN

() CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310102347 C) 2401101700EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

(G2577/23 NOTAMR G2576/23

() CZXX/Q0EXX/IV/NBD/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310201806 C) 2401192359EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)



PARTRIDGE POINT - CPP9 -Req

NOTAM

(G2577/23 NOTAMR G2576/23 (0257/23 NOTANR 02576/23 Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310201806 C) 2401192359EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE ADVISOR AND STREETUR (ADVIS) DIE TO DOTENTIAL DISK TO AUTOTION AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

(M3440/23 NOTAMR M3434/23 Q) CZYZ/QCAAS/IV/B/AE/000/999/4629N08431W070 A) CYAM B) 2312062147 C) 2312152359 E) SAULT STE. MARIE EMERG FREQ 243.0MHZ U/S)

(G2479/23 NOTAMR G1466/23 Q) CZXX/QOECH/IV/NBO/E/000/999/5518N09358W999 A) CZWG CZYZ B) 23100931803 C) 2401081800EST E) ALL ACFT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACTT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CANADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G2482/23 NOTAMN

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 C) CZWG CZWG B) 2310102347 C) 2401101700EST
 E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)



SAULT STE. MARIE (SAULT AREA HOSP) - CSM9 - Cert

NOTAM

(M3440/23 NOTAMR M3434/23 Q) C2YZ/QCAAS/IV/B/AE/000/999/4629N08431W070 A) CYAM B) 2312062147 C) 2312152359 E) SAULT STE. MARIE EMERG FREQ 243.0MHZ U/S)

(G2479/23 NOTAMR G1466/23

Q) CZXX/Q0ECH/IV/NBO/E/000/999/5518N09358W999 A) CZWG CZYZ B) 2310091803 C) 2401081800EST E) ALL ACT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATO CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CANADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G2482/23 NOTAMN

() CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310102347 C) 2401101700EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

(G2577/23 NOTAMR G2576/23

Q) CZXX/Q0EXX/IV/NB0/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310201806 C) 2401192359EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)



SAULT STE. MARIE - CYAM - Cert

METAR

METAR CYAM 140200Z 22006KT 15SM FEW044 SCT170 BKN250 M02/M07 A3054 RMK SC1AC3CI SC TR SLP355=

METAR	LOCATION	DATE - TIME	
	CYAM - SAULT STE. MARIE/ON	14 DECEMBER 2023 -	
		0200 UTC	
WIND	VISIBILITY	RUNWAY VISUAL RANGE	
220 TRUE @ 6	15 STAT. MILES		
KNOTS			
WEATHER	CLOUDINESS	TEMP / DEWPOINT	
	FEW CLOUDS (1/8 - 2/8)	-2 C / -7 C	
	4400 FT		
	SCATTERED CLOUDS		
	(3/8 - 4/8) 17000 FT		
	BROKEN CLOUDS (5/8 - 7/8)		
	25000 FT		
ALTIMETER	RECENT WEATHER	WIND SHEAR	
30.54 IN HG			

METAR CYAM 140100Z 21007KT 15SM FEW044 SCT170 BKN250 M02/M07 A3055 RMK SC2AC1CI SLP360=

METAR	LOCATION CYAM - SAULT STE. MARIE/ON	DATE - TIME 14 DECEMBER 2023 - 0100 UTC
WIND 210 TRUE @ 7 KNOTS	VISIBILITY 15 STAT. MILES	RUNWAY VISUAL RANGE
WEATHER	CLOUDINESS FEW CLOUDS (1/8 - 2/8) 4400 FT SCATTERED CLOUDS (3/8 - 4/8) 17000 FT BROKEN CLOUDS (5/8 - 7/8) 25000 FT	TEMP / DEWPOINT -2 C / -7 C
ALTIMETER 30.55 IN HG	RECENT WEATHER	WIND SHEAR

METAR CYAM 14000 SLP358=	0Z 22007KT 20SM 0VC046	M02/M08 A3055 RMK SC8
METAR	LOCATION CYAM - SAULT STE. MARIE/ON	DATE - TIME 14 DECEMBER 2023 - 0000 UTC
WIND 220 TRUE @ 7 KNOTS	VISIBILITY 20 STAT. MILES	RUNWAY VISUAL RANGE

WEATHER	CLOUDINESS OVERCAST 4600 FT	TEMP / DEWPOINT -2 C / -8 C
ALTIMETER 30.55 IN HG	RECENT WEATHER	WIND SHEAR

TAF

TAF CYAM 140140Z 1402/1414 24008KT P6SM SCT020 BKN050 FM140300 25006KT P6SM BKN120 RMK NXT FCST BY 140800Z=				
TAI	=	LOCATIO CYAM - SAUL ⁻ MARIE/O	T STE.	VALIDITY [UTC] 14 DEC - 0140 to 14 DEC - 1400
TIMES [UTC]WIND [DEGREES TRUE]VISIBILITY [STAT. MILES]WEATHER [CLOUDINESS [FEET AGL]				
14 DEC - 0200 to 14 DEC - 0300	240 @ 8 KNOTS	6+	NIL	2000 SCATTERED 5000 BROKEN
14 DEC - 250 @ 6+ NIL 12000 BROKEN 14 DEC - 6 KNOTS 6+ NIL 12000 BROKEN				
	REMARKS			

NOTAM

(J7005/23 NOTAMR J6918/23

ADDN NON-GRF/TALPA INFO:

(J7653/23 NOTAMR J5696/23

(G2479/23 NOTAMR G1466/23

TC)

CRFI 04/22 -1C .55 OBS AT 2312132216.) (M3440/23 NOTAMR M3434/23 Q) CZYZ/QCAAS/IV/B/AE/000/999/4629N08431W070 A) CYAM B) 2312062147 C) 2312152359 E) SAULT STE. MARIE EMERG FREQ 243.0MHZ U/S)

Q) CZYZ/QFAXX/IV/NB0/A/000/999/4629N08431W005

A) CTAM B) 2312132220 C) 2312140230 E) RSC 04 6/6/6 10 PCT COMPACTED SNOW, 10 PCT COMPACTED SNOW, 10 PCT COMPACTED SNOW. 140FT WIDTH. REMAINING WIDTH COMPACTED SNOW. VALID DEC 13 2216 - DEC 14 0616.

RSC 22 6/6/6 10 PCT COMPACTED SNOW, 10 PCT COMPACTED SNOW, 10 PCT COMPACTED SNOW. 140FT WIDTH. REMAINING WIDTH COMPACTED SNOW. VALID DEC 13 2216 - DEC 14 0616.

(J/63/23 NUIAWK J5056/23 Q) CZYZ/QFAXX/IV/NBO/A/000/999/4629N08431W005 A) CYAM B) 2312071639 C) 2401110901EST E) AUTOLAND PROCEDURES NOT RECOMMENDED DUE TO POSSIBLE INTERFERENCE TO RADALT FROM 5G NETWORK RESULTING IN DEGRADED SYSTEM PERFORMANCE. REPORT ANY SUSPECTED CASES OF INTERFERENCE TO ATC OR

(62479/23 NOTAWR 61466/23 9) CZXX/QOECH/Y/VNBO/Z909/5518N09358W999 A) CZWG CZYZ B) 2310091803 C) 2401081800EST E) ALL ACFT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATOR CERTIFICATE

RSC 12 6/6/6 DRY, DRY, DRY. VALID DEC 13 2216 - DEC 14 0616. RSC 30 6/6/6 DRY, DRY, DRY. VALID DEC 13 2216 - DEC 14 0616.

(A6565/23 NOTAMR A6353/23

(J)05/23 WUMAW J9910/23 Q) CZY2/QFUAH/IV/NBK0/A/000/999/4629N08431W005 A) CYAM B) 2311041807 C) 2402011600EST E) PVT ADV EXECUTUR AVIATION FUEL HR OF OPS TO READ: 1100-0000 AVBL AFTER HR CALL OUT CHARGE APPLY 249-889-1244)

(AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CANADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

(G2482/23 NOTAMN

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310102347 C) 2401101700EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

(62577/23 NOTAMR 62576/23

(G257/23 NOTAWR G2576/23 Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZYZ CZWG B) 2310201806 C) 2401192359EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

SAULT STE. MARIE ON

REF	N46 30 16 W84 19 24 Adj S 7°W UTC-5(4) Elev 580′ A5001	····· ································
OPR	Cdn Bushplane Heritage Centre 705-945-6242 Reg	
PF	B1 avbl 13-22Z‡ C-2,3,4,5,6	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
SERVICES FUEL	12-23Z May-Oct 100LL PN Humphrey Aviation Service 705-542-2590 1,2,3,4,5	CANADA U.S.A. St Marys River
A/D DATA	Open water May-Nov. Current 5 kt, ramp, slipway	
LIGHTING	Floodlit 24 hrs.	RPAS
COMM ATF	tfc 122.7 2NM 3000 ASL	WILCO
PRO	See Sault Ste. Marie VTPC.	
CAUTION	Co-lctd heliport, helipads aprx 200' E of aprt, also on 122.7. Ramp usage is depe	docks. High IvI of tfc in vic Sault, Michigan endent on IvI of St. Mary's River. Ctc opr.

CPX8

CPP9

SAULT STE. MARIE FSS-RCO

London 119.4 (RAAS) 0345-1120Z‡ (N43 01 W81 09)

SAULT STE. MARIE / PARTRIDGE POINT ON

ON OFFICIE				0110
REF	N46 30 51 W84 14 54 Adj E 7°W (2023) UTC-5(4) Elev 580' A5001	ELEV 580		Partridge
OPR	Mark Dick 705-257-8587 Reg PPR			
PF	C-1,2,3,4,5,6,7	2400		, , , , , ,
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)		dock, Le	ewis Q oint t t Q
A/D DATA DOCKS	Open water May-Nov. Ltd moorings (no long-term parking), beach, ramp	Ť.	Masia Bay Brassar F Pt	Q E
COMM	tfc 122.7 2NM 3600 ASL		2 3 4	5 6000'
CAUTION	Heavy boat tfc in St. Mary's River. Heav	vy tfc vic Sault	Michigan aprt.	

CANADA FLIGHT SUPPLEMENT / GPH 205 Effective 0901Z 30 November 2023 to 0901Z 25 January 2024

ONTARIO

AERODROME/FACILITY DIRECTORY

SAULT STE. MARIE ON (Heli)

SAULT STE.	MARIE ON (Heli)	CNR3
REF	N46 30 16 W84 19 24 Adj S 7°W UTC-5(4) Elev 580′ A5001	Image: state I
OPR	Canadian Bushplane Heritage Centre 705-945-6242 Reg	
PF	B1 avbl 13-22Z‡ C-2,3,4,5,6	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
SERVICES FUEL	13-22Z‡ May-Oct, dawn til dusk Nov-Apr 100LL Humphrey Aviation Services 705-542-2590	ARR/DEP CANADA St Marys River
HELI DATA RCR	57´ dia concrete Opr	
	Floodlit Apron; Aiming point lighting, 6 re	ed lgts.
COMM	tfc 122.7 2NM 3000 ASL	WILCO
PRO	Arr/dep btwn 131°-246° fr heli. Arr/dep hover area & aiming point lctd S of pad.	
CAUTION	Co-located water aerodrome, docks just W of helipads. Hi lvl of tfc in vic Sault, Michigan aprt, also on 122.7	















SAULT STE. MARIE ON

REF	N46 30 16 W84 19 24 Adj S 7°W UTC-5(4) Elev 580′ A5001	····· ································
OPR	Cdn Bushplane Heritage Centre 705-945-6242 Reg	
PF	B1 avbl 13-22Z‡ C-2,3,4,5,6	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
SERVICES FUEL	12-23Z May-Oct 100LL PN Humphrey Aviation Service 705-542-2590 1,2,3,4,5	CANADA U.S.A. St Marys River
A/D DATA	Open water May-Nov. Current 5 kt, ramp, slipway	
LIGHTING	Floodlit 24 hrs.	RPAS
COMM ATF	tfc 122.7 2NM 3000 ASL	WILCO
PRO	See Sault Ste. Marie VTPC.	
CAUTION	Co-lctd heliport, helipads aprx 200' E of aprt, also on 122.7. Ramp usage is depe	docks. High IvI of tfc in vic Sault, Michigan endent on IvI of St. Mary's River. Ctc opr.

CPX8

CPP9

SAULT STE. MARIE FSS-RCO

London 119.4 (RAAS) 0345-1120Z‡ (N43 01 W81 09)

SAULT STE. MARIE / PARTRIDGE POINT ON

ON OFFICIE				0110
REF	N46 30 51 W84 14 54 Adj E 7°W (2023) UTC-5(4) Elev 580' A5001	ELEV 580		Partridge
OPR	Mark Dick 705-257-8587 Reg PPR			
PF	C-1,2,3,4,5,6,7	2400		, , , , , ,
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)		dock, Le	ewis Q oint t t Q
A/D DATA DOCKS	Open water May-Nov. Ltd moorings (no long-term parking), beach, ramp	Ť.	Masia Bay Brassar F Pt	Q E
COMM	tfc 122.7 2NM 3600 ASL		2 3 4	5 6000'
CAUTION	Heavy boat tfc in St. Mary's River. Heav	vy tfc vic Sault	Michigan aprt.	

AERODROME/FACILITY DIRECTORY B217

CJP3

SAVANT LAKE (STURGEON LAKE) ON

REF	N50 12 W90 41 3.5SE 2°W UTC-6(5) Elev 1342' A5008	$\begin{bmatrix} t & \varphi & \varphi & \varphi & \text{ELEV 1342} \\ t & t & t \\ t & t \\$
OPR	Rusty Myers Flying Svc Ltd 807-788-5224 May-Oct or 866-707-7637 Reg	$\begin{array}{c} t\\ t\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ $
PF	B-1 PPAS	£ 3200
FLT PLN FIC	Pilots to open/close VFR flt plan with London rdo, FISE or by phone London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	$\begin{array}{c} Q \\ t \\ Q \\ t \\ Q \\ t \\ t \\ t \\ t \\ t \\$
SERVICES FUEL OIL S	100LL (D), JA-1 All 5	$\begin{array}{c} t \\ \hline \\$
A/D DATA	Open water mid May-Oct. Sand bottom, dock & beach.	RPAS
COMM	tfc 122.8 5NM 4400 ASL	WILCO
CAUTION	Twr 1700 ASL 2.5NM NE. Small boat the	. Reef SE.

SAWDUST BAY ON - See NOBEL / SAWDUST BAY







ONTARIO

AERODROME/FACILITY DIRECTORY

CSM9

SAULT STE. MARIE (SAULT AREA HOSP) ON (Heli)





REF	N46 32 51 W84 18 45 5N 7°W UTC-5(4) Elev 797' A5001	
OPR	Sault Area Hospital 705-759-3434 Ext 4412 Cert PPR	
PF	A-1 C-2,3,4,5,6	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)	
HELI DATA RCR	86' dia concrete 115' dia safety area Max heli overall length 57.4' Opr	
LIGHTING	RY(LO)	
COMM ATF	tfc 122.7 2NM 3000 ASL	
PRO	Arr/dep btwn 115°-120° & 340°-345° fr heli, slope 16% (H2), day/night use.	
CAUTION	Twr 224 AGL aprx 0.2NM W and twr 230 AGL aprx 0.7NM NW of heli.	









WILCO







CANADA FLIGHT SUPPLEMENT / GPH 205 Effective 0901Z 30 November 2023 to 0901Z 25 January 2024

ONTARIO

AERODROME/FACILITY DIRECTORY

SAULT STE. MARIE ON

SAULT STE.	MARIE ON	CYAN
REF	N46 29 06 W84 30 34 8WSW 7°W (2012) UTC-5(4) Elev 632′ A5001 LO4 HI4 HI5 CAP	310" 5NM TO 3000 ELEV 632
OPR	Sault Ste. Marie Airport Development Corporation 705-779-3031 1045-0345Z ⁺ Cert Ldg fees	
PF	B-1,2,3,6,7 D-4,5	F 9 760
CUST	AOE/30 888-226-7277	6000, FIN TWR
FLT PLN FIC WX	Pilots to open/ close VFR flt plan with London rdo 123.475 or by phone. London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) METAR H24. TAF H24, issue times: 02, 08, 14 & 20Z.	
SERVICES FUEL OIL S SUP FL JASU PVT ADV	1100-0001Z‡ O/T call out chg 249-889- JD Aero (Avjet Fuels) 128.875 10-22Z‡ 705-779-3977 Ext 213/215 or 705-541-8) 122.45 Mon-Fri 11-01Z‡, Sat-Sun 1244 705-779-3977 Ext 200 O/T call out chg apply 153 (FBO mgr)
RWY DATA RWY CERT RCR	Rwy 04(040°)/22(220°) 6000x148 ASPH Rwy 12(115°)/30(295°) 6000x200 ASPH Rwy 04/22 AGN IV Rwy 12 RVR 1200(1/4sm)/Rwy 30 RVR Opr Win maint CRFI/RSC 1030-0230Z: PLR/PCN	0000
LIGHTING	04-AO(TE ME) P2, 22-AO(TE ME) P2 ARCAL-118.8 type K when twr clsd.	2, 12-AN(TE HI), 30-AO(TE HI) P1
COMM RCO ATIS GND TWR MF		g only 705-779-3707)

PAL	applicable over Cdn territory Toronto Ctr 132.65 344.5		
NAV VOR/DME ILS			
PRO	Heli arr/dep E as indicated on VTPC. Heli arr/dep N & S at Twr discretion. Hi lvl of tfc in the vic Sault, Michigan aprt, also on 122.7. Twy G run-ups: only south of the svc road intxn and facing west.		
CAUTION	Dur win months btwn 0330-1130Z (when ATC clsd), aprt maint & snow removal vehicles may be oprg on the rwy surface. Ctc all gnd vehicles on MF when ATC clsd.		