

# Created using **RPAS Wilco**®

Operation Name:

Pilot Name:

Pilot Certificate:

Flight Start:

Flight End:

Flight Area (Latitude):

Flight Area (Longitude):

Altitude - Radius:

Airspace:

FIR - Contact:

Mission 01-25-2024

Ulf Bergquist

PC2305919413

January 25, 2024 9:50 AM

January 25, 2024 11:50 AM

43° 10' 52.00" N ( 43.181 )

80° 41' 47.00" W ( -80.696 )

Alt: 400 ft - Rad: 100 m ( 0.05 nm )

UNCONTROLLED

CZYZ - 905-676-4509

Please ensure you received all required authorizations prior to flight.

## Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

# Included

Site Survey

Obstacles (if available)

Nearby Aerodromes

Canadian Aviation Regulations

GFA

Aerodrome Supplements


-METAR & TAF (if available)

-NOTAMs

-CFS



# Flight Map




# MAP Details

		Latitude	Longitude
×	MODEL	43° 10' 52.00" N ( 43.181 )	80° 41' 47.00" W ( -80.696 )
•	<b>Pilot</b> Ulf Bergquist	43° 10' 55.60" N ( 43.1821 )	80° 41' 50.60" W ( -80.6974 )



# Airspace Classification



# Overlying Airspaces

Class	Name	Floor	Ceiling
В	T614 Airway	12500MSL	18000MSL
E	T614 Airway	2200AGL	12500MSL
В	T781 Airway	12500MSL	18000MSL
E	T781 Airway	2200AGL	12500MSL
E	T608 Airway	2200AGL	12500MSL
В	T608 Airway	12500MSL	18000MSL
В	Southern Ontario Low Level Control Area CAE	12500MSL	18000MSL
E	Southern Ontario Low Level Control Area CAE	6500MSL	12500MSL
E	Toronto XPNDR MANDTRY	6500MSL	12500MSL
E	Southern Ontario Low Level Control Area CAE	2500MSL	6500MSL

# Nearest Aerodromes & Distance from Operation

INNERKIP (CNR2 - AERODROME - Reg)	Lat: 43.233	Long: -80.694	5.773 KM	3.12 NM
WOODSTOCK (NORM BECKHAM / BOB HEWITT FIELD) (CPR5 - AERODROME - Reg)	Lat: 43.11	Long: -80.821	12.835 KM	6.93 NM
CURRIES (RAND PRIVATE AIRFIELD) (CRE3 - AERODROME - Reg)	Lat: 43.065	Long: -80.7	KM	6.97 NM
WOODSTOCK (HOSPITAL) (CWH3 - HELIPORT - Cert)	Lat: 43.105	Long: -80.754	9.668 KM	5.22 NM
PLATTSVILLE (EDWARD'S AIR BASE) (CLB2 - AERODROME - Reg)	Lat: 43.306	Long: -80.548	18.366 KM	9.92 NM

# Canadian Aviation Regulations

## Division III — General Operating and Flight Rules

For full listing please visit: https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

### Visual Line-of-sight

- 901.11 (1) Subject to subsection (2), no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

### Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
  - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
  - O (b) emergency procedures, including with respect to
    - (i) a control station failure,
    - (ii) an equipment failure.
    - (iii) a failure of the remotely piloted aircraft,
    - (iv) a loss of the command and control link,
    - (v) a fly-away, and
    - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

## Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation.

## Operations at or in the Vicinity of an Aerodrome, Airport or Heliport


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
- Subject to section 901.73, no pilot shall operate a remotely piloted aircraft at a distance of less than
  - O (a) three nautical miles from the centre of an airport; and
  - O (b) one nautical mile from the centre of a heliport.
- (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

## Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
  - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights; and
  - O (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
    - (i) the names of the persons who performed them.
    - (ii) the dates they were undertaken,
    - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
    - (iv) if applicable, any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
  - (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
  - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).



GFA Issue time + 00 hr - CLOUDS AND WEATHER




GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 06 hr - CLOUDS AND WEATHER




GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






# GFA Issue time + 12 hr - CLOUDS AND WEATHER



# GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





# INNERKIP - CNR2 - Req

## NOTAM

### (G2907/23 NOTAMN

- (02:997/25 NOTARIN )
  (0) CZXX/QPZITT/IV/B0/E/000/999/5245N09040W999
  A) CZMG CZYZ B) 2312202142 C) 2412191600EST
  E) TRIGGER NOTAM AIP SUPPLEMENT 26/18 IN EFFECT. ADJUSTMENT TO THE CANADA AIR DEFENCE IDENTIFICATION ZONE (ADIZ).)

- (G0044/24 NOTAMR G2577/23 Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
- Q) CZAZ (QUEAT, VN MD/Z-V0009 3997-52430N99940999

  A) CZYZ CZWG B) 240109181840 C) 24040817090EST

  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT

  IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR

  OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO

  TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

### (G0014/24 NOTAMR G2479/23

- (G0014/24 NOTAMR G2479/23

  Q) CZXX/QDGCH/TV/NBO/E/000/999/5518N09358W999

  A) CZWG CZYZ B) 2401041403 C) 2404041800EST

  E) ALL ACFT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR
  INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE
  CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN
  FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS
  INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION
  OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATOR CERTIFICATE
  ACCOL TSSIED BY MISSIAN FEDERATION AND RELABUSTAN ALTHORYTISS OR BELANDS, AND ALL OPERATORS HOLDING AN AIR OPERATIOR CENTIFICATI (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12MM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CAMADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

## (G0043/24 NOTAMR G2482/23

- Q) CZXX/Q0EXX/IV/NB0/E/000/999/5245N09040W999
- A) CZYZ CZWG B) 2401081837 C) 2404081700EST
  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF
- E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV
- (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

## (G2888/23 NOTAMN

- Q) CZYZ/QAFTT/IV/B0/E/000/999/4729N08055W999
- A) CZYZ B) 2312201514 C) 2403212359
  E) TRIGGER NOTAM AIP SUPPLEMENT 77/23 WEF 14 DEC 2023 UNTIL 21 MAR 2024 ADS-B IN FAA AIRSPACE AMENDMENT TO THE CANADIAN DESIGNATED AIRSPACE HANDBOOK)

## (G2891/23 NOTAMN

- (02.6937/23 NOTAMN )
  Q) CZYZ/QAFTT/IV/BO/E/000/999/4729N08055W999
  A) CZYZ B) 2312201529 C) 2412191600EST
  E) TRIGGER NOTAM AIP SUPPLEMENT 76/23 IN EFFECT AUTOLAND PROCEDURES NOT RECOMMENDED IN RUNWAYS NOT COVERED BY ISED'S DESIGNATED 5G EXCLUSION AND PROTECTION ZONES)



# WOODSTOCK (NORM BECKHAM / BOB HEWITT FIELD) - CPR5 - Reg

# NOTAM

### (G2907/23 NOTAMN

- Q) CZXX/QPZTT/IV/B0/E/000/999/5245N09040W999 A) CZWG CZYZ B) 2312202142 C) 2412191600EST
- E) TRIGGER NOTAM AIP SUPPLEMENT 26/18 IN EFFECT. ADJUSTMENT TO THE CANADA AIR DEFENCE IDENTIFICATION ZONE (ADIZ).)

- (G0044/24 NOTAMR G2577/23 Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
- Q) CZAZ (QUEAT, VN MD/Z-V0009 3997-52430N99940999

  A) CZYZ CZWG B) 240109181840 C) 24040817090EST

  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT

  IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR

  OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO

  TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

### (G0014/24 NOTAMR G2479/23

- (G0014/24 NOTAMR G2479/23

  Q) CZXX/QDGCH/TV/NBO/E/000/999/5518N09358W999

  A) CZWG CZYZ B) 2401041403 C) 2404041800EST

  E) ALL ACFT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR
  INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE
  CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN
  FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS
  INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION
  OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATOR CERTIFICATE
  ACCOL TSSIED BY MISSIAN FEDERATION AND RELABUSTAN ALTHORYTISS OR BELANDS, AND ALL OPERATORS HOLDING AN AIR OPERATIOR CENTIFICATI (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12MM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CAMADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

## (G0043/24 NOTAMR G2482/23

- Q) CZXX/Q0EXX/IV/NB0/E/000/999/5245N09040W999
- A) CZYZ CZWG B) 2401081837 C) 2404081700EST
  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF
- E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV
- (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

## (G2888/23 NOTAMN

- Q) CZYZ/QAFTT/IV/B0/E/000/999/4729N08055W999
- A) CZYZ B) 2312201514 C) 2403212359
  E) TRIGGER NOTAM AIP SUPPLEMENT 77/23 WEF 14 DEC 2023 UNTIL 21 MAR 2024 ADS-B IN FAA AIRSPACE AMENDMENT TO THE CANADIAN DESIGNATED AIRSPACE HANDBOOK)

## (G2891/23 NOTAMN

- (02.6937/23 NOTAMN )
  Q) CZYZ/QAFTT/IV/BO/E/000/999/4729N08055W999
  A) CZYZ B) 2312201529 C) 2412191600EST
  E) TRIGGER NOTAM AIP SUPPLEMENT 76/23 IN EFFECT AUTOLAND PROCEDURES NOT RECOMMENDED IN RUNWAYS NOT COVERED BY ISED'S DESIGNATED 5G EXCLUSION AND PROTECTION ZONES)



CURRIES (RAND PRIVATE AIRFIELD) - CRE3 - Reg



# WOODSTOCK (HOSPITAL) - CWH3 - Cert

# **NOTAM**

### (G2907/23 NOTAMN

- Q) CZXX/QPZTT/IV/B0/E/000/999/5245N09040W999 A) CZWG CZYZ B) 2312202142 C) 2412191600EST
- E) TRIGGER NOTAM AIP SUPPLEMENT 26/18 IN EFFECT. ADJUSTMENT TO THE CANADA AIR DEFENCE IDENTIFICATION ZONE (ADIZ).)

- (G0044/24 NOTAMR G2577/23 Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
- Q) CZAZ (QUEAT, VN MD/Z-V0009 3997-52430N99940999

  A) CZYZ CZWG B) 240109181840 C) 24040817090EST

  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT

  IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR

  OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO

  TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

### (G0014/24 NOTAMR G2479/23

- (G0014/24 NOTAMR G2479/23

  Q) CZXX/QDGCH/TV/NBO/E/000/999/5518N09358W999

  A) CZWG CZYZ B) 2401041403 C) 2404041800EST

  E) ALL ACFT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR
  INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE
  CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN
  FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS
  INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION
  OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATOR CERTIFICATE
  ACCOL TSSIED BY MISSIAN FEDERATION AND RELABUSTAN ALTHORYTISS OR BELANDS, AND ALL OPERATORS HOLDING AN AIR OPERATIOR CENTIFICATI (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12MM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CAMADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

## (G0043/24 NOTAMR G2482/23

- Q) CZXX/Q0EXX/IV/NB0/E/000/999/5245N09040W999
- A) CZYZ CZWG B) 2401081837 C) 2404081700EST
  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF
- E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV
- (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

## (G2888/23 NOTAMN

- Q) CZYZ/QAFTT/IV/B0/E/000/999/4729N08055W999
- A) CZYZ B) 2312201514 C) 2403212359
  E) TRIGGER NOTAM AIP SUPPLEMENT 77/23 WEF 14 DEC 2023 UNTIL 21 MAR 2024 ADS-B IN FAA AIRSPACE AMENDMENT TO THE CANADIAN DESIGNATED AIRSPACE HANDBOOK)

## (G2891/23 NOTAMN

- (02.6937/23 NOTAMN )
  Q) CZYZ/QAFTT/IV/BO/E/000/999/4729N08055W999
  A) CZYZ B) 2312201529 C) 2412191600EST
  E) TRIGGER NOTAM AIP SUPPLEMENT 76/23 IN EFFECT AUTOLAND PROCEDURES NOT RECOMMENDED IN RUNWAYS NOT COVERED BY ISED'S DESIGNATED 5G EXCLUSION AND PROTECTION ZONES)



# PLATTSVILLE (EDWARD'S AIR BASE) - CLB2 - Reg

# **NOTAM**

### (G2891/23 NOTAMN

- (02.6937/23 NOTAMN )
  Q) CZYZ/QAFTT/IV/BO/E/000/999/4729N08055W999
  A) CZYZ B) 2312201529 C) 2412191600EST
  E) TRIGGER NOTAM AIP SUPPLEMENT 76/23 IN EFFECT AUTOLAND PROCEDURES NOT RECOMMENDED IN RUNWAYS NOT COVERED BY ISED'S DESIGNATED 5G EXCLUSION AND PROTECTION ZONES)

- Q) CZXX/QPZTT/TV/B0/E/000/999/5245N09040W999 A) CZWG CZYZ B) 2312202142 C) 2412191600EST E) TRIGGER NOTAM AIP SUPPLEMENT 26/18 IN EFFECT. ADJUSTMENT TO THE CANADA AIR DEFENCE IDENTIFICATION ZONE (ADIZ).)

### (G0044/24 NOTAMR G2577/23

- Q) CZXX/Q0EXX/IV/NB0/E/000/999/5245N09040W999
- A) CZYZ CZWG B) 240109481840 C) 2404081700EST
  E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN LEBANON. CANADIAN AIR OPERATORS AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPERATING IN LEBANESE AIRSPACE AND FIR BEIRUT (OLBB) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

### (G0014/24 NOTAMR G2479/23

- 0) CZXX/00ECH/IV/NB0/E/000/999/5518N09358W999
- A) CZWG CZYZ B) 2401041403 C) 2404041800EST E) ALL ACFT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG.

ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CANADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.)

# (G0043/24 NOTAMR G2482/23

- 0) CZXX/00EXX/IV/NB0/E/000/999/5245N09040W999
- A) CZYZ CZWG B) 2401081837 C) 2404081700EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF
- E) ALROPACE SECURITY WARKING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN ISRAEL. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE ADVISED TO TAKE ALL POTENTIAL RISK INFO INTO ACCOUNT IN THEIR RISK ASSESSMENT AND ROUTING DECISIONS WHEN OPR IN ISRAELI AIRSPACE AND FIR TEL-AVIV (LLLL) DUE TO POTENTIAL RISK TO AVIATION FROM MIL ACT.)

## (G2888/23 NOTAMN

- (02-6967-28 NUT-NIN)
  Q) CZYZ/QAFTT/IV/B0/E/000/999/4729N08055W999
  A) CZYZ B) 2312201514 C) 2403212359
  E) TRIGGER NOTAM AIP SUPPLEMENT 77/23 WEF 14 DEC 2023 UNTIL 21 MAR 2024 ADS-B IN FAA AIRSPACE AMENDMENT TO THE CANADIAN DESIGNATED AIRSPACE HANDBOOK)

tfc 123.2 5NM 4000 ASL

P-line 60 AGL E Thld 27. Trees 50 AGL W Thld 09.

INNERKIP ON		CNR2		
REF	N43 13 57 W80 41 41 1.4N 9°W (2015) UTC-5(4) Elev 1010' VTA A5000	ELEV 1010		
OPR	Larry Ernewein 519-469-3874 Reg PPR	£ 2 2 2		
PF	B-1 C-2,3 D-4,5,6	9 1844' A		
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	ANDIUS 5 1/2 Q		
RWY DATA  RCR	Rwy 09(088°)/27(268°) 1844x80 GRASS Opr No win maint. Rwy soft when wet.	2600		
СОММ				



**ATF** 

**CAUTION** 

















# WOODSTOCK (NORM BECKHAM / BOB HEWITT FIELD) ON

# CPR5

110000100	IX (NOKIII DECKITAIII / DOD HEWITT THEE		CFKJ
REF	N43 06 35 W80 49 15 2.5W 9°W UTC-5(4) Elev 1040′ A5000	QADIUS 5 NA É Q É E	ELEV 1040
OPR	Dave Hewitt 519-421-1755 or 519-539-3303 Reg Aprt not regularly attended PN	3200 C	2
PF	B-1 C-2,3,4,5,6	60,	8 /
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)		
SERVICES FUEL S	100LL (emergency use only) 5,6	2 2 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1	//:: <sup>2</sup>
RWY DATA	Rwy 06/24 3100x100 GRASS/GRVL 20' gravel (screenings) centre on eastern ha Opr No win maint, rwy soft in spring.	alf of rwy and twy	
LIGHTING	06-(TE LO), 24-(TE LO) ARCAL-122.9 type J PN Opr		
СОММ			
ATF	UNICOM ltd hrs O/T tfc 122.8 5NM 4000 ASL		
CAUTION	Wildlife in vic of rwy.		



















CURRIES (RAND PRIVATE AIRFIELD) O	N
-----------------------------------	---

CURNIES (K)	AND PRIVATE AIRFIELD) ON	CRES
REF	N43 03 54 W80 42 00 Adj ESE 9°W UTC-5(4) Elev 1060' VTA A5000	ELEV 1060
OPR	George Rand 519-424-2175 519-617-3707 Reg PPR	
PF	B-1 C-2,3	80.
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	ADIUS 5 N
RWY DATA	Rwy 11(112°)/29(292°) 1799x60 GRASS Opr No win maint. Rwy may be soft in early spring and late fall.	3200
PRO	Rwy conditions must be confirmed with opr prior to use.	
CAUTION		1572 ASL (480 AGL) aprx 1NM N of A/D, to f A/D, to 1572 ASL (480 AGL) aprx 0.6NM to



















# WOODSTOCK (HOSPITAL) ON (Heli) CWH3 **ELEV 1046** N43 06 20 W80 45 16 Adj S **REF** 9°W (2012) UTC-5(4) Elev 1046' VTA A5000 OPR Honeywell/Woodstock Hospital 519-421-4211 Ext 5011 Cert PPR A-1,2,3,4 C-5,6 PF FLT PLN FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free ARR/DEP 190° within Canada & USA) FATO 92' dia CONC **HELI DATA** TLOF 39' dia CONC Athlone Ave Safety Area 118' dia Max heli overall length 57.5' (CAR 602.96) RCR Opr DR RY(LO) green RF(FH) ARCAL-123.2 type K LIGHTING COMM **ATF** tfc 123.2 5NM 4000 ASL **PRO** Arr/dep 190° fr heli, slope 12% (H2), day/night use



CAUTION



Multiple lgtd and unlgtd twrs W of heli. Woodstock UNICOM 122.8 3NM W.















CAUTION

ThId 25.

# PLATTSVILLE (EDWARD'S AIR BASE) ON CLB<sub>2</sub> **ELEV 980** N43 18 21 W80 32 55 3E 10°W **REF** UTC-5(4) Elev 980' VTA A5000 Edward Lubitz 519-684-7686 Reg OPR B-1 C-2,4,5 PF FLT PLN FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free ARDIUS 5 NA within Canada & USA) Rwy 07(066°)/25(246°) 1980x75 **RWY DATA GRASS** 3300 RCR Opr No win maint Ç COMM Q ATF tfc 123.2 5NM 4000 ASL Std circuit hgt 2000 ASL. Ultralight circuit hgt 1500 ASL. PRO

Gnd drops off 20' at Thld 25. Trees 25 AGL 75' SE of Thld 25. Trees 25 AGL 225' NW

















