

## Created using **RPAS Wilco**®

Reference No: Title: Pilot Name: Pilot Certificate: Flight Start: Flight End: Flight Area (Latitude): Flight Area (Longitude): Altitude - Radius: Classification: FIR - Contact:

A5BAAB Mission 01-28-2025 Ulf Bergguist PC2305919413 January 28, 2025 2:25 PM January 28, 2025 3:25 PM 43° 10′ 53.30″ N ( 43.181 ) 80° 41′ 48.03″ W ( -80.697 )

**Alt:** 400 ft - **Rad:** 370.4 m (0.2 nm)

UNCONTROLLED CZYZ - 905-676-4509

Please ensure you received all required authorizations prior to flight.

### Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

## Included

Site Survey

Obstacles (if available)

**Nearby Aerodromes** 

Canadian Aviation Regulations

Aerodrome Supplements

-METAR & TAF (if available)

-NOTAMs

-CFS



## Flight Map



## **RPAS Specification**

- Manufacturer: MAAC
- Model: MODEL AIRPLANE
- Registration Number: C-2305908471
- Eligible for advanced operations: No
- Manufacturer RPAS safety assurance:
  - Controlled Airspace: N/A
  - Near People: N/A
  - o Over People: N/A

### **MAP Details**


		Latitude	Longitude
×	MODEL	43° 10' 53.30" N ( 43.181 )	80° 41' 48.03" W ( -80.697 )
•	<b>Pilot</b> Ulf Bergquist	43° 10' 56.90" N ( 43.1825 )	80° 41' 51.63" W ( -80.6977 )



Canada's #1 FREE Drone Training Hub



Airspace Classification



## **Overlying Airspaces**

Class	Name	Floor	Ceiling
E	T614 Airway	2200AGL	12500MSL
В	T614 Airway	12500MSL	18000MSL
E	T781 Airway	2200AGL	12500MSL
В	T781 Airway	12500MSL	18000MSL
E	T608 Airway	2200AGL	12500MSL
В	T608 Airway	12500MSL	18000MSL
В	Southern Ontario Low Level Control Area CAE	12500MSL	18000MSL
E	Southern Ontario Low Level Control Area CAE	6500MSL	12500MSL
E	Toronto XPNDR MANDTRY	6500MSL	12500MSL
E	Southern Ontario Low Level Control Area CAE	2500MSL	6500MSL

## Nearest Aerodromes & Distance from Operation

INNERKIP (CNR2 - AERODROME - Reg)	Lat: 43.233	Long: -80.694	5.734KM	3.1NM	N
WOODSTOCK (NORM BECKHAM / BOB HEWITT FIELD) (CPR5 - AERODROME - Reg)	Lat: 43.11	Long: -80.821	12.841KM	6.93NM	SW
WOODSTOCK (HOSPITAL) (CWH3 - HELIPORT - Cert)	Lat: 43.105	Long: -80.754	9.692KM	5.23NM	SW
PLATTSVILLE (EDWARD'S AIR BASE) (CLB2 - AERODROME - Reg)	Lat: 43.306	Long: -80.548	18.351KM	9.91NM	NE
SARGEANT PRIVATE AIRFIELD ON (CAY5 - AERODROME - Reg)	Lat: 43.306	Long: -80.499	21.168KM	11.43NM	l NE

INNERKIP ON	CNR2
-------------	------

IIIII O	TY CONTRACTOR OF THE CONTRACTO	ONITE
REF	N43 13 57 W80 41 41 1.4N 9°W (2015) UTC-5(4) Elev 1010' VTA A5000	ELEV 1010
OPR	Larry Ernewein 519-469-3874 Reg PPR	£ 2 2 2
PF	B-1 C-2,3 D-4,5,6	8 1844' A
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	ANDIUS 5 NA Q
RWY DATA  RCR	Rwy 09(088°)/27(268°) 1844x80 GRASS Opr No win maint. Rwy soft when wet.	2600
COMM	tfc 123.2 5NM 4000 ASL	
CAUTION	P-line 60 AGL E Thld 27. Trees 50 AGL	W Thid 09.



















## WOODSTOCK (NORM BECKHAM / BOB HEWITT FIELD) ON

## CPR5

MOODOTOO	IX (NOKIII DECKITAIII / DOD HEMITT FILL	D) ON	CFRS
REF	N43 06 35 W80 49 15 2.5W 9°W UTC-5(4) Elev 1040′ A5000	QQDIUS SVA & Q & E	LEV 1040
OPR	Dave Hewitt 519-421-1755 or 519-539-3303 Reg Aprt not regularly attended PN	3200 C	2
PF	B-1 C-2,3,4,5,6	60'	8
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)		
SERVICES FUEL S	100LL (emergency use only) 5,6	2 2 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	/:: ¿
RWY DATA	Rwy 06/24 3100x100 GRASS/GRVL 20' gravel (screenings) centre on eastern ha Opr No win maint, rwy soft in spring.	lf of rwy and twy	
LIGHTING	06-(TE LO), 24-(TE LO) ARCAL-122.9 type J PN Opr		
СОММ			
ATF	UNICOM ltd hrs O/T tfc 122.8 5NM 4000 ASL		
CAUTION	Wildlife in vic of rwy.		



















### WOODSTOCK (HOSPITAL) ON (Heli) CWH3 **ELEV 1046** N43 06 20 W80 45 16 Adj S REF 9°W (2012) UTC-5(4) Elev 1046' VTA A5000 OPR Honeywell/Woodstock Hospital 519-421-4211 Ext 5011 Cert PPR PF A-1,2,3,4 C-5,6 FLT PLN FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free ARR/DEP 190° within Canada & USA) **HELI DATA** FATO 92' dia CONC TLOF 39' dia CONC Athlone Ave Safety Area 118' dia Max heli overall length 57.5' (CAR 602.96) RCR Opr DR RY(LO) green RF(FH) ARCAL-123.2 type K LIGHTING COMM **ATF** tfc 123.2 5NM 4000 ASL



**PRO** 

CAUTION



Multiple lgtd and unlgtd twrs W of heli. Woodstock UNICOM 122.8 3NM W.

Arr/dep 190° fr heli, slope 12% (H2), day/night use















# PLATTSVILLE (EDWARD'S AIR BASE) ON

$\sim$			^
		_	•
 _	_	ட	

LATIOVILL	L (LDWARD 5 AIR BASE) OR	CLBZ
REF	N43 18 21 W80 32 55 3E 10°W UTC-5(4) Elev 980' VTA A5000	ELEV 980
OPR	Edward Lubitz 519-684-7686 Reg	5 5 5 5
PF	B-1 C-2,4,5	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	RADIUS 5 14 C & Mith River &
RWY DATA  RCR	Rwy 07(066°)/25(246°) 1980x75 GRASS Opr No win maint	3300
COMM	tfc 123.2 5NM 4000 ASL	Q Q
PRO	Std circuit hgt 2000 ASL. Ultralight circu	it hgt 1500 ASL.
CAUTION	Gnd drops off 20' at Thld 25. Trees 25 A0 Thld 25.	GL 75' SE of Thld 25. Trees 25 AGL 225' NW



















## **AYR / SARGEANT PRIVATE AIRFIELD ON**

	Α	v	,	c
<u>ں</u>	н	ч		J

		57116
REF	N43 18 21 W80 29 57 2.6NW 10°W UTC-5(4) Elev 970' VTA A5000	ELEV 970
OPR	Gavin Sargeant 519-748-5418/7480 Reg PPR	S Nith Hot S
PF	B-1 C-2,3 D-4,5,6	5 6 6
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	ADIUS STATE OF THE RADIUS STATE OF THE PROPERTY OF THE PROPERT
RWY DATA  RCR	Rwy 18(180°)/36(360°) 3047x90 GRASS Thld 36 displ 324' Rwy 18 down 3% Opr No win maint. Rwy may be soft early spring and late fall.	3300
COMM	tfc 123.2 5NM 4000 ASL	
PRO	Rwy conditions must be confirmed with opr prior to use.	
CAUTION	P-line, aprx 50 AGL, 335' N of thld of Rv	vy 18, marked. Trees on apch to Rwy 36.



















## Canadian Aviation Regulations

### Division III — General Operating and Flight Rules

For full listing please visit: https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

#### Visual Line-of-sight

- 901.11 (1) Subject to subsection (2), no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

#### Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
  - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
  - O (b) emergency procedures, including with respect to
    - (i) a control station failure,
    - (ii) an equipment failure.
    - (iii) a failure of the remotely piloted aircraft,
    - (iv) a loss of the command and control link,
    - (v) a fly-away, and
    - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

#### Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation.

### Operations at or in the Vicinity of an Aerodrome, Airport or Heliport


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
- Subject to section 901.73, no pilot shall operate a remotely piloted aircraft at a distance of less than
  - O (a) three nautical miles from the centre of an airport; and
  - O (b) one nautical mile from the centre of a heliport.
- (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

### Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
  - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights; and
  - O (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
    - (i) the names of the persons who performed them.
    - (ii) the dates they were undertaken,
    - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
    - (iv) if applicable, any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
  - (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
  - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).



### GFA Issue time + 00 hr - CLOUDS AND WEATHER




## GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL






### GFA Issue time + 06 hr - CLOUDS AND WEATHER




## GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






### GFA Issue time + 12 hr - CLOUDS AND WEATHER



## GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





## INNERKIP - CNR2 - Reg

### **NOTAM**

#### (G0165/25 NOTAMN

Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2501281124 C) 2501290300

E) DUE TO REDUCED SYSTEM CAPACITY AND ANTICIPATED TFC DEMANDS, VFR FLT FLW NOT AVBL VCY CYAM, CYLD, CYEL, CYEM, CYXZ, CYVV, CYOS, CYLS, CYKM, CYHS, CYEE, CNY3, CNV8, AND CNK4 ON FREQ 132.57MHZ, 124.02MHZ, 132.65MHZ, 135.4MHZ AND 124.07MHZ)

#### (G3517/24 NOTAMN

Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR FR NW RNAV WALPP IKLUX KIVUN UKROX)

### (G3450/24 NOTAMR G3244/24

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2412131853 C) 2502131600EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE PROHIBITED FM OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK TO AVIATION FROM GANG ACT. EXCEPTIONAL WAIVERS MAY BE GRANTED UPON MOTIVATED REQUEST TO THE COMPETENT AUTH. AFFECTED AIR OPR WISHING TO OBTAIN SUCH AN AUTH MUST APPLY TO THE DEPARTMENT OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(A)TC.GC.CA)

(G2993/24 NOTAMR G2907/23 Q) CZXX/OPZTT/IV/BO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2410161344 C) 2504171600



## WOODSTOCK (NORM BECKHAM / BOB HEWITT FIELD) - CPR5 - Reg **NOTAM**

#### (G0165/25 NOTAMN

Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2501281124 C) 2501290300 E) DUE TO REDUCED SYSTEM CAPACITY AND ANTICIPATED TFC DEMANDS, VFR FLT FLW NOT AVBL VCY CYAM, CYLD, CYEL, CYEM, CYXZ, CYVV, CYOS, CYLS, CYKM, CYHS, CYEE, CNY3, CNV8, AND CNK4

ON FREQ 132.57MHZ, 124.02MHZ, 132.65MHZ, 135.4MHZ AND 124.07MHZ)

#### (G3517/24 NOTAMN

Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2412260901 C) PERM E) AMEND PUBLICATIONS: AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR

### (G3450/24 NOTAMR G3244/24

FR NW RNAV WALPP IKLUX KIVUN UKROX)

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZWG CZYZ B) 2412131853 C) 2502131600EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE PROHIBITED FM OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK TO AVIATION FROM GANG ACT. EXCEPTIONAL WAIVERS MAY BE GRANTED UPON MOTIVATED REQUEST TO THE COMPETENT AUTH. AFFECTED AIR OPR WISHING TO OBTAIN SUCH AN AUTH MUST APPLY TO THE DEPARTMENT OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(A)TC.GC.CA)

- (G2993/24 NOTAMR G2907/23 Q) CZXX/QPZTT/IV/BO/E/000/999/5245N09040W999
- A) CZWG CZYZ B) 2410161344 C) 2504171600
- E) TRIGGER NOTAM AIP SUPPLEMENT 26/18 IN EFFECT. ADJUSTMENT TO THE CANADA AIR DEFENCE IDENTIFICATION ZONE (ADIZ).)



## WOODSTOCK (HOSPITAL) - CWH3 - Cert

### **NOTAM**

#### (G0165/25 NOTAMN

Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2501281124 C) 2501290300

E) DUE TO REDUCED SYSTEM CAPACITY AND ANTICIPATED TFC DEMANDS, VFR FLT FLW NOT AVBL VCY CYAM, CYLD, CYEL, CYEM, CYXZ, CYVV, CYOS, CYLS, CYKM, CYHS, CYEE, CNY3, CNV8, AND CNK4 ON FREQ 132.57MHZ, 124.02MHZ, 132.65MHZ, 135.4MHZ AND 124.07MHZ)

#### (G3517/24 NOTAMN

Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR FR NW RNAV WALPP IKLUX KIVUN UKROX)

### (G3450/24 NOTAMR G3244/24

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2412131853 C) 2502131600EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE PROHIBITED FM OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK TO AVIATION FROM GANG ACT. EXCEPTIONAL WAIVERS MAY BE GRANTED UPON MOTIVATED REQUEST TO THE COMPETENT AUTH. AFFECTED AIR OPR WISHING TO OBTAIN SUCH AN AUTH MUST APPLY TO THE DEPARTMENT OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(A)TC.GC.CA)

(G2993/24 NOTAMR G2907/23 Q) CZXX/OPZTT/IV/BO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2410161344 C) 2504171600



## PLATTSVILLE (EDWARD'S AIR BASE) - CLB2 - Reg

### **NOTAM**

#### (G0165/25 NOTAMN

Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2501281124 C) 2501290300

E) DUE TO REDUCED SYSTEM CAPACITY AND ANTICIPATED TFC DEMANDS, VFR FLT FLW NOT AVBL VCY CYAM, CYLD, CYEL, CYEM, CYXZ, CYVV, CYOS, CYLS, CYKM, CYHS, CYEE, CNY3, CNV8, AND CNK4 ON FREQ 132.57MHZ, 124.02MHZ, 132.65MHZ, 135.4MHZ AND 124.07MHZ)

#### (G3517/24 NOTAMN

Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR FR NW RNAV WALPP IKLUX KIVUN UKROX)

### (G3450/24 NOTAMR G3244/24

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2412131853 C) 2502131600EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE PROHIBITED FM OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK TO AVIATION FROM GANG ACT. EXCEPTIONAL WAIVERS MAY BE GRANTED UPON MOTIVATED REQUEST TO THE COMPETENT AUTH. AFFECTED AIR OPR WISHING TO OBTAIN SUCH AN AUTH MUST APPLY TO THE DEPARTMENT OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(A)TC.GC.CA)

(G2993/24 NOTAMR G2907/23 Q) CZXX/OPZTT/IV/BO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2410161344 C) 2504171600



## SARGEANT PRIVATE AIRFIELD ON - CAY5 - Reg

### **NOTAM**

#### (G0165/25 NOTAMN

Q) CZYZ/QXXXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2501281124 C) 2501290300

E) DUE TO REDUCED SYSTEM CAPACITY AND ANTICIPATED TFC DEMANDS, VFR FLT FLW NOT AVBL VCY CYAM, CYLD, CYEL, CYEM, CYXZ, CYVV, CYOS, CYLS, CYKM, CYHS, CYEE, CNY3, CNV8, AND CNK4 ON FREQ 132.57MHZ, 124.02MHZ, 132.65MHZ, 135.4MHZ AND 124.07MHZ)

#### (G3517/24 NOTAMN

Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR FR NW RNAV WALPP IKLUX KIVUN UKROX)

### (G3450/24 NOTAMR G3244/24

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2412131853 C) 2502131600EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE PROHIBITED FM OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK TO AVIATION FROM GANG ACT. EXCEPTIONAL WAIVERS MAY BE GRANTED UPON MOTIVATED REQUEST TO THE COMPETENT AUTH. AFFECTED AIR OPR WISHING TO OBTAIN SUCH AN AUTH MUST APPLY TO THE DEPARTMENT OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(A)TC.GC.CA)

(G2993/24 NOTAMR G2907/23 Q) CZXX/OPZTT/IV/BO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2410161344 C) 2504171600