



Flight Plan & Site Survey

Created using **RPAS Wilco®**

Reference No:	F545A8
Title:	Manotick United Church 04-15-2025
Pilot Name:	
Pilot Certificate:	
Flight Start:	April 15, 2025 3:55 PM
Flight End:	April 15, 2025 5:55 PM
Flight Area (Latitude):	45° 13' 27.40" N (45.224)
Flight Area (Longitude):	75° 40' 54.90" W (-75.682)
Altitude - Radius:	Alt: 400 ft - Rad: 926.0 m (0.5 nm)
Classification:	CONTROLLED
FIR - Contact:	CZUL - 506-867-7173

Notes:

Your flight is in controlled airspace.

If your RPAS is > 250g, please obtain RPAS Flight Authorization using the NavDrone app or by contacting NavCanada. (CARs 901.71)

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see


<https://rpaswilco.com/#/tnc>

Included

- Site Survey
- Obstacles (if available)
- Nearby Aerodromes
- Canadian Aviation Regulations
- GFA
- Aerodrome Supplements
 - METAR & TAF (if available)
 - NOTAMs
 - CFS



Flight Map



RPAS Specification

- **Manufacturer:**
MAAC
- **Model:**
Model Airplane (sherryd)
- **Registration Number:**
c0000000000
- **Eligible for advanced operations:**
Yes
- **Manufacturer RPAS safety assurance:**
 - Controlled Airspace: Yes
 - Near People: N/A
 - Over People: N/A

MAP Details

	Latitude	Longitude
 MODEL	45° 13' 27.40" N (45.224)	75° 40' 54.90" W (-75.682)
 Pilot	45° 13' 31.00" N (45.2253)	75° 40' 58.50" W (-75.6829)




Sign Up Today!



Canada's **#1** FREE Drone Training Hub



Airspace Classification



Overlying Airspaces

Class	Name	Floor	Ceiling
E	Montreal FIR CAE	6000MSL	12500MSL
B	Montreal FIR CAE	12500MSL	18000MSL
B	Ottawa, ON CAE	12500MSL	18000MSL
E	Ottawa, ON CAE	2500MSL	12500MSL
E	Ottawa XPNDR MANDTRY	6500MSL	12500MSL
C	Ottawa/Macdonald-Cartier Intl CZ	SFC	2000MSL
C	Ottawa/Macdonald-Cartier Intl CZ	2000MSL	3000MSL
C	Ottawa, ON TCA	1500MSL	2500MSL
E	T614 Airway	2200AGL	12500MSL
B	T614 Airway	12500MSL	18000MSL
B	Ottawa, ON TCA	12500MSL	18000MSL
C	Ottawa, ON TCA	5000MSL	12500MSL
C	Ottawa, ON TCA	4000MSL	5000MSL
C	Ottawa, ON TCA	3000MSL	4000MSL
C	Ottawa, ON TCA	2500MSL	3000MSL
E	T749 Airway	2200AGL	12500MSL
B	T749 Airway	12500MSL	18000MSL
E	T781 Airway	2200AGL	12500MSL
B	T781 Airway	12500MSL	18000MSL

Nearest Aerodromes & Distance from Operation


MACDONALD-CARTIER INTL (CYOW - AERODROME - Cert)	Lat: 45.323	Long: -75.667	11.039KM	5.96NM	N
RIDEAU VALLEY AIR PARK (CPL3 - AERODROME - Reg)	Lat: 45.1	Long: -75.633	14.341KM	7.74NM	S
OTTAWA (CIVIC HOSPITAL) (CPP7 - HELIPORT - Cert)	Lat: 45.392	Long: -75.721	18.899KM	10.2NM	N
OTTAWA (CHILDREN'S HOSPITAL) (CPK7 - HELIPORT - Cert)	Lat: 45.401	Long: -75.65	19.808KM	10.7NM	N
ROCKCLIFFE (CYRO - AERODROME - Cert)	Lat: 45.461	Long: -75.643	26.497KM	14.31NM	N

ONTARIO

AERODROME/FACILITY DIRECTORY

OTTAWA / MACDONALD-CARTIER INTL ON

CYOW



REF	N45 19 21 W75 40 02 Adj S 14°W UTC-5(4) Elev 377' A1905 A5000 A5002 LO6 LO7 HI5 T2 CAP OC
OPR	Ottawa Macdonald-Cartier Intl Apt Authority 613-248-2200 H24 Cert
PF	A-1,2,3,6,7 C-4,5

ONTARIO

AERODROME/FACILITY DIRECTORY

OTTAWA / MACDONALD-CARTIER INTL ON (Cont'd) CYOW

CUST	AOE 888-226-7277 Pilots to call appropriate fixed base opr (FBO) prior to ldg on pvt adv freq & request cust be advised of intended location for clnc. Cust clnc at Apron II 12-05Z± 1 hr PN.
FLT PLN	
FIC	(bil) Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA)
ACC	Montreal 514-633-3211 or 800-633-1353, all Flt Plns, IFR tng PPR
WX	METAR H24 TAF H24, issue times: 00, 03, 06, 09, 12, 15, 18 & 21Z.
DUAT	Ottawa Flying Club; World Fuel Services/Skyservice/Air Elite; Innotech/Execaire/Shell Aerocentre
SERVICES	
FUEL	100LL, JA-1
OIL	All
S	1(ltd), 2,3,4(ltd)
ARFF	DESIGNATED CAT 8
SUP FL	LHOX PN, D & A-ice
PVT ADV	Ottawa Flying Club (North Field) 123.35 12-02Z±; Innotech/Execaire/Shell Aerocentre (South Field) 123.0 11-03Z±; World Fuel Services/Skyservice/Air Elite 129.85 10-05Z±, O/T 613-739-3776
MIL CON	Sky Service FBO Inc. 613-739-3776
RWY DATA	Rwy 14(140°)/32(320°) 10,005x197 grooved ASPH Rwy 07(071°)/25(251°) 8000x197 grooved ASPH Rwy 04(039°)/22(219°) 3300x75 ASPH Thld 04 displ 250'. Rwy 04 down 0.36%. Rstd to acft not exceeding 60,000 lbs. Sked pax svc not auth. RESA: 07/25 984'; 14/32 1000' Abv 15°C, no acft with more than 100 pax or over 85,000 lbs is auth to perform 180° turns on any rwy without perms 613-248-2013
RWY CERT	Rwy 14 RVR 1200(1/4sm)/Rwy 32 RVR 1200(1/4sm) AGN V Rwy 07 RVR 1200(1/4sm)/Rwy 25 RVR 1200(1/4sm) AGN V Rwy 04/22 AGN II
TWY CERT	Twy A: AGN V fr Apron I to Twy L & AGN II fr Twy L to Twy M Twy G AGN IIIB Twy K: AGN V fr Rwy 14/32 to Twy A & AGN IIIB fr Twy A to Apron II Twy: M, P, Q, T AGN II
TWY	Twy G: Uncontrolled. Bridge max weight 122,000 lbs. Twy M, P, Q and T rstd to acft not exceeding 60,000 lbs Twy R: Uncontrolled.
APRON	De-icing Bays Bay 1, 3, 4, 6 - May be used by acft with wingspans 36m (118') or less Bay 2 - May be used by acft with the wingspans 65m (213') or less. If CC used, the Taxi must be on the East taxi line only to/from Bay 2. Bay 5 - May be used by acft with the wingspan 65m (213') or less. If CC used, taxi must be on the East taxi line only to/from Bay 5.
RCR	Opr CRFI. PCN
LIGHTING	07-AN(TE HI) P3, 25-AN(TE HI) P3, 14-AN(TE HI) P3, 32-AN(TE HI) P3
COMM	(bil)
RCO	Québec rdo 123.15 (FISE) 126.7 (bcst)
ATIS	(English) 121.15 (French) 132.95
CLNC DEL	Ottawa 119.4 all dep acft to ctc clnc del
GND	Ottawa 121.9
TWR	Ottawa 118.8 (VFR South) 120.1 (VFR North) 118.8 341.3 (V) (emerg only 613-248-3814)
TML	Ottawa 127.7
ARR	Ottawa ARR 135.15
DEP	Ottawa DEP 128.175

ONTARIO

AERODROME/FACILITY DIRECTORY

OTTAWA / MACDONALD-CARTIER INTL ON (Cont'd)

CYOW

NAV	DME DME ILS YOW 114.6 Ch 93 N45 26 30 W75 53 49 (482') IOW 109.5 Ch 32 N45 18 50 W75 40 01 (398') IOW 109.5 (Rwy 07) RVR IRP 110.3 (Rwy 32) RVR
PRO	Pilots should refer to Canadian Airport Charts (CAC) to obtain details on established hot spots, prior to operating on maneuvering areas. CAC are available for free on the NAV CANADA website. ATC: <u>IFR CLNC ACKNOWLEDGEMENT:</u> IFR clnc read back with Ottawa twr clnc del shall include acft call sign, assigned SID name and transponder code. CIRCUITS: Rgt hand circuits Rwys 07, 14 & 22 (CAR 602.96). FOD: The grade of sand which is used extensively on the aprt dur win may pose a FOD hazard to some acft. Formations and other line astern flt ops should adopt pro to avoid ingestion. NOISE ABATEMENT PROCEDURES: Turbojet and turbofan acft; refer to CAP; propeller acft: dep Rwy 32 to 1500 ASL before proceeding on crs. Circuit hgt 1500 ASL Rwys 04-14 to maintain 1500 ASL, wx permitting, until established on final apch. Tng flt permitted 0815-2359 lcl time, no VFR tng circuits on Rwy 14/32 below 1500 ASL, no practice rwy pro to Rwy 14. For practice IFR apchs to active IFR rwys dur peak hrs 1315-1400Z± & 1930-2400Z± Mon-Fri, ctc Montreal Flight Planning 514-633-3211 or 800-633-1353, for possible delays & rwy info. Turbo-jet take-off and landing not permitted Rwy 04/22. WEST VFR ARR/DEP ROUTES: DEPARTURES: SEE OTTAWA M.-C.I. WEST VFR DEPARTURE PROCEDURES CHART Unless otherwise instructed by ATC contact North Tower on 120.1 when ready, – Bells Corners Departure (Depart Rwy 22), climb rwy hdg to Rideau River remaining north of Rwy 25 centerline at all times, at Rideau River, turn rgt hdg 250, climb to 1300 ASL. At 1300 ASL, continue climb not abv 1500 ASL direct Bells Corners and then to Constance Lake. • Contact Ottawa Terminal on 127.7 at Bells Corners – Champlain Bridge Departure (Depart Rwy 04), left turn direct Champlain Bridge then to Deschenes Quarry climb not abv 1500 ASL. • Contact Ottawa Terminal on 127.7 at the bridge All other VFR acft should anticipate dep instructions from ATC. ARRIVALS: SEE OTTAWA M.-C.I. WEST VFR ARRIVALS PROCEDURES CHART – Rwy 22, proceed via E side of Ottawa River to Deschenes Quarry & then direct Champlain Bridge at 2000 ASL. – Rwy 04, proceed via W side of Ottawa River to Constance Lake, then direct Bells Corners at 2000 ASL. All other VFR acft should anticipate arr instructions from ATC.
PRO (Cont'd)	DE-ICING OPERATIONS 1.Ctc PAD CONTROL on 122.925 30 min prior to dep if de-icing is rqrd. Notify of any special treatments prior to taxi to CDF. 2. Ctc Ottawa GND after pushback for taxi to CDF. 3. Hold short of the CDF on K, AA, BB or CC and ctc PAD CONTROL for further taxi. 4. Follow instructions and electronic sign boards to de-icing bays. 5. Stop on the 2nd (illuminated) yellow stop bar, immediately set brakes and advise PAD CONTROL. DO NOT MOVE ACFT. This will allow positioning of trucks while you configure your aircraft. 6. Once instructed switch to ICEMAN on 122.350, confirm brakes are set, confirm treatment and that acft is configured for treatment (engines at idle/props feathered/pacs off). If you can't reduce engines to idle ICEMAN must know, de-icing may not be possible with running engines. 7. After de-icing, configure acft for taxi, however, DO NOT MOVE ACFT. 8. Once instructed, ctc PAD CONTROL for taxi. 9. Follow instructions to designated exit point. Holding short of Twy A, ctc GND 121.9

OTTAWA / MACDONALD-CARTIER INTL ON (Cont'd) CYOW

VFR FLIGHTS IN OTTAWA MACDONALD-CARTIER CLASS C CZ AND TCA TERMINAL.

In order to minimize delays, ATC frequency congestion and for better airspace management, as well as to improve safety, a procedure is available allowing VFR aircraft to obtain a transponder code prior to take off. This mandatory procedure applies to VFR aircraft that did not file a flight plan or flight itinerary with Nav Canada and wishing to penetrate or operate in the Ottawa/MacDonald-Cartier Class C and terminal Class C airspace. All acft not respecting mandatory transponder code procedure will not be accepted in Ottawa/MacDonald-Cartier Class C CZ and TCA C airspace.

To obtain a transponder code:

A discrete transponder code shall be obtained at least 30 minutes prior to the flight taking off toward Ottawa/MacDonald-Cartier Class C CZ and TCA airspace, by contacting the Montreal ACC at 866-VFR-CODE (866-837-2633), or the FIC at 1-866-GOMETEO or 1-866-WX BRIEF, and providing ATC with flight information. Aircraft departing CYUL, CYJN, CYHU, CYOW, CYMX or CYND will obtain their transponder code from the Control Tower or FSS.

Flight procedure:

- 1.Set your transponder to the assigned code prior to your first communication with ATC.
- 2.To the extent possible, ctc ATC at least 5NM prior to entering Ottawa/MacDonald-Cartier Class C and terminal Class C airspace.

OTTAWA CZ AIRSPACE SPLIT FOR VFR FLIGHTS

YOW CZ is divided into two sectors with separate frequencies.
Contact OTTAWA TWR on 120.1 when North of Rwy 07/25 extended centreline and OTTAWA TWR on 118.8 when South of Rwy 07/25 extended centreline or on final for Rwy 07/25. Holding short of Rwy 04/22, contact OTTAWA TWR on 120.1 when ready for take-off.

CAUTION

Migratory birds in vic of aprt Mar-Apr, Sep-Oct.


ONTARIO

AERODROME/FACILITY DIRECTORY

KARS / RIDEAU VALLEY AIR PARK ON

CPL3

REF	N45 06 W75 38 3S 14°W UTC-5(4) Elev 286' A1905 A5000 A5002
OPR	Chris Williams 613-296-3391 Reg PPR
PF	C-1,2,4,5 D-3,6
FLT PLN FIC	(bil) Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA)
RWY DATA RCR	Rwy 08/26 1800x100 GRASS Opr No win maint. May be soft in spring.
COMM ATF	tfc 123.4 5NM 3300 ASL excluding the airspace that lies within Ottawa TCA class C airspace
PRO	Glider activity in area.




ONTARIO

AERODROME/FACILITY DIRECTORY

OTTAWA (CIVIC HOSP) ON (Heli)

CPP7

REF	N45 23 30 W75 43 14 14°W UTC-5(4) Elev 265' A1905 A5000 A5002
OPR	Ottawa Civic Hosp 613-761-4000 Cert PPR
PF	B-1 C-2,3,4,5,6
FLT PLN FIC	(bil) Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA)
HELI DATA RCR	FATO/TLOF 86' dia ASPH Safety Area 114' dia Max heli overall length 57.5' Opr
LIGHTING	RY(LO) RF(FL)
COMM RCO TWR	Québec rdo (Ottawa/M.-C. Intl) 123.15 (FISE) 126.7 (bcst) Ottawa 118.8
PRO	Arr/dep 190°-220° fr heli, slope 8% (H3), day/night use.
CAUTION	P-lines and trees near ldg area.




ONTARIO

AERODROME/FACILITY DIRECTORY

OTTAWA (CHILDREN'S HOSP) ON (Heli)

CPK7


REF	N45 24 04 W75 39 01 Adj 13°W (2015) UTC-5(4) Elev 272' A1905 A5000 A5002	
OPR	Children's Hosp of Eastern Ontario 613-737-7600 Cert PPR	
FLT PLN	(bil)	
FIC	Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA)	
HELI DATA	FATO 86' dia ASPH TLOF 34' x 34' ASPH Safety Area 114' dia Max heli overall length 56.5'	
RCR	Opr	
LIGHTING	DR RY (LO)	
COMM	Québec rdo (Ottawa/M.-C. Intl) 123.15 (FISE) 126.7 (bcst) Ottawa 118.8	
RCO		
TWR		
PRO	Arr/dep 209° fr heli, slope 12% (H1), day/night use. All acft to park with exhaust away fr bldg at all times.	

ONTARIO

AERODROME/FACILITY DIRECTORY

OTTAWA / ROCKCLIFFE ON

CYRO



REF	N45 27 38 W75 38 36 Adj NE 13°W (2016) UTC-5(4) Elev 184' A1905 A5000 A5002 LO6 LO7 T2
OPR	Rockcliffe Flying Club 613-746-4425 Fax 613-746-3354 11-23Z† Cert Ldg fees for commercial acft exc flt schools
PF	B-1 C-2,3,4,5,6
CUST	AOE/CAN
FLT PLN	(bil)
FIC	Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA)
ACC	Montreal 514-633-3211 or 800-633-1353, all Flt Plns, IFR tng PPR
SERVICES	
FUEL	100LL 11-23Z† 1 HR PN
OIL	15W50
S	2 (13-21Z† Mon-Fri),4,5,6
RWY DATA	Rwy 09(092°)/27(272°) 3319x100 ASPH Thld 09 displ 200'. Thld 27 displ 214'.
RWY CERT	Rwy 09/27 AGN II
TWY	Twy D: unlgtd
RCR	Opr Ltd win maint. Rstd to acft 18,000 lbs and under. PPR for acft over 18,000 lbs.
LIGHTING	09-(TE ME) P1 5.7°, 27-(TE ME) P1 5.7° ARCAL 123.5 type K (see CAUTION)
COMM	
RCO	Québec rdo (Gatineau) 123.375 (FISE)
ATF	UNICOM ltd hrs O/T tfc 123.5 5NM 3200 ASL excluding Gatineau CZ, Ottawa/Macdonald-Cartier Intl CZ and the airspace that lies within Ottawa TCA class C airspace.

ONTARIO

AERODROME/FACILITY DIRECTORY

OTTAWA / ROCKCLIFFE ON (Cont'd)

CYRO

PRO	CIRCUITS: Rgt hand circuits Rwy 27 (CAR 602.96). As soon as practicable after tkof fr Rwy 09 or 27 turn 20° to the North. MUSEUM: Aircraft wishing to park at the Canada Aviation and Space Museum are requested to contact the Rockcliffe Flying Club, by tel or UNICOM for instructions prior arr. AIRSPACE: VFR FLIGHTS IN OTTAWA CLASS C AND TERMINAL CLASS C AIRSPACE SEE OTTAWA / MACDONALD-CARTIER INTL FOR PROCEDURES. VFR Codes: In order to minimize delays, ATC freq congestion and for better airspace management, as well as to improve safety, ctc the Montreal ACC at 866-VFR-CODE (866-837-2633), or the FIC at 1-866-GOMETEO or 1-866-WX BRIEF, to provide ATC with info pertaining to your flt to obtain your transponder code at least 30 min prior to a flight into Ottawa Class C airspace.
CAUTION	Sections of North apron breaking up & covered with loose gravel. Extv bird activity. Feb-May and Sep-Nov. Rstd areas CYR537 and CYR538 cont located 1.5NM W. Adjust flt path/altitude to avoid entry. See VTPC. PAPI apch slope ensures clearance over trees. ARCAL: Acft arr fr the E or S may not be able to activate ARCAL until aprx 1NM from the aprt. Acft on the ground positioned at the E end of the aprt may not be able to activate ARCAL until positioned closer to the W end of the aprt.

Canadian Aviation Regulations

Division III — General Operating and Flight Rules

For full listing please visit : <https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27>

Visual Line-of-sight

- **901.11 (1)** Subject to subsection (2), no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- **(2)** A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate — RPAS issued under section 903.03.

Procedures

- **901.23 (1)** No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - **(a)** normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - **(b)** emergency procedures, including with respect to
 - **(i)** a control station failure,
 - **(ii)** an equipment failure,
 - **(iii)** a failure of the remotely piloted aircraft,
 - **(iv)** a loss of the command and control link,
 - **(v)** a fly-away, and
 - **(vi)** flight termination.
- **(2)** If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- **(3)** No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- **(4)** No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- **(a)** the boundaries of the area of operation;
- **(b)** the type of airspace and the applicable regulatory requirements;
- **(c)** the altitudes and routes to be used on the approach to and departure from the area of operation;
- **(d)** the proximity of manned aircraft operations;
- **(e)** the proximity of aerodromes, airports and heliports;
- **(f)** the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- **(g)** the predominant weather and environmental conditions for the area of operation; and
- **(h)** the horizontal distances from persons not involved in the operation.


Operations at or in the Vicinity of an Aerodrome, Airport or Heliport

- **901.47 (1)** No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the *Canada Flight Supplement* or the *Water Aerodrome Supplement* in a manner that could interfere with an aircraft operating in the established traffic pattern.
- **(2)** Subject to section 901.73, no pilot shall operate a remotely piloted aircraft at a distance of less than
 - **(a)** three nautical miles from the centre of an airport; and
 - **(b)** one nautical mile from the centre of a heliport.
- **(3)** No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate — RPAS issued under section 903.03.


Records

- **901.48 (1)** Every owner of a remotely piloted aircraft system shall keep the following records:
 - **(a)** a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights; and
 - **(b)** a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - **(i)** the names of the persons who performed them,
 - **(ii)** the dates they were undertaken,
 - **(iii)** in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - **(iv)** if applicable, any instructions provided to complete the work.
- **(2)** Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
 - **(a)** in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - **(b)** in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- **(3)** Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).


GFA Issue time + 00 hr - CLOUDS AND WEATHER




GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL



GFA Issue time + 06 hr - CLOUDS AND WEATHER




GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 12 hr - CLOUDS AND WEATHER



GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





MACDONALD-CARTIER INTL - CYOW - Cert

METAR

SPECI CYOW 151901Z 17008KT 15SM BKN030 BKN100 05/05 A2934 RMK SC5AC1 CU EMBD HVY SH E SLP940=

TAF

TAF CYOW 151741Z 1518/1624 29008KT P6SM SCT020 BKN060 TEMPO
1518/1519 3SM SHRA BR BKN020 OVC060 PROB30 1518/1519 VRB15G25KT
2SM TSGRRA BR OVC020CB
FM151900 27010G20KT P6SM SCT020 BKN060 TEMPO 1519/1523 P6SM
-SHRA BKN020 OVC060
FM152300 27010G20KT P6SM SCT012 OVC030 TEMPO 1523/1602 5SM -SHRA
BR BKN012 OVC030
FM160200 28012G22KT 5SM -SHSNRA BR BKN015 OVC030
FM160500 28015G25KT P6SM BKN020 OVC040
FM161400 28015G25KT 4SM -SN OVC020 PROB30 1614/1617 1 1/2SM -SN
FM161700 29015G25KT P6SM BKN030 BKN070
RMK NXT FCST BY 152100Z=

NOTAM

(S1227/25 NOTAMN
Q) CZUL/QFAXX/IV/NBO/A/000/999/4519N07540W005
A) CYOW B) 2504151725 C) 2504160125
E) RSC 04/22 100 PCT WET. VALID APR 15 1723 - APR 16 0123.

RSC 07 5/5/5 100 PCT WET, 100 PCT WET, 100 PCT WET. VALID APR 15
1715 - APR 16 0115.

RSC 25 5/5/5 100 PCT WET, 100 PCT WET, 100 PCT WET. VALID APR 15
1715 - APR 16 0115.

RSC 14 5/5/5 100 PCT WET, 100 PCT WET, 100 PCT WET. VALID APR 15
1719 - APR 16 0119.

RSC 32 5/5/5 100 PCT WET, 100 PCT WET, 100 PCT WET. VALID APR 15
1719 - APR 16 0119.

ADDN NON-GRF/TALPA INFO:

RMK: TWY TWY ALPHA, ALPHA-ALPHA, BRAVO, BRAVO-BRAVO, CHARLIE,
CHARLIE-CHARLIE, DELTA, ECHO, FOXTROT, GOLF, JULIET, KILO, LIMA,
MIKE, PAPA, QUEBEC, ROMEO, TANGO, 202504151719, WET.
RMK: APN APN DE-ICING PAD, MAIN ATB APRON E, MAIN ATB APRON W,
SECONDARY APRON, 202504151719, WET.

FR:
RSC 04/22 100 PCT MOUILLEE. VALIDE APR 15 1723 - APR 16 0123.

RSC 07 5/5/5 100 PCT MOUILLEE, 100 PCT MOUILLEE, 100 PCT
MOUILLEE. VALIDE APR 15 1715 - APR 16 0115.

RSC 25 5/5/5 100 PCT MOUILLEE, 100 PCT MOUILLEE, 100 PCT
MOUILLEE. VALIDE APR 15 1715 - APR 16 0115.

RSC 14 5/5/5 100 PCT MOUILLEE, 100 PCT MOUILLEE, 100 PCT
MOUILLEE. VALIDE APR 15 1719 - APR 16 0119.

RSC 32 5/5/5 100 PCT MOUILLEE, 100 PCT MOUILLEE, 100 PCT
MOUILLEE. VALIDE APR 15 1719 - APR 16 0119.

INFO ADDN NON-GRF/TALPA:

RMK: TWY TWY ALPHA, ALPHA-ALPHA, BRAVO, BRAVO-BRAVO, CHARLIE,
CHARLIE-CHARLIE, DELTA, ECHO, FOXTROT, GOLF, JULIET, KILO, LIMA,
MIKE, PAPA, QUEBEC, ROMEO, TANGO, 202504151719, WET.
RMK: APN APN DE-ICING PAD, MAIN ATB APRON E, MAIN ATB APRON W,
SECONDARY APRON, 202504151719, WET.)

(H1403/25 NOTAMN
Q) CZUL/QCDAS/IV/BO/E/000/999/5440N06941W999
A) CZUL B) 2504170200 C) 2504170500
E) CPDLC NOT AVBL

FR:
CPDLC NON AVBL)

(H1402/25 NOTAMN
Q) CZUL/QCCAS/IV/BO/E/000/999/5440N06941W999
A) CZUL B) 2504170200 C) 2504170500

E) ADS-C NOT AVBL

FR:
ADS-C NON AVBL)

(E2280/25 NOTAMN
Q) CZUL/QOBCE/IV/M/AE/000/006/4519N07540W005
A) CYOW B) 2504141000 C) 2504181930
D) DAILY 1000-1930
E) MOBILE CRANE WITHIN 118FT RADIUS CENTRED ON 451921N 0753953W APRX
3250FT BEYOND THR 07 AND 1930FT NORTH RCL. 127FT AGL 521FT AMSL.
LGTD, NOT PAINTED.

FR:
GRUE MOBILE DANS UN RAYON DE 118FT CENTRE 451921N 0753953W APRX
3250FT APRES THR 07 ET 1930FT AU NORD DE RCL. 127FT AGL 521FT
AMSL. LGTD, NON PEINTE.)

(E2043/25 NOTAMR E1958/25
Q) CZUL/QPICH/I/NBO/A/000/999/4519N07540W005
A) CYOW B) 2504011316 C) PERM
E) AMEND PUBLICATIONS:
ILS RWY 07 APCH: LOC/DME MINIMA TO READ: 700 (327) 1 RVR 50
DIST/ALT TABLE: LAST ALT TO READ: 1.1/700 INSTEAD OF 0.9/660

FR:
MODIFIEZ PUBLICATIONS:
APCH ILS PISTE 07: MINIMUM LOC/DME DEVRAIT LIRE:
700 (327) 1 RVR 50
TABLEAU DES DIST ET ALT: DERNIERE ALT DEVRAIT LIRE:
1.1/700 AU LIEU DE 0.9/660)

(E1853/25 NOTAMR E1409/25
Q) CZUL/QOBCE/IV/M/AE/000/005/4524N07539W005
A) CYOW B) 2503241142 C) 2504301800EST
E) MOBILE CRANE WITHIN 80FT RADIUS CENTRED ON 452407N 0753914W (APRX
4.8NM NNE AD (CYOW)). 165FT AGL 420FT AMSL. NOT LGTD, NOT
PAINTED.

FR:
GRUE MOBILE DANS UN RAYON DE 80FT CENTRE 452407N 0753914W (APRX
4.8NM NNE AD (CYOW)). 165FT AGL 420FT AMSL. NON LGTD, NON PEINTE.)

(E1132/25 NOTAMR E7203/24
Q) CZUL/QPICH/I/NBO/A/000/999/4519N07540W005
A) CYOW B) 2502181329 C) 2505161800EST
E) DUE CRANE:

.
RNAV (GNSS) Z RWY 14 APCH:
LNAV/VNAV MINIMA TO READ: 739 (388) 1
LNAV MINIMA TO READ: 800 (449) 1
DIST/ALT TABLE: LAST ALT TO READ 1.3/800 INSTEAD OF 1.1/760

FR:
EN RAISON DE GRUE:
.
APCH RNAV (GNSS) Z PISTE 14:
MINIMUM LNAV/VNAV DEVRAIT LIRE: 739 (388) 1
MINIMUM LNAV DEVRAIT LIRE: 800 (449) 1
TABLEAU DES DIST ET ALT PUBLIE :
DERNIERE ALT DEVRAIT LIRE 1.3/800 AU LIEU DE 1.1/760)

(H0574/25 NOTAMR H5908/24
Q) CZXX/QOEXX/IV/NBO/E/000/999/5243N05321W999
A) CZQX CZQM CZUL B) 2502121914 C) 2505151600EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR
OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO
NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE
(MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.

FR:
AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR
LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE
SECURITE EN HAITI. IL EST RECOMMANDE AUX EXPLOITANTS AERIENS
CANADIENS ET PROPRIETAIRES D'ACFT IMMATRICULES AU CANADA DE NE
PAS OPR A UN NIVEAU DE VOL INFERIEUR A FL100 DANS L'ESPACE
AERIEN HAITIEN ET LA REGION D'INFORMATION DE VOL DE
PORT-AU-PRINCE (MTEG), EN RAISON DU RISQUE POTENTIEL LIE A
L'ACT DES GANGS.)

(G0296/25 NOTAMR G3450/24
Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
A) CZWG CYYZ B) 2502121911 C) 2505151600EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR
OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO
NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE
(MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.)

(H0401/25 NOTAMN
Q) CZUL/QOEXX/IV/NBO/E/000/999/5243N05321W999
A) CZUL B) 2501311448 C) 2504301400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC
OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT
REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA
(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.

FR:
AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR
LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE
SECURITE DANS LA REPUBLIQUE DEMOCRATIQUE DU CONGO. IL EST
RECOMMANDE AUX OPR AERIENS CANADIENS ET PROPRIETAIRES ACFT
IMMATRICULES AU CANADA DE NE PAS PENETRER DANS LA FIR KINSHASA
(FZZA) A UN NIVEAU DE VOL DE MOINS DE FL260 EN RAISON DES
RISQUES LIES AUX ARMES ANTI-AERIENNES.)

(G0197/25 NOTAMN

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
A) CZWG CYYZ B) 2501311445 C) 2504301400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC
OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT
REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA
(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(G3517/24 NOTAMN

Q) CYYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CYYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160
AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L
ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR
FR NW RNAV WALPP IKLUX KIVUN UKROX)

RIDEAU VALLEY AIR PARK - CPL3 - Reg

NOTAM

(H1403/25 NOTAMN
Q) CZUL/QCDAS/IV/BO/E/000/999/5440N06941W999
A) CZUL B) 2504170200 C) 2504170500
E) CPDLC NOT AVBL

FR:
CPDLC NON AVBL)

(H1402/25 NOTAMN
Q) CZUL/QCCAS/IV/BO/E/000/999/5440N06941W999
A) CZUL B) 2504170200 C) 2504170500
E) ADS-C NOT AVBL

FR:
ADS-C NON AVBL)

(H0574/25 NOTAMR H5908/24
Q) CZXX/QOEXX/IV/NBO/E/000/999/5243N05321W999
A) CZQX CZQM CZUL B) 2502121914 C) 2505151600EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR
OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO
NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE
(MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.

FR:
AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR
LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE
SECURITE EN HAITI. IL EST RECOMMANDE AUX EXPLOITANTS AERIENS
CANADIENS ET PROPRIETAIRES D'ACFT IMMATRICULES AU CANADA DE NE
PAS OPR A UN NIVEAU DE VOL INFERIEUR A FL100 DANS L'ESPACE
AERIEN HAITIEN ET LA REGION D'INFORMATION DE VOL DE
PORT-AU-PRINCE (MTEG), EN RAISON DU RISQUE POTENTIEL LIE A
L'ACT DES GANGS.)

(G0296/25 NOTAMR G3450/24
Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
A) CZWG CZYZ B) 2502121911 C) 2505151600EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR
OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO
NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE
(MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.)

(H0401/25 NOTAMN
Q) CZUL/QOEXX/IV/NBO/E/000/999/5243N05321W999
A) CZUL B) 2501311448 C) 2504301400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC
OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT
REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA
(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.

FR:
AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR
LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE
SECURITE DANS LA REPUBLIQUE DEMOCRATIQUE DU CONGO. IL EST
RECOMMANDE AUX OPR AERIENS CANADIENS ET PROPRIETAIRES ACFT
IMMATRICULES AU CANADA DE NE PAS PENETRER DANS LA FIR KINSHASA
(FZZA) A UN NIVEAU DE VOL DE MOINS DE FL260 EN RAISON DES
RISQUES LIES AUX ARMES ANTI-AERIENNES.)

(G0197/25 NOTAMN
Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
A) CZWG CZYZ B) 2501311445 C) 2504301400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC
OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT
REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA
(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(V0137/25 NOTAMN
Q) CZUL/QOLAS/IV/M/AE/000/007/4506N07541W005
A) CXXX B) 2501302200 C) 2504302359
E) CPL3 KARS/RIDEAU VALLEY AIR PARK
OBST LGT U/S TOWER 450557N 0754107W (APRX 2.2NM WNW AD) 311FT
AGL, 620FT AMSL.

FR:
CPL3 KARS/RIDEAU VALLEY AIR PARK
OBST LGT U/S TOUR 450557N 0754107W (APRX 2.2NM WNW AD) 311FT AGL,
620FT AMSL.)

(G3517/24 NOTAMN
Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CYYZ B) 2412260901 C) PERM
E) AMEND PUBLICATIONS:
AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160
AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L
ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR
FR NW RNAV WALPP IKLUX KIVUN UKROX)



OTTAWA (CIVIC HOSPITAL) - CPP7 - Cert

NOTAM

(H1403/25 NOTAMN

Q) CZUL/QCDAS/IV/BO/E/000/999/5440N06941W999

A) CZUL B) 2504170200 C) 2504170500

E) CPDLC NOT AVBL

FR:

CPDLC NON AVBL)

(H1402/25 NOTAMN

Q) CZUL/QCCAS/IV/BO/E/000/999/5440N06941W999

A) CZUL B) 2504170200 C) 2504170500

E) ADS-C NOT AVBL

FR:

ADS-C NON AVBL)

(E1853/25 NOTAMR E1409/25

Q) CZUL/QOBCE/IV/M/AE/000/005/4524N07539W005

A) CYOW B) 2503241142 C) 2504301800EST

E) MOBILE CRANE WITHIN 80FT RADIUS CENTRED ON 452407N 0753914W (APRX 4.8NM NNE AD (CYOW)). 165FT AGL 420FT AMSL. NOT LGTD, NOT PAINTED.

FR:

GRUE MOBILE DANS UN RAYON DE 80FT CENTRE 452407N 0753914W (APRX 4.8NM NNE AD (CYOW)). 165FT AGL 420FT AMSL. NON LGTD, NON PEINTE.)

(Q0320/25 NOTAMR Q0142/25

Q) CZUL/QFPLC/IV/B/A/000/999/4527N07544W005

A) CXXX B) 2503201146 C) 2505152359

E) CTA9 OTTAWA/GATINEAU (CASINO) (HELI)

HELIPORT CLSD

FR:

CTA9 OTTAWA/GATINEAU (CASINO) (HELI)
HELIPORT CLSD)

(H0574/25 NOTAMR H5908/24

Q) CZXX/QOEXX/IV/NBO/E/000/999/5243N05321W999

A) CZQX CZQM CZUL B) 2502121914 C) 2505151600EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.

FR:

AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE SECURITE EN HAITI. IL EST RECOMMANDE AUX EXPLOITANTS AERIENS CANADIENS ET PROPRIETAIRES D'ACFT IMMATRICULES AU CANADA DE NE PAS OPR A UN NIVEAU DE VOL INFERIEUR A FL100 DANS L'ESPACE AERIEN HAITIEN ET LA REGION D'INFORMATION DE VOL DE PORT-AU-PRINCE (MTEG), EN RAISON DU RISQUE POTENTIEL LIE A L'ACT DES GANGS.)

(G0296/25 NOTAMR G3450/24

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2502121911 C) 2505151600EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.)

(H0401/25 NOTAMN

Q) CZUL/QOEXX/IV/NBO/E/000/999/5243N05321W999

A) CZUL B) 2501311448 C) 2504301400EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.

FR:

AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE SECURITE DANS LA REPUBLIQUE DEMOCRATIQUE DU CONGO. IL EST RECOMMANDE AUX OPR AERIENS CANADIENS ET PROPRIETAIRES ACFT IMMATRICULES AU CANADA DE NE PAS PENETRER DANS LA FIR KINSHASA (FZZA) A UN NIVEAU DE VOL DE MOINS DE FL260 EN RAISON DES RISQUES LIES AUX ARMES ANTI-AERIENNES.)

(G0197/25 NOTAMN

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CYYZ B) 2501311445 C) 2504301400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC
OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT
REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA
(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(G3517/24 NOTAMN

Q) CYYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CYYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160
AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L
ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR
FR NW RNAV WALPP IKLUX KIVUN UKROX)



OTTAWA (CHILDREN'S HOSPITAL) - CPK7 - Cert

NOTAM

(H1403/25 NOTAMN

Q) CZUL/QCDAS/IV/BO/E/000/999/5440N06941W999

A) CZUL B) 2504170200 C) 2504170500

E) CPDLC NOT AVBL

FR:

CPDLC NON AVBL)

(H1402/25 NOTAMN

Q) CZUL/QCCAS/IV/BO/E/000/999/5440N06941W999

A) CZUL B) 2504170200 C) 2504170500

E) ADS-C NOT AVBL

FR:

ADS-C NON AVBL)

(E1853/25 NOTAMR E1409/25

Q) CZUL/QOBCE/IV/M/AE/000/005/4524N07539W005

A) CYOW B) 2503241142 C) 2504301800EST

E) MOBILE CRANE WITHIN 80FT RADIUS CENTRED ON 452407N 0753914W (APRX 4.8NM NNE AD (CYOW)). 165FT AGL 420FT AMSL. NOT LGTD, NOT PAINTED.

FR:

GRUE MOBILE DANS UN RAYON DE 80FT CENTRE 452407N 0753914W (APRX 4.8NM NNE AD (CYOW)). 165FT AGL 420FT AMSL. NON LGTD, NON PEINTE.)

(Q0320/25 NOTAMR Q0142/25

Q) CZUL/QFPLC/IV/B/A/000/999/4527N07544W005

A) CXXX B) 2503201146 C) 2505152359

E) CTA9 OTTAWA/GATINEAU (CASINO) (HELI)

HELIPORT CLSD

FR:

CTA9 OTTAWA/GATINEAU (CASINO) (HELI)
HELIPORT CLSD)

(H0574/25 NOTAMR H5908/24

Q) CZXX/QOEXX/IV/NBO/E/000/999/5243N05321W999

A) CZQX CZQM CZUL B) 2502121914 C) 2505151600EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.

FR:

AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE SECURITE EN HAITI. IL EST RECOMMANDE AUX EXPLOITANTS AERIENS CANADIENS ET PROPRIETAIRES D'ACFT IMMATRICULES AU CANADA DE NE PAS OPR A UN NIVEAU DE VOL INFERIEUR A FL100 DANS L'ESPACE AERIEN HAITIEN ET LA REGION D'INFORMATION DE VOL DE PORT-AU-PRINCE (MTEG), EN RAISON DU RISQUE POTENTIEL LIE A L'ACT DES GANGS.)

(G0296/25 NOTAMR G3450/24

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2502121911 C) 2505151600EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.)

(H0401/25 NOTAMN

Q) CZUL/QOEXX/IV/NBO/E/000/999/5243N05321W999

A) CZUL B) 2501311448 C) 2504301400EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.

FR:

AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE SECURITE DANS LA REPUBLIQUE DEMOCRATIQUE DU CONGO. IL EST RECOMMANDE AUX OPR AERIENS CANADIENS ET PROPRIETAIRES ACFT IMMATRICULES AU CANADA DE NE PAS PENETRER DANS LA FIR KINSHASA (FZZA) A UN NIVEAU DE VOL DE MOINS DE FL260 EN RAISON DES RISQUES LIES AUX ARMES ANTI-AERIENNES.)

(G0197/25 NOTAMN

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CYYZ B) 2501311445 C) 2504301400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC
OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT
REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA
(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(G3517/24 NOTAMN

Q) CYYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CYYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160
AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L
ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR
FR NW RNAV WALPP IKLUX KIVUN UKROX)



ROCKCLIFFE - CYRO - Cert

NOTAM

(H1403/25 NOTAMN
Q) CZUL/QCDAS/IV/BO/E/000/999/5440N06941W999
A) CZUL B) 2504170200 C) 2504170500
E) CPDLC NOT AVBL

FR:
CPDLC NON AVBL)

(H1402/25 NOTAMN
Q) CZUL/QCCAS/IV/BO/E/000/999/5440N06941W999
A) CZUL B) 2504170200 C) 2504170500
E) ADS-C NOT AVBL

FR:
ADS-C NON AVBL)

(A2862/25 NOTAMN
Q) CZUL/QFAXX/IV/NBO/A/000/999/4528N07539W005
A) CYRO B) 2504151319 C) 2504152119
E) RSC 09/27 40 PCT WET. VALID APR 15 1318 - APR 16 1318.

ADDN NON-GRF/TALPA INFO:
CRFI 09 NR/NR/NR.
CRFI 27 NR/NR/NR.

RMK: NEXT OBS AT APR 15 2030.

FR:
RSC 09/27 40 PCT MOUILLEE. VALIDE APR 15 1318 - APR 16 1318.

INFO ADDN NON-GRF/TALPA:
CRFI 09 NR/NR/NR.
CRFI 27 NR/NR/NR.

RMK: PROCHAINE OBS A APR 15 2030.)

(E1853/25 NOTAMR E1409/25
Q) CZUL/QOBCE/IV/M/AE/000/005/4524N07539W005
A) CYOW B) 2503241142 C) 2504301800EST
E) MOBILE CRANE WITHIN 80FT RADIUS CENTRED ON 452407N 0753914W (APRX
4.8NM NNE AD (CYOW)). 165FT AGL 420FT AMSL. NOT LGTD, NOT
PAINTED.

FR:
GRUE MOBILE DANS UN RAYON DE 80FT CENTRE 452407N 0753914W (APRX
4.8NM NNE AD (CYOW)). 165FT AGL 420FT AMSL. NON LGTD, NON PEINTE.)

(K1044/25 NOTAMN
Q) CZUL/QPIAU/I/NBO/A/000/999/4531N07534W005
A) CYND B) 2503211411 C) 2506181900
E) WHEN THR RWY 27 DISPLACED:

.
RNAV (GNSS) RWY 27 APCH:
LPV MINIMA: NOT AUTH
PUBLISHED DIST/ALT TABLE NOT VALID
PUBLISHED CONSTANT DESCENT ANGLE NOT VALID

.
AD CHART: DEP PROC RWY 09: NOT ASSESSED.
PILOT RESPONSIBLE FOR OBST AND TERRAIN AVOIDANCE.

.
SID GATINEAU THREE DEP: DEP RTE RWY 09: NOT AUTH

FR:
LORSQUE THR PISTE 27 DECALE:

.
APCH RNAV (GNSS) PISTE 27:
MINIMUM LPV: NON AUTH
TABLEAU DES DIST ET ALT PUBLIE NON VALIDE
ANGLE DE DESCENTE CONSTANT PUBLIE NON VALIDE

.
CARTE AD: PROC DE DEP: PISTE 09: NON EVALUEE.
LE PILOTE EST RESPONSABLE D'EVITER LES OBST ET LE RELIEF.

.
SID GATINEAU TROIS DEP: RTE DE DEP PISTE 09: NON AUTH)

(K1043/25 NOTAMN
Q) CZUL/QPIAU/I/NBO/A/000/999/4531N07534W005
A) CYND B) 2503211408 C) 2506181900
E) WHEN THR RWY 09 DISPLACED:

.
RNAV (GNSS) RWY 09 APCH:
LPV MINIMA: NOT AUTH
PUBLISHED DIST/ALT TABLE NOT VALID
PUBLISHED CONSTANT DESCENT ANGLE NOT VALID

AD CHART: DEP PROC RWY 27: NOT ASSESSED.
PILOT RESPONSIBLE FOR OBST AND TERRAIN AVOIDANCE.

SID GATINEAU THREE DEP: DEP RTE RWY 27: NOT AUTH

FR:
LORSQUE THR PISTE 09 DECALE:

APCH RNAV (GNSS) PISTE 09:
MINIMA LPV: NON AUTH
TABLEAU DES DIST ET ALT PUBLIE NON VALIDE
ANGLE DE DESCENTE CONSTANT PUBLIE NON VALIDE

CARTE AD: PROC DE DEP: PISTE 27: NON EVALUEE.
LE PILOTE EST RESPONSABLE D'EVITER LES OBST ET LE RELIEF.

SID GATINEAU TROIS DEP: RTE DE DEP PISTE 27: NON AUTH)

(K1041/25 NOTAMR K0817/25
Q) CZUL/QLGAS/IV/BO/A/000/999/4531N07534W005
A) CYND B) 2503220115 C) 2505311030
D) DAILY 0115-1030
E) ACFT RDO CTL AD LGT (ARCAL) U/S,
REDL 09/27, TWY EDGE LGT AND PAPI ON CONTINUOUSLY LOW INTST

FR:
BALISAGE LUMINEUX D'AD TELECOMMANDE (ARCAL) U/S, REDL 09/27, LGT
DE BORD DE TWY ET PAPI ALLUMES CONTINUELLEMENT INTST BASSE)

(Q0320/25 NOTAMR Q0142/25
Q) CZUL/QFPLC/IV/B/A/000/999/4527N07544W005
A) CXXX B) 2503201146 C) 2505152359
E) CTA9 OTTAWA/GATINEAU (CASINO) (HELI)
HELIPORT CLSD

FR:
CTA9 OTTAWA/GATINEAU (CASINO) (HELI)
HELIPORT CLSD)

(H0574/25 NOTAMR H5908/24
Q) CZXX/QOEXX/IV/NBO/E/000/999/5243N05321W999
A) CZQX CZQM CZUL B) 2502121914 C) 2505151600EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR
OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO
NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE
(MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.

FR:
AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR
LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE
SECURITE EN HAITI. IL EST RECOMMANDE AUX EXPLOITANTS AERIENS
CANADIENS ET PROPRIETAIRES D'ACFT IMMATRICULES AU CANADA DE NE
PAS OPR A UN NIVEAU DE VOL INFERIEUR A FL100 DANS L'ESPACE
AERIEN HAITIEN ET LA REGION D'INFORMATION DE VOL DE
PORT-AU-PRINCE (MTEG), EN RAISON DU RISQUE POTENTIEL LIE A
L'ACT DES GANGS.)

(G0296/25 NOTAMR G3450/24
Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
A) CZWG CZYZ B) 2502121911 C) 2505151600EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR
OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO
NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE
(MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.)

(H0401/25 NOTAMN
Q) CZUL/QOEXX/IV/NBO/E/000/999/5243N05321W999
A) CZUL B) 2501311448 C) 2504301400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC
OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT
REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA
(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.

FR:
AVERTISSEMENT RELATIF A LA SECURITE DE L'ESPACE AERIEN EMIS PAR
LE MINISTERE DES TRANSPORTS EN REPONSE A LA SITUATION DE
SECURITE DANS LA REPUBLIQUE DEMOCRATIQUE DU CONGO. IL EST
RECOMMANDE AUX OPR AERIENS CANADIENS ET PROPRIETAIRES ACFT
IMMATRICULES AU CANADA DE NE PAS PENETRER DANS LA FIR KINSHASA
(FZZA) A UN NIVEAU DE VOL DE MOINS DE FL260 EN RAISON DES
RISQUES LIES AUX ARMES ANTI-AERIENNES.)

(G0197/25 NOTAMN
Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999
A) CZWG CZYZ B) 2501311445 C) 2504301400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT
IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC
OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT
REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA
(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(G3517/24 NOTAMN
Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999
A) CZYZ B) 2412260901 C) PERM
E) AMEND PUBLICATIONS:
AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160
AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L
ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR
FR NW RNAV WALPP IKLUX KIVUN UKROX)