

Created using **RPAS Wilco**®

Reference No: Title: Pilot Name: Pilot Certificate: Flight Start: Flight End: Flight Area (Latitude): Flight Area (Longitude): Altitude - Radius: Classification: FIR - Contact:

922058 North Shore community center 04-29-2025

April 29, 2025 12:30 PM April 29, 2025 2:30 PM 50° 41' 49.70" N (50.697) 120° 21' 54.00" W (-120.365) Alt: 400 ft - Rad: 926.0 m (0.5 nm) CONTROLLED CZVR - 604-586-4500

Notes:

Your flight is in controlled airspace. If your RPAS is > 250g, please obtain RPAS Flight Authorization using the NavDrone app or by contacting NavCanada. (CARs 901.71)

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

Included

Site Survey

Obstacles (if available)

Nearby Aerodromes

Canadian Aviation Regulations

GFA

Aerodrome Supplements

-METAR & TAF (if available)

-NOTAMs

-CFS

Flight Map

WILCO









- Manufacturer: MAAC
- Model: Model Airplane (sherryd)
- Registration Number: c000000000
- Eligible for advanced operations: Yes
- Manufacturer RPAS safety assurance:
 - Controlled Airspace: Yes
 - Near People: N/A
 - Over People: N/A

MAP Details Latitude

×	MODEL	50° 41' 49.70" N (50.697)	120° 21 (-120.3
•	Pilot	50° 41' 53.30" N	120° 21
	Sherry Denesha	(50.6981)	(-120.3

' 54.00" W 365)

Longitude


Flight Plan & Site Survey

' 57.60" W 366)





Airspace Classification



Overlying Airspaces

Class	Name	Floor	Ceiling
E	T650 Airway	2200AGL	12500MSL
В	T650 Airway	12500MSL	18000MSL
Е	T789 Airway MEA: 12700MSL	2200AGL	12700MSL
В	T789 Airway MEA: 12700MSL	12700MSL	18000MSL
Е	Kamloops CZ	SFC	3000GND
Е	T695 Airway	2200AGL	12500MSL
В	T695 Airway	12500MSL	18000MSL
Е	Kamloops, BC TA	700AGL	12500MSL
В	Kamloops, BC TA	12500MSL	18000MSL
Е	T611 Airway	2200AGL	12500MSL
В	T611 Airway	12500MSL	18000MSL
E	T687 Airway	2200AGL	12500MSL
В	T687 Airway	12500MSL	18000MSL
E	Kamloops, BC TA	1600AGL	12500MSL
В	Kamloops, BC TA	12500MSL	18000MSL
E	Williams Lake, BC CAE	8000MSL	12500MSL
В	Williams Lake, BC CAE	12500MSL	18000MSL

Nearest Aerodromes & Distance from Operation

KAMLOOPS (CAH7 - WATERDROME - Reg)	Lat: 50.7	Long: -120.433	4.8KM	2.59NM W
KAMLOOPS (CYKA - AERODROME - Cert)	Lat: 50.703	B Long: -120.448	5.882KM	3.18NM W
KAMLOOPS (ROYAL INLAND HOSPITAL) (CBC4 - HELIPORT - Cert) Lat: 50.669	Delta Long: -120.333	3.857KM	2.08NM SE

CANADA WATER AERODROME SUPPLEMENT Effective 0901Z 17 April 2025 to 0901Z 19 March 2026 B90 AERODROME/FACILITY DIRECTORY

JENKINS COVE NB — See KARS / JENKINS COVE

JENNY'S LANDING ON - See KENNISIS LAKE / JENNNY'S LANDING

JOHN'S BAY ON - See LAKE ROSSEAU / JOHN'S BAY

KAMANISKEG LAKE ON - See COMBERMERE / KAMANISKEG LAKE

KAMLOOPS BC

	20	er an
REF	N50 42 W120 26 3WNW 17°E (2013) UTC-8(7) Elev 1129' A5004	ELEV 1129
OPR	Kamloops Aprt Ltd 250-376-3613 Reg	
PF	A-1,2,3,6 C-4,5 at adj land A/D	
CUST	AOE/15 16-08Z‡ 888-226-7277	
FLT PLN FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)	A DIUS 5 Ma Thompson River
SERVICES	Float cart chg. Call out chg may be levied for one or more svcs. Mountainaire Svc 250-376-3800, Spring Avn 250-554-2616.	5300
FUEL	100LL, JA-1 avbl at adj A/D, acft removal fr water rqrd, refuelling at dock proh.	0 1 2 3 4 5 6000' . Executive Flight Centre 250-376-9069.
OIL	80, 100, 120	A. Executive Flight Centre 250-570-5005.
S	1 (ltd),2,3 (at adj land A/D), 5	
A/D DATA	Open water Apr-mid Nov. Depth 12′, san water level by 12′. Buoys, ramp & beach	d bottom, current 5 kt. Spring freshets raise n.
COMM RADIO RCO MF	125.7 297.0 (V) (emerg only 250-376 Pacific rdo 123.375 (FISE) 126.7 (bcst) rdo 125.7 5NM 4100 ASL centred on la)
PRO	Seaplane conform to land A/D tfc pattern (CAR 602.96). E departures climb to 220	n: Rgt hand circuits Rwys 04, 22 & 27 00 ASL or river junction before turning N.
CAUTION	Migratory bird activity in vic of A/D. Seas hazardous; oprg channel swings from N Adj land A/D. Class "E" CZ to 5NM radiu	side of river E of dock, to S side W of dock.

CAH7

KAMLOOPS FIC - RCO

L

Cross reference to PACIFIC RADIO - RCO (New)

KAMLOOPS FSS – RCO

Victoria 119.7 (RAAS) 08-14Z⁺ (N48 38 W123 25)

CANADA WATER AERODROME SUPPLEMENT

Effective 0901Z 17 April 2025 to 0901Z 19 March 2026

AERODROME/FACILITY DIRECTORY B91

KARS / JENKINS COVE NB

KARS / JENK	INS COVE NB	CJO3
REF	N45 35 38 W65 57 25 1.3ESE 17°W (2017) UTC-4(3) Elev 20' A5003	t Q ELEV 20 Q t Munutury
OPR	Richard Pattie 506-485-1122 Reg	
PF	B-1 C-2,5	
FLT PLN FIC ACC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) (IFR only) Moncton 506-867-7177 or 866-480-8200.	$\begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \end{array}{} \\ \begin{array}{c} \end{array}{} \\ \\ \\ \end{array}{} \\ \\ \\ \end{array}{} \\ \end{array}{} \\ \\ \\ \\ \end{array}{} \\ \\ \\ \\ \\ \end{array}{} \\ \\ \\ \\ \end{array}{} \\ \\ \\ \\ \\ \\ \end{array}{} \\ \\ \\ \\ \\ \end{array}{} \\ \\ \\ \\ \\ \\ \\ \end{array}{} \\ \\ \\ \\ \\ \\ \\ \end{array}$ } \\ } \\ } \\ } } } } } } } } } \\ } } } } } } } } } } } } }
SERVICES	5	t t
A/D DATA	Open water May-Dec	0 1 2 3 4 5 6000'
COMM ATF	tfc 123.05 5NM 3000 ASL	

KASBA LAKE NT

CJP5


REF	N60 17 W102 31 7°E (2013) UTC-6(5) Elev 1089' A5024 A5031	ELEV 1089 £ ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
OPR	Kasba Lake Lodge 250-248-3572 Reg PPR	o a port
PF	B-1,2,5 PN Oprg Jun15-Sep 1	wharves
FLT PLN FIC	Edmonton 866-WXBRIEF (Toll free within Canada) or 866-541-4102 (Toll free within Canada & USA)	Kasba Lake +
SERVICES FUEL	100LL, JA Prior arng thru Opr Jun 15 - Aug 15	0 2600 0 7 0 2600
A/D DATA	Open water Jun-Oct. Sand beach.	
COMM	UNICOM ltd hrs O/T tfc 122.8 5NM 4200 ASL	0 2 4 6 8 10 12000'

BRITISH COLUMBIA

AERODROME/FACILITY DIRECTORY

KAMLOOPS BC

СҮКА



REF	N50 42 09 W120 26 55 5WNW 16°E (2016) UTC-8(7) Elev 1133' A5004 LO2 HI3 CAP RCAP	
OPR	Kamloops Aprt Ltd 250-376-3613 Cert	
PF	A-1,2,3,6 C-4,5	
CUST	AOE/30 1630-0030Z‡ Mon-Fri exc hols 888-226-7277	
FLT PLN FIC WX	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA) or 250-376-8392 METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.	
SERVICES FUEL OIL S ARFF PVT ADV MIL CON	Call out chg may be levied for one or more svcs 100LL, JA-1 (FSII avbl) 80, 100, 120 1 (Itd), 2,3,4,5,6 (Itd) DESIGNATED CAT 6 14-08Z‡, O/T 2 hr PN 250-376-3233 call out chg Shell 123.0 250-376-7633; Executive Flight Centre 122.85 250-376-9069 Executive Flight Centre Fuel 250-376-9069	
RWY DATA RWY CERT	Rwy 09(087°)/27(267°) 8000x148 ASPH Rwy 05(045°)/23(225°) 1875x49 ASPH Thid 23 displ 249'. Rwy 05/23 AGN I Rwy 09/27 AGN IIIB	
TWY CERT TWY	Twy: D, E AGN II Twy A, no vehicle ctl first 600' W of Apron I. Twy E: Unlgtd	
APRON	Apron 1: Uncontrolled, avbl to sked pax fit only. All acft must yield to acft in pushback from ATB. Prkg fees. Apron II: Uncontrolled, avbl for transient and itinerant prkg. All acft must yield to acft in pushback from ATB. Pilot/pax access via groundside Gate 10 only; no access/egress permitted via ATB. Prkg fees. Apron V: Uncontrolled, PPR for prkg on or within 25' of apn. FSS Win maint 13-08Z‡ O/T 2 hrs PN cost recovery. CRFI, PCN.	
LIGHTING	09-AO(TE ME) P2, 27-AO(TE ME) P2 ARCAL-125.7 type K avbl when FSS clsd PAPI limitation/restriction. PAPI Rwy 09 to be used only within 4NM of thld; PAPI Rwy 27 to be used only within 4NM of thld. Twy D RR.	

CANADA FLIGHT SUPPLEMENT / GPH 205 Effective 0901Z 17 April 2025 to 0901Z 12 June 2025

BRITISH COLUMBIA

AERODROME/FACILITY DIRECTORY

KAMLOOPS BC (Cont'd)


COMM RADIO RCO CLNC DEL MF PAL	125.7 PTC avbl (V) (emerg only 250-376-7941) Pacific rdo 123.375 (FISE) 126.7 (bcst) 121.9 PTC avbl Itd hrs rdo 125.7 5NM 4100 ASL (CAR 602.98) Vancouver Ctr 132.35 133.5 134.4 236.0
NAV	IKA 109.3 Ch 30 N50 42 14 W120 27 41 (1136')
ILS	IKA 109.3 (Rwy 09)
LOC	IPP 109.9 (Rwy 27)
PRO	Pilots should refer to Canadian Airport Charts (CAC) to obtain details on established hot spots, prior to operating on maneuvering areas. CAC are available for free on the NAV CANADA website. Day: rgt hand circuits Rwys 05, 23 & 27 (CAR 602.96). Night: follow VTPC night circuit pro. Tkof and ldg in grass adj rwys by fixed-wing acft not auth.
CAUTION	Migratory bird activity in vic of A/D. Only pilots familiar with IcI terrain should use this aprt dur hrs of darkness. Ngt ops not recommended unless all 6 hazard beacons are oprg. Hi terrain reduces operational length of Rwys 09 and 27 PAPI. Painted & Igtd twr 1253 ASL (128 AGL) aprx 250' beyond ThId 05 and aprox 2710' NW rwy centreline. Fuel facility (tanks 80 AGL) aprx 0.5NM NE A/D; no low alt heli ops.

BRITISH COLUMBIA

AERODROME/FACILITY DIRECTORY

KAMLOOPS (ROYAL INLAND HOSP) BC (Heli)





BRITISH COLUMBIA

AERODROME/FACILITY DIRECTORY

KAMLOOPS (ROYAL INLAND HOSP) BC (Heli) (Cont'd)

CBC4

СОММ	MF A/G	Kamloops rdo 125.7 5NM 4100 ASL centered on Kamloops aprt (CAR 602.98). Hosp Security PEPCORD1 148.655 FM 3 min PN
PRO		Surface Pad 1 Arr/dep 125° fr heli, (H3) (CAR 602.96). Arr/dep 002° to 125° fr heli, (H1) (CAR 602.96). Rooftop Pad 2 Arr/dep 265° to 108° fr heli (H1) (CAR 602.96).
CAUTIO	N	Unlgtd embankment to 40', adj SE. Marked & lgtd hosp penthouse elevator aprx 30' W of rooftop pad safety area.

Canadian Aviation Regulations

Division III — General Operating and Flight Rules

0

For full listing please visit : https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

Visual Line-of-sight

- 901.11 (1) Subject to subsection (2), no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - (b) emergency procedures, including with respect to
 - (i) a control station failure,
 - (ii) an equipment failure,
 - (iii) a failure of the remotely piloted aircraft,
 - (iv) a loss of the command and control link,
 - (v) a fly-away, and
 - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation.

Operations at or in the Vicinity of an Aerodrome, Airport or Heliport


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
 - (2) Subject to section 901.73, no pilot shall operate a remotely piloted aircraft at a distance of less than
 - O (a) three nautical miles from the centre of an airport; and
 - O (b) one nautical mile from the centre of a heliport.
 - (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Records

- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
 - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights; and
 - O (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - (i) the names of the persons who performed them,
 - (ii) the dates they were undertaken,
 - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - (iv) if applicable, any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of


 (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).






GFA Issue time + 00 hr - CLOUDS AND WEATHER

GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL









GFA Issue time + 06 hr - CLOUDS AND WEATHER


GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL







GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





KAMLOOPS - CAH7 - Reg

NOTAM

(F1290/25 NOTAMN

Q) CZEG(QXXXX/I/NBO/E/000/999/5405N11235W400 A) CZEG B) 2504291530 C) 2504291800 E) DUE TO REDUCED SYSTEM CAPACITY IN EDMONTON ACC, ALL IFR FLT OPR BTN CYYC AND CYMM/OILSANDS AIRPORTS SHALL FLT PLAN FL280 OR BLW.)

(F1289/25 NOTAMN

Q) CZXX/QXXLW/IV/BO/E/000/999/5054N11508W400 A) CZEG CZVR B) 2504291530 C) 2504291800 E) DUE TO REDUCED SYSTEM CAPACITY IN EDMONTON ACC, ALL IFR FLT OPR BTN CYYC AND CYLW SHALL FLT PLAN FL280 OR BLW. FOR INFO CTC CZEG OPS DUTY MANAGER AT 780-890-8397)

(F1275/25 NOTAMR F0314/25

Q) CZXX/QOEXX/IV/NBO/E/000/999/6650N11045W999 A) CZEG CZVR B) 2504281317 C) 2507281400EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(I1572/25 NOTAMN

Q) CZVR/QOBCE/IV/M/AE/000/013/5043N12026W005 A) CYKA B) 2504231400 C) 2505070200 E) MOBILE CRANE WITHIN 100FT RADIUS CENTRED ON 504240N 1202616W APRX 1470FT BFR DTHR 23 AND 2770FT NW EXTENDED RCL. 140FT AGL 1275FT AMSL. NOT LGTD, PAINTED.)

(11253/25 NOTAMR 11250/25 Q) CZVR/QFFAH/IV/BO/A/000/99/5042N12027W005 A) CYKA B) 2504010000 C) 2505010730 E) ACFT RESCUE AND FIRE FIGHTING (ARFF) HR OF OPS: MON-FRI: 0000-0215 0545-0730 1230-1330 1615-1815 2100-2215 2330-2359 SAT: 0000-0215 0545-0730 1230-1330 1615-1800 2100-2230 2330-2359 OT 2HR PN COST RECOVERY)

(I0721/25 NOTAMN

Q) CZVR/QPICH/I/NBO/A/000/999/5042N12027W005 A) CYKA B) 2502200901 C) PERM E) AMEND PUBLICATIONS: LOC Z RWY 27 APCH: ADD OPS NOTE: DME RELIABLE ONLY WITHIN 10 DEG EITHER SIDE OF CENTRELINE.)

(F0472/25 NOTAMR F0470/25 Q) CZXX/QOEXXI/V/NBO/E/000/99/6650N11045W999 A) CZVR CZEG B) 2502121910 C) 2505151600EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.)



KAMLOOPS - CYKA - Cert

METAR

METAR CYKA 291600Z 26005KT 40SM BKN099 10/03 A3000 RMK AC7 SLP166=

TAF

TAF CYKA 291240Z 2913/3001 VRB03KT P6SM SCT100 BKN170 FM291800 28010KT P6SM BKN100 TEMPO 2918/3001 SCT100 RMK NXT FCST BY 291900Z=

NOTAM

(F1290/25 NOTAMN Q) CZEG/QXXXX/I/NBO/E/000/999/5405N11235W400 A) CZEG B) 2504291530 C) 2504291800 E) DUE TO REDUCED SYSTEM CAPACITY IN EDMONTON ACC, ALL IFR FLT OPR BTN CYYC AND CYMM/0LSANDS AIRPORTS SHALL FLT PLAN FL280 OR BLW.)

(F1289/25 NOTAMN

(1120)20 NOVIRON (11)2000/999/5054N11508W400 A) CZZKJQXXLW/IV/BO/E/000/999/5054N11508W400 A) CZEG CZVR B) 2504291530 C) 2504291800 E) DUE TO REDUCED SYSTEM CAPACITY IN EDMONTON ACC, ALL IFR FLT OPR BTN CYYC AND CYLW SHALL FLT PLAN FL280 OR BLW. FOR INFO CTC CZEG OPS DUTY MANAGER AT 780-890-8397)

(F1275/25 NOTAMR F0314/25

Q) CZXX/QOEXXIV/NBO/E/000/999/6650N11045W999 A) CZEG CZVR B) 2504281317 C) 2507281400EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(I1572/25 NOTAMN

QI CZVR/QOBCE/I/V/MAE/000/013/5043N12026W005 A) CYKA B) 2504231400 C) 2505070200 E) MOBILE CRANE WITHIN 100FT RADIUS CENTRED ON 504240N 1202616W APRX 1470FT BFR DTHR 23 AND 2770FT NW EXTENDED RCL. 140FT AGL 1275FT AMSL. NOT LGTD, PAINTED.)

(I1253/25 NOTAMR 11250/25 Q) CZVR/QFFAH/IV/BO/A/000/99/5042N12027W005 A) CYKA B) 2504010000 C) 2505010730 E) ACFT RESCUE AND FIRE FIGHTING (ARFF) HR OF OPS: MON-FRI: 0000-0215 0545-0730 1230-1330 1615-1815 2100-2215 2330-2359 SAT: 0000-0215 0545-0730 1230-1330 1615-1800 2100-2215 SUN: 0045-0215 0545-0730 1230-1330 1615-1800 2100-2230 2330-2359 O/T 2HR PN COST RECOVERY)

(10721/25 NOTAMN Q) CZVR/QPICH//NBO/A/000/999/5042N12027W005 A) CYKA B) 2502200901 C) PERM E) AMEND PUBLICATIONS: LOC Z RWY 27 APCH: ADD OPS NOTE: DME RELIABLE ONLY WITHIN 10 DEG EITHER SIDE OF CENTRELINE.)

(F0472/25 NOTAMR F0470/25

Q) CZXX/QOEXX/IV/NBO/E/000/999/6650N11045W999 A) CZVR CZEG B) 2502121910 C) 2505151600EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.)



KAMLOOPS (ROYAL INLAND HOSPITAL) - CBC4 - Cert

NOTAM

(F1290/25 NOTAMN Q) CZEG/QXXXX/I/NBO/E/000/999/5405N11235W400 A) CZEG B) 2504291530 C) 2504291800

E) DUE TO REDUCED SYSTEM CAPACITY IN EDMONTON ACC, ALL IFR FLT OPR BTN CYYC AND CYMM/OILSANDS AIRPORTS SHALL FLT PLAN FL280 OR BLW.)

(F1289/25 NOTAMN

Q) CZXX/QXXLW/IV/BO/E/000/999/5054N11508W400 A) CZEG CZVR B) 2504291530 C) 2504291800 E) DUE TO REDUCED SYSTEM CAPACITY IN EDMONTON ACC, ALL IFR FLT OPR BTN CYYC AND CYLW SHALL FLT PLAN FL280 OR BLW. FOR INFO CTC CZEG OPS DUTY MANAGER AT 780-890-8397)

(F1275/25 NOTAMR F0314/25

Q) CZXX/QOEXX/IV/NBO/E/000/999/6650N11045W999 A) CZEG CZVR B) 2504281317 C) 2507281400EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(I1572/25 NOTAMN

Q) CZVR/QOBCE/IV/M/AE/000/013/5043N12026W005 A) CYKA B) 2504231400 C) 2505070200 E) MOBILE CRANE WITHIN 100FT RADIUS CENTRED ON 504240N 1202616W APRX 1470FT BFR DTHR 23 AND 2770FT NW EXTENDED RCL. 140FT AGL 1275FT AMSL. NOT LGTD, PAINTED.)

(11253/25 NOTAMR 11250/25 Q) CZVR/QFFAH/IV/BO/A/000/99/5042N12027W005 A) CYKA B) 2504010000 C) 2505010730 E) ACFT RESCUE AND FIRE FIGHTING (ARFF) HR OF OPS: MON-FRI: 0000-0215 0545-0730 1230-1330 1615-1815 2100-2215 2330-2359 SAT: 0000-0215 0545-0730 1230-1330 1615-1800 2100-2230 2330-2359 OT 2HR PN COST RECOVERY)

(I0721/25 NOTAMN

Q) CZVR/QPICH/I/NBO/A/000/999/5042N12027W005 A) CYKA B) 2502200901 C) PERM E) AMEND PUBLICATIONS: LOC Z RWY 27 APCH: ADD OPS NOTE: DME RELIABLE ONLY WITHIN 10 DEG EITHER SIDE OF CENTRELINE.)

(F0472/25 NOTAMR F0470/25 Q) CZXX/QOEXXI/V/NBO/E/000/99/6650N11045W999 A) CZVR CZEG B) 2502121910 C) 2505151600EST E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN HAITI. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED TO NOT OPR BLW FL100 WITHIN HAITIAN AIRSPACE AND FIR PORT-AU-PRINCE (MTEG) DUE TO POTENTIAL RISK FROM GANG ACT.)